


ASS. REC. BY: Steve REF: CS/CT/22000667/13 Eqy3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. SNM22D200414/C02
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLT 3776C Yr Regn: 26/1P/17
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Land Rover Discovery c.c. 2993
 Colour: Green A/C: Insured / Std / NI / NA
 Sp. Reading: 71210 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: SALRA2AK8HA038154
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: NII / S/Rim / STD A/Rim or
 Tyre Size: F: 255/55R20
 R: 11
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
 Front _____ Rear _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 15/1/22 D.O.I. 24/1/22
 Survey held at Wearnes
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV-218K</u>
<u>03/02/22 @ 5.23pm</u>	<u>revised to Irene Tay via Merimen.</u>
	<u>Steve Finalize \$21,530.11 (P/P, before GST). 5 days. (Red \$11803.46, 35%)</u>

Date/Time, File Pass to?

☐ : Prell. Report
☐ : Final Report

1) 29/03 Typist

Date/Time, File Return to?

2)

Report Format: MER-TP

Lump Sum / I.B.I. (\$) 21530.11

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ \$ + RS. ____ SI

Photos

Others

TOTAL

Steve (LKK)
24/1/22, 10.10L
m n
PIP
M PL Y
S Y

SERVICE ESTIMATE

68151 - C00001
 Mr Sw Chan Kit
 2 Sembawang Walk
 #01-85

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 17/01/2022

WIP No. : 64618

Veh.In/Out:

*Tel.No. : Mobile: 97545918

Reg.No. : SLT3776C

Reg.date : 26/10/2017

Mileage : 0

Chassis No: SALRA2AK8HA038154

Singapore 757616

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Sw Chan Kit

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, 1300 X 2600	0		5200.00	0		5,200.00	S
	REAR BOOTLID, BOOTLAMP, TAILLAMP, BUMPER TOW COVER, BUMPER BEAM REAR, REPAIR REAR FENDER LH 1000X2						2600	
800	TO SPRAYPAINT ON	0		4000.00	0		4,000.00	S
	REAR BUMPER, BOOTLID, REAR FENDER LH ETC						2000	
802	TO REPLACE REAR WINDSCREEN	0		600.00	0		600.00	S
0080	TO INSTALL REAR WINDSCREEN FIL	0		280.00	0		280.00	S
280	TO CHECK WIRING INCLUDE	0		621.00	0		621.00	S
	RESETTING OF ALL ELECTRICAL MODULES							
NOTES	NOTES							
	BUMPER - REAR	1.0	EA	2171.20			2,171.20	S
	COVER - TOWING HOOK	1.0	EA	432.30			432.30	S
	LH BRACKET - BUMPER	1.0	EA	52.60			52.60	S

SERVICE ESTIMATE

68151 - C00001
 Mr Sw Chan Kit
 2 Sembawang Walk
 #01-85

SL: SERVICE SALES - PC

Singapore 757616

Closed by : Paul Ong Qing Yong
 Svc Consultant :
 Remarks : Mr Sw Chan Kit

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 2
 Inv.date. : 17/01/2022
 WIP No. . : 64618
 Veh.In/Out:
 *Tel.No. . : Mobile: 97545918
 Reg.No. . : SLT3776C
 Reg.date . : 26/10/2017
 Mileage ... : 0
 Chassis No: SALRA2AK8HA038154

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
	RH BRACKET - BUMPER		1.0 EA	52.60			52.60	S
	INSERT - BUMPER LH		1.0 EA	140.10			140.10	S
	INSERT - BUMPER RH		1.0 EA	140.10			140.10	S
	REINFORCEMENT - REAR		1.0 EA	650.70			650.70	S
	LH REINFORCEMENT - B		1.0 EA	383.80			383.80	S
	RH REINFORCEMENT - B		1.0 EA	383.80			383.80	S
	LH BRACKET - BUMPER		1.0 EA	99.40			99.40	S
	RH BRACKET - BUMPER		1.0 EA	99.40			99.40	S
	BRACKET - BUMPER MOU		1.0 EA	94.90			94.90	S
	WIRING - BUMPER REAR		1.0 EA	299.50			299.50	S
	LAMP - REAR, STOP AN	X BR	1.0 EA	1303.00			1,303.00	S
	LAMP - REAR, STOP AN	X BR	1.0 EA	1303.00			1,303.00	S
	LAMP - DAYTIME RUNNI	X BR	1.0 EA	1085.80			1,085.80	S
	LAMP - DAYTIME RUNNI	X BR	1.0 EA	1085.80			1,085.80	S
	TAILGATE - COMPLETE	/ BR	1.0 EA	2808.40			2,808.40	S
	SEAL - TAILGATE	/ MC	1.0 EA	260.10			260.10	S
	GLASS - TAILGATE WIN	/ MC (ph1.)	1.0 EA	2711.50			2,711.50	S

SERVICE ESTIMATE

68151 - C00001
Mr Sw Chan Kit
2 Sembawang Walk
#01-85

Singapore 757616

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 3

Inv.date. : 17/01/2022

WIP No. : 64618

Veh.In/Out:

*Tel.No. : Mobile: 97545918

Reg.No. : SLT3776C

Reg.date : 26/10/2017

Mileage : 0

Chassis No: SALRA2AK8HA038154

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Mr Sw Chan Kit

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	D PRIMER GLASS & P ADHESIVE AND SEALER	1.0 EA	43.30			43.30	S
	NAME PLATE - PLASTIC	2.0 EA	159.50			319.00	S
	NAME PLATE - PLASTIC	1.0 EA	202.20			202.20	S
	NAME PLATE - PLASTIC	1.0 EA	185.00			185.00	S
	NAME PLATE	1.0 EA	98.60			98.60	S
	NAME PLATE Td6	1.0 EA	159.10			159.10	S
	SENSOR - PARKING AID	4.0 EA	276.10			1,104.40	S
	SENSOR - PARKING AID	2.0 EA	276.10			552.20	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Labour Total 10,701.00
Parts Total 18,221.80
Package Total 0.00

Acknowledged by Repairer

Signature:

Date:

Gross Total. 28,922.80
Net..... 28,922.80
GST @ 7.0% 2,024.60
Total..... 30,947.40
Paid..... 0.00
Please Pay.. 30,947.40

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	17/01/2022 15:04 (SGT)
Date of Accident	15/01/2022 10:53 (SGT)
Exact Location of Accident	BKE, Singapore
Additional Location Information	BKE Towards Woodlands near SLE/CTE Exit
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT3776C
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	Sw Chan Kit
NRIC No	SXXXX538D
Email Address	sck96@singnet.com.sg
Mobile Phone No	(Phone) +65-97545918
Alternative Phone No	+65-97545918

VEHICLE PARTICULARS

Manufacturer	LandRover
Model	Discovery
Variant	Discovery 3.0D HSE
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2993

INSURANCE COMPANY

Name of Insurance Company	Liberty Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	-
Cover Note Number	-

DRIVER

Name of Driver	Sw Chan Kit
NRIC No	SXXXX538D

Date Of Birth	20/08/1963
Occupation	Indoor
Date Of Driving Pass	03/03/1989
Driving experience	32 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97545918
Alt. Phone Number	+65-97545918
Email Address	sck96@singnet.com.sg
Address	2 Sembawang Walk #01-85
Address complement	-
Postcode	757616
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	4
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	Chia Ng Moi
Gender	Female

PASSENGER 2

Name	Sw Sook Fun
Gender	Female

PASSENGER 3

Name	Edmund Yeo Soon Leong
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Woodlands Division Headquarters
Police Station Phone No	(Phone) +65-18004660000
Police Station Address	1 Woodlands St 12 Singapore 738622
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
---	-----

Was there any video captured by Car Camera?
Was there any audio recorded?

Yes
No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH3894B
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	Chia Ng Moi
Gender	Female
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SLT3776C
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	-

INJURED 2

Name of injured person	Sw Sook Fun
Gender	Female
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SLT3776C
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	-



**SINGAPORE
POLICE FORCE**



L/20220115/7031

1 of 2

POLICE REPORT (NP299)

Police Station Of Origin
Woodlands Division HQ
1 Woodlands Street 12 SINGAPORE 738622
Tel No: 1800-4660000

Report No. L/20220115/7031

Date/Time Report Made 15/01/2022 17:35	Vide Report No.	Station Diary No.
Name Of Informant SW CHAN KIT	Address 2 SEMBAWANG WALK #01-85 SINGAPORE 757616	
ID Type / ID No. NRIC NO / S1584538D	Contact No. Home/Office:	Mobile: 97545918
Nationality SINGAPORE CITIZEN	Email Address sck96@singnet.com.sg	
Occupation Accountant	Sex Male	Age 58
Institution/School Name	Date of Birth 20/08/1963	Race Chinese
	Language English	
Date/Time Of Incident 15/01/2022 10:50 - 15/01/2022 12:00	Location Of Incident 2 SEMBAWANG WALK #01-85 SINGAPORE 757616	

Brief details.

Car Accident Report (SLT 3776 C)

I was driving on BKE towards woodlands and about to exit SLE/CTE while driving on the 2nd left lane. The traffic is smooth but all slow down to a stop when about to exit to SLE/CTE expressway. My Vehicle had stopped on the 2nd left lane for about 3 seconds (total complete stop). A loud bang (heard) and a heavy jerk inside the vehicle after the complete stop. The engine turns to a complete stop and can't even re-start the car. This is the case until 20 minutes later then I am able to re-start the car engine.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 15/01/2022 17:35
Officer In-Charge Of Case:	Classification Of Case:



**SINGAPORE
POLICE FORCE**



L/20220115/7031

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. L/20220115/7031

I realized that I was hit by a small lorry having the number plate GBH 3894 B.

My mother (Chia Ng Moi) who sat beside me at the front left hand side had a chest pain due to the pulling of the safety belt. She complained that she have difficulties in breathing after the accident. My sister (Sw Sook Fun) who sat directly behind her got her head knocked against the safety belt feature and had acute pain after the accident. Hence, both was sent to KTPH for X-ray just to ensure that there is no fracture in their bones.

Both were given Medical leave for 3 days and discharged between 2 to 3 pm.

Subjects Involved			
Victim			
Person Name	SW CHAN KIT		
ID Type	NRIC NO	ID No	S1584538D
Gender	Male	Age	58
Race	Chinese	Language	English
Occupation	Accountant	Address	2 SEMBAWANG WALK #01-85 SINGAPORE 757616
Mobile No	97545918	Is Informant A Victim?	Yes
Person Name	SW CHAN KIT (Informant)		

Signature Of Officer Recording The Report:

Not applicable

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

Signature Of Informant:

The identity of the person making this report has been authenticated by Singpass. No signature is required.

Date/Time:
15/01/2022 17:35

Classification Of Case: