



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22000668/Kqf3e2	
			Date: 17/03/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 4885B	Veh. Inspected	SDS 5515B
	Policy No.		Coverage (\$)	0.00
	Claim No.	D22000046MFVS	Excess (\$)	0.00
	Assign From	CAROLINE CABRERA	Assign Date	19/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ E200	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	WDD2130422A446624	Colour	METALLIC LIGHT BLUE
	Odometer	103464 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/40 R18	PIRELLI	8 mm
	L/H Front Tyre	245/40 R18	PIRELLI	8 mm
	R/H Rear Tyre	245/40 R18	PIRELLI	8 mm
	L/H Rear Tyre	245/40 R18	PIRELLI	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/12/2021	Inspection Date	19/01/2022
	Survey held at	MENG WHEE BROS MOTOR SERVICE BLK 10 ANG MO KIO IND PARK 2A #05-25 SINGAPORE 568047		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	