

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	ALLIED WORLD A	SSURANCE COMPANY LTD	R	tef:	CS3/AWA22000679/Vqf3e2	
		NCH) 60 ANSON ROAD #08-01 LETREE ANSON SINGAPORE	D	ate:	04/02/2022	
			С	ode:	AWA	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBD 3643E	Veh. Inspected		SMT 8437L	
	Policy No.	BVFCSB0007242114	Coverage (\$)		0.00	
	Claim No.	NSV2200008/PC	Excess (\$)		0.00	
	Assign From	STELLA GOH	Assign Date		19/01/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA SHUTTLE	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	GP72009049	Colour		WHITE	
	Odometer	48460 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	185/60 R15	YOKOHAMA		7 mm	
	L/H Front Tyre	185/60 R15	YOKOHAMA		7 mm	
	R/H Rear Tyre	185/60 R15	YOKOHAMA		7 mm	
	L/H Rear Tyre	185/60 R15	YOKOHAMA		7 mm	
4.	Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR PORTION.				
5.	. General Information					
	Accident Date	15/01/2022	Inspect Date / Ti	me	19/01/2022 ( 12:00 PM )	
	Survey held at	1969 S B AUTO MAC PTE LTD				
		2 KAKI BUKIT AVENUE 2, #02-09, KAKI BUKIT AUTOHUB, SINGAPORE 417921				
5a.	Remarks					
	B) THE REPAIR ES THE REPAIRER W C) ENCLOSED PLI	THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. E REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b.	Estimate Days of Repair					
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:	4	Worki	ng Days	

Report Ref No. CS3/AWA22000679/Vqf3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

L

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser