ASS. REC. BY: Stove REF: CS/ASM77	000693/Eq.y3
PRS . ASSIC	FINMENT
From: Date:	Veh No: SKN 218517 Yr Regn: 23/5/14
Estimated Cost:	Type: M.Car/ M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD / TPY WS / TP RES / OD RES / EVA / INV / MY	Truck / Trailer or
To Inspect Vehicle No:	Make: 13 MW X 3 c.c 1997
at Workshop m/s	Colour Silver A/C: Insured / Std / NI / NA
of	Sp.Reading 173931 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: WBAWX371900B18693
Claims No. S2M03RCO	Gen. Cond: Good / Fall / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nii / SIRIm / STD A/Rim or Tyre Size: F: 245/50 R18
(Policy Condition) Permerks The year had commenced its	BS / DUN / EXNOVA GH FS / LIZA / MIC / OHTSU / PIR / SUMI /
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	TOYO / YOKO or Pirelli
to the first the second second	Dave
Bal. or Market Value: 70K(est)	R/Bal. 5 mm R/Bal. 5 mm
IDAC Accident Rport: Consistent? : Yes or No CIA / PR Seen: Consistent? : Yes or No	L/Bal. 5 mm L/Bal. 5 mm
GIA / FIX Occil.	D.O.A. 16/1/22 D.O.I. 19/1/22
Est. Repairs: 6 days Res.: Yes or No Lum Sum: % 3 Val.: Yes or No	Survey held at Gold AutoWorks
2.74.5	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	Front LH
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
Estimate COR: \$6000-\$7000; 6 repair days.	
26/01/22@12.08pm revised to Kitty Teo via Smart Claims	
26/01/22 Submit PRS	
Date/Time, File Pass to? : Prell. Report Days Of Repair: 6	
Date/Time, File Pass to? : Prell. Report	Resurvey No. of Trip: 1 Survey Fee:
1) 26/01 Typist : Final Report Date/Time, File Return to?	Transportation:
2)Add Fe	The state of the s
	: Interview (\$) Photos
Report Format: SMART CLAIMS - PRS Lump Sum / I.B.I: (\$: Weekend (\$
Lamp cam / mam (4	TOTAL