



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: ONG KIAN THENG DERICK			Ref: CS/ASM22000701/Ety3e2 Date: 25/02/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLD 8852S	Veh. Inspected	SJM 4304K	
Policy No.	GA576246	Coverage (\$)	0.00	
Claim No.	S2M03RB3	Excess (\$)	0.00	
Assign From	ONG KIAN THENG DERICK	Assign Date	19/01/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA FIT	c.c	1339	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	GE61138275	Colour	WHITE	
Odometer	127167 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	GOODYEAR	4 mm	
L/H Front Tyre	195/55 R15	GOODYEAR	4 mm	
R/H Rear Tyre	195/55 R15	GOODYEAR	4 mm	
L/H Rear Tyre	195/55 R15	GOODYEAR	4 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	15/01/2022	Inspection Date	09/02/2022	
Survey held at	WIN AUTOMOTIVE SERVICES BLK 6, 399J WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 678008			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	