

## VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052

Steve (CLKK)  
20/1/22, 10.30am  
ON-MAL  
EXCISE?  
P/P  
M BL Y  
15 dys



## Quotation

Non binding - Preview

Company  
INDIA INTERNATIONAL INSURANCE  
64 CECIL STREET  
#04-05 IOB BUILDING  
Singapore 049711

Customer Details:  
Mr  
CHIA  
CHUEN HUEI  
401 SERANGOON AVENUE 1  
#11-15  
Singapore 550401

Page 1/4  
Document no.  
Document date 19-01-2022  
Customer no. 5211000972  
Customer GST-ID 198703792K  
Dealer 30001  
Job order number 2022002135/ 1  
Job order date 18-01-2022  
Service Advisor Dass Anthonidas Christopher

License plate SKP6909A	Model code 1T332Z	First registration 30-09-2014	VIN WVGZZZ1TZEW103171	Model TOURAN 1.6BMTCOMFO 77 TDID7F	Mileage 20
---------------------------	----------------------	----------------------------------	--------------------------	---------------------------------------	---------------

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
9801B002	B&P LEAKED CHECK VACUUM & REGAS				#1	420.00	449.40
9801B002	A/C GAS				#1	60.00	64.20
9801B001	R&R ENGINE				#1	1,938.00	2,073.66
9801B003	B&P WHEEL ALIGNMENT				#1	360.00	385.20
9801B001	R&R RIM & BALANCE				#1	50.00	53.50
2K0819403 9B9	Water Deflector Satin Black	1	pcs.	147.75	#1	147.75	158.09
1T0823031Q	WIPER COWLING	1	pcs.	1,220.74	#1	1,220.74	1,306.19
1T0823301F	Hood	1	pcs.	145.09	#1	145.09	155.25
1T0823301F	FRT BONNET	1	pcs.	145.09	#1	145.09	155.25
1T0823302F	Flap Hinge	1	pcs.	145.09	#1	145.09	155.25
1K8823186F 9B9	BONNET HINGE LH	1	pcs.	110.54	#1	110.54	118.28
N 90820401	Flap Hinge	1	pcs.	110.54	#1	110.54	118.28
1T2823531E	BONNET HINGE RH	1	pcs.	110.54	#1	110.54	118.28
5N0823411A	Hook Satin Black	1	pcs.	110.54	#1	110.54	118.28
WHT000425	BONNET LATCH	1	pcs.	110.54	#1	110.54	118.28
1T0807221M GRU	Bolt Hex. Hd.	2	pcs.	4.00	#1	8.00	8.56
1T0805903D 9B9	Cable Hood Latch	1	pcs.	49.47	#1	49.47	52.93
1T0807109D	LOCK CABLE	1	pcs.	18.87	#1	18.87	20.19
N 10699701	Holder For Bowden Cable	1	pcs.	18.87	#1	18.87	20.19
5K0807651D	Hexagon Socket Oval Head	2	pcs.	2.77	#1	5.54	5.93
1T0807248K	Cover For Bumper Primed	1	pcs.	1,348.15	#1	1,348.15	1,442.52
1T0807183C	Spoiler Satin Black	1	pcs.	372.22	#1	372.22	398.28
1T0807184C	Impact Beam	1	pcs.	678.70	#1	678.70	726.21
1K0825237AG	REINFORCEMENT	1	pcs.	678.70	#1	678.70	726.21
1T0853651BQPWF	Bolt Hex. Hd. With Should	8	pcs.	5.18	#1	41.44	44.34
1T0853677D 9B9	Cross Member	1	pcs.	301.99	#1	301.99	323.13
1T0853101B ZZZ	Foam Insert	1	pcs.	80.40	#1	80.40	86.03
1T0853666R 9B9	Guide Piece	1	pcs.	59.03	#1	59.03	63.16
1T2941005H	BUMPER SIDE BRACKET LH	1	pcs.	59.03	#1	59.03	63.16
	Guide Piece	1	pcs.	59.03	#1	59.03	63.16
	BUMPER SIDE BRACKET RH	1	pcs.	59.03	#1	59.03	63.16
	Sound Baffle	1	pcs.	277.90	#1	277.90	297.35
	ENGINE LOWER COVER	1	pcs.	277.90	#1	277.90	297.35
	Radiator Grille With Blac	1	pcs.	416.73	#1	416.73	445.90
	Cooling Air Grill Satin B	1	pcs.	321.61	#1	321.61	344.12
	BUMPER CTR LOWER GRILLE	1	pcs.	321.61	#1	321.61	344.12
	Decorative Moulding Brigh	1	pcs.	284.33	#1	284.33	304.23
	BUMPER CTR LOWER GRILLE CHROM	1	pcs.	284.33	#1	284.33	304.23
	Cover Part For Bumper Sat	1	pcs.	160.30	#1	160.30	171.52
	RHS FOG LAMP GRILLE	1	pcs.	160.30	#1	160.30	171.52
	Twin Halogen Headlamps	1	pcs.	836.48	#1	836.48	895.03
	LH	1	pcs.	836.48	#1	836.48	895.03



## VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation

Non binding - Preview

Page

2/4

Company  
INDIA INTERNATIONAL INSURANCE  
64 CECIL STREET  
#04-05 IOB BUILDING  
Singapore 049711

Customer Details:  
Mr  
CHIA  
CHUEN HUEI  
401 SERANGOON AVENUE 1  
#11-15  
Singapore 550401

Document no.  
Document date  
Customer no.  
Customer GST-ID  
Dealer  
Job order number  
Job order date  
Service Advisor  
19-01-2022  
5211000972  
198703792K  
30001  
2022002135/ 1  
18-01-2022  
Dass Anthonidas  
Christopher

License plate	Model code	First registration	VIN	Model	Mileage
SKP6909A	1T332Z	30-09-2014	WVGZZZ1TZEW103171	TOURAN 1.6BMTCOMFO 77 TDID7F	20

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
1T2941006H	Twin Halogen Headlamps	1	pcs.	836.48	#1	836.48	895.03
	RH						
N 91095301	Bolt Hex. Hd.	2	pcs.	1.63	#1	3.26	3.49
1K8941297	Adapter	2	pcs.	6.50	#1	13.00	13.91
6R0973735	Flat Contact Housing	2	pcs.	22.74	#1	45.48	48.66
	H/LAMP WIRE HOUSING						
1T0805588AF9B9	Lock Carrier With Mountin	1	pcs.	999.78	#1	999.78	1,069.76
5C6010008	Sticker 'Ac' *Refrigeran	1	pcs.	16.18	#1	16.18	17.31
701010002AA	Kennschild *Bei Ölüberfü	1	pcs.	16.43	#1	16.43	17.58
1T0805567A	Support For Lock Carrier	1	pcs.	132.60	#1	132.60	141.88
1T0805931A	Cross Support	1	pcs.	63.51	#1	63.51	67.96
	H/LAMP TOP PANEL LH						
1T0805932A	Cross Support	1	pcs.	63.51	#1	63.51	67.96
	H/LAMP TOP PANEL RH						
1K0805971C 9B9	Air Duct Satin Black	1	pcs.	51.70	#1	51.70	55.32
1K0805962E 9B9	Intake Air Duct Satin Bla	1	pcs.	15.93	#1	15.93	17.05
1K0805965J 9B9	Intake Air Duct Satin Bla	1	pcs.	16.94	#1	16.94	18.13
1K0129618BQ	Air Duct	1	pcs.	35.99	#1	35.99	38.51
	U- AIR HOSE						
1K0820411AH	Refrigerant Condenser Wit	1	pcs.	834.64	#1	834.64	893.06
4E0260749A	Seal Ring	1	pcs.	7.08	#1	7.08	7.58
3D0260749C	Seal Ring	1	pcs.	6.46	#1	6.46	6.91
G 055535M2	Oil For Refrigerant Compr	0.1	pcs.	391.45	#1	39.15	41.89
	A/C OIL						
1K0145803CG	Charge Air Cooler	1	pcs.	726.79	#1	726.79	777.67
1K0121251AB	Radiator	1	pcs.	768.68	#1	768.68	822.49
G 12E050A2	Coolant 1B	2	pcs.	22.95	#1	45.90	49.11
1K0959455ET	Electric Fan	1	pcs.	646.47	#1	646.47	691.72
1K0959455FR	Electric Fan	1	pcs.	964.80	#1	964.80	1,032.34
1T0121284D	Air Duct	1	pcs.	47.06	#1	47.06	50.35
	AIR GUIDE RH						
1T0121283D	Air Duct	1	pcs.	47.06	#1	47.06	50.35
	AIR GUIDE LH						
1T0121330	Air Duct	1	pcs.	28.08	#1	28.08	30.05
	AIR GUIDE UPPER						
1K0955453S	Wash Water Reservoir	1	pcs.	153.35	#1	153.35	164.08
	WIPER TANK						
7M0919382	Seal Ring	1	pcs.	13.75	#1	13.75	14.71
8E0955465A	Plug	1	pcs.	2.25	#1	2.25	2.41
431955465A	Gasket	1	pcs.	5.73	#1	5.73	6.13
444955647	Plug	1	pcs.	8.97	#1	8.97	9.60
1K0199262CN	Engine Mounting	1	pcs.	379.16	#1	379.16	405.70
N 10552402	Bolt Hex. Hd. With Should	2	pcs.	8.65	#1	17.30	18.51
N 90596906	Bolt Hex. Hd. With Should	1	pcs.	13.62	#1	13.62	14.57
N 91029602	Double Hex. Hd. Bolt	1	pcs.	13.22	#1	13.22	14.15
N 01950213	Bolt Hex. Hd. With Should	2	pcs.	4.08	#1	8.16	8.73
1K0199555N	Gearbox Mounting	1	pcs.	252.49	#1	252.49	270.16



## VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation

Non binding - Preview

Page

3/4

Company  
INDIA INTERNATIONAL INSURANCE  
64 CECIL STREET  
#04-05 IOB BUILDING  
Singapore 049711

Customer Details:  
Mr  
CHIA  
CHUEN HUEI  
401 SERANGOON AVENUE 1  
#11-15  
Singapore 550401

Document no.  
Document date  
Customer no.  
Customer GST-ID  
Dealer  
Job order number  
Job order date  
Service Advisor  
19-01-2022  
5211000972  
198703792K  
30001  
2022002135/ 1  
18-01-2022  
Dass Anthonidas  
Christopher

License plate	Model code	First registration	VIN	Model	Mileage
SKP6909A	1T332Z	30-09-2014	WVGZZZ1TZEW103171	TOURAN 1.6BMTCOMFO 77 TDID7F	20

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
N 90596906	Bolt Hex. Hd. With Should	4	pcs.	13.62	#1	54.48	58.29
N 10552402	Bolt Hex. Hd. With Should	2	pcs.	8.65	#1	17.30	18.51
1T0821021D	Fender LH	1	pcs.	689.67	#1	689.67	737.95
1T0821135C	Cross Support	1	pcs.	45.81	#1	45.81	49.02
1T0805911N	LHS FENDER BRACKET	1	pcs.	205.69	#1	205.69	220.09
1T0821022D	Wheelhouse Liner	1	pcs.	689.67	#1	689.67	737.95
1T0821136C	LHS FENDER LINER	1	pcs.	45.81	#1	45.81	49.02
1T0805912G	Cross Support	1	pcs.	205.69	#1	205.69	220.09
1T0853515F GRU	RHS FENDER BRACKET	1	pcs.	232.85	#1	232.85	249.15
5G0073147A FZZ	Wheelhouse Liner	1	pcs.	883.30	#1	883.30	945.13
311601361	RHS FENDER LINER	1	pcs.	3.85	#1	3.85	4.12
WHT005437A	Protection Strip For Door	1	pcs.	10.76	#1	21.52	23.03
N 91108201	LHS FRT DOOR MLDG	2	pcs.	5.05	#1	60.60	64.84
N 90942902	Wheel Disc 'Alum.' With	12	pcs.	3.60	#1	7.20	7.70
N 10332002	Rubber Valve	2	pcs.	3.12	#1	18.72	20.03
N 0150816	12-Point Socket Shoulder	6	pcs.	3.21	#1	6.42	6.87
N 10558002	Screw	2	pcs.	9.22	#1	9.22	9.87
N 91167101	Hex. Nut Self-Locking	1	pcs.	6.11	#1	6.11	6.54
N 91066101	Shouldered Hex. Nut	1	pcs.	6.02	#1	6.02	6.44
	Shouldered Hex. Nut	1	pcs.	195.00	#1	195.00	208.65
	Bolt Hex. Hd.	1	pcs.	840.00	#1	840.00	8,089.20
	Bolthex.Hd.With Shoul.	1	pcs.	800.00	#1	800.00	7,704.00
	Bolt Hex. Hd.	1	pcs.	1,500.00	#1	1,500.00	1,605.00
	Towing assistance - AWP	1	pcs.	80.00	#1	80.00	85.60
	LABOUR						
	SPRAY PAINT						
	VEHICLE ON BENCH - CELETTE						
	FRT NUMBER PLATE						
	INDIAN INTERNATIONAL INSURANCE OD						
	DOA:18/01/2021						
	EXCESS:						
	SURVEY BY:						

Quotation valid till 25-01-2022

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	3,588.00	34,175.29	7%	2,643.43	37,763.29	40,406.72
Total	3,588.00	34,175.29		2,643.43	37,763.29	40,406.72

# VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation

Non binding - Preview

Page	4/4
Document no.	19-01-2022
Document date	5211000972
Customer no.	198703792K
Customer GST-ID	30001
Dealer	2022002135/ 1
Job order number	18-01-2022
Job order date	Dass Anthonidas
Service Advisor	Christopher

Company  
INDIA INTERNATIONAL INSURANCE  
64 CECIL STREET  
#04-05 IOB BUILDING  
Singapore 049711

Customer Details:  
Mr  
CHIA  
CHUEN HUEI  
401 SERANGOON AVENUE 1  
#11-15  
Singapore 550401

License plate	Model code	First registration	VIN	Model	Mileage
SKP6909A	1T332Z	30-09-2014	WVGZZZ1TZEW103171	TOURAN 1.6BMTCOMFO 77 TDID7F	20

Customer

Service Advisor

—VISIT OUR WEBSITE: [aftersales.vw.com.sg](https://aftersales.vw.com.sg) (for online service appointments) and [volkswagen.com.sg](https://volkswagen.com.sg) and [www.skoda.com.sg](https://www.skoda.com.sg) (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission ..... 18/01/2022 17:03 (SGT)  
Date of Accident ..... 18/01/2022 12:17 (SGT)  
Exact Location of Accident ..... 209 Hougang Street 21, Singapore 530209  
Additional Location Information ..... -  
Country/State of Loss ..... Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SKP6909A

#### INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... CHIA CHUEN HUEI  
NRIC No ..... S1751209I  
Email Address ..... chia1668@gmail.com  
Mobile Phone No ..... (Phone) +65-81260863  
Alternative Phone No ..... +65-81260863

#### VEHICLE PARTICULARS

Manufacturer ..... Volkswagen  
Model ..... Touran  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private use  
Are you claiming under your own insurance policy for repair to your vehicle? ..... Yes  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 1600

#### INSURANCE COMPANY

Name of Insurance Company ..... India International Insurance Pte Ltd  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... D18MPC0001826\_03  
Cover Note Number ..... -

#### DRIVER

Name of Driver ..... CHIA CHUEN HUEI  
NRIC No ..... S1751209I



Date Of Birth	21/03/1966
Occupation	Indoor
Date Of Driving Pass	28/09/1985
Driving experience	36 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-81260863
Alt. Phone Number	+65-81260863
Email Address	chia1668@gmail.com
Address	BLK 401 SERANGOON AVENUE 1 #11-15
Address complement	-
Postcode	550401
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Major/Minor Rd
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO STATEMENT AND SKETCH

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD79H
Vehicle Manufacturer	Renault
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	CHERN YOUNG
Contact Number	-
Address	-
Address complement	-

Police Code ..... -  
Insurance Company Name ..... -  
Nature Of Damage ..... -  
Details of property damaged in accident ..... -  
No. Of Passenger (Including Driver) ..... -

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

18/1/2022


Sketch Plan



Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel



A - My Vehicle  
SPR 6909A

B TAXI  
SHD 79H



## Describe Circumstances of the Accident

On 18th Jan 2022 @ around 12.17pm, I (veh CKP 6909A) exited from the parking lot after looking to my right. I saw the taxi was quite a safe distance away and I moved out of my parking lot and turn left. Suddenly I heard and felt a loud banging sound and saw that taxi (SHD 79H) collided my car at the right front fender & tyre area. The taxi was moving very fast, more than usual carpark speed.

## Declaration

We declare the foregoing particulars are true in every respect.

*Amalinder*

Policyholder's Signature / Date & Time  
18/1/2022

Driver's Signature (if driver is not the policyholder) / Date & Time


*[Signature]*

Witnessed by Reporting Centre Personnel

## CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

**All Accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.**

CERTIFICATE NO.: D18MPC0001826_03		COVER: COMPREHENSIVE
1. Index Mark and Registration Number of Vehicle	: SKP6909A	
Chassis No	: WVGZZZITZEW103171	
2. Name of Policyholder	: CHIA CHUEN HUEI	
3. Effective date of Insurance	: 30 Sep 2021	
4. Expiry date of Insurance	: 29 Sep 2022	
5. Persons or Classes of Persons entitled to drive*		
(a) The Policyholder The Policyholder may also drive a Motor Car not belonging to or hired (under a hire purchase agreement or otherwise) to him/her or his/her employer or his/her partner.		
(b) Any other person who is driving on the Policyholder's order or with his/her permission. Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle		
6. Limitations as to use*		
Use only for social, domestic and pleasure purposes and for the Policyholder's business.		
<b>The Policy does not cover</b>		
a) Use for hire or reward. b) Use for racing, pace-making, reliability trial, speed-testing. c) Use for the carriage of goods other than samples in connection with any trade or business. d) Use for any purpose in connection with the Motor Trade.		
*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.		
Insured & Named Drivers Excess Sect I : SGD500.00 Unnamed Drivers Excess Sect I : SGD1,000.00 Windscreen Excess : SGD100.00 Hire Purchase Company : N.A		
<b>FOR DRIVERS BELOW 21 YEARS OR ABOVE 69 YEARS OF AGE &amp;/OR LESS THAN 2 YEARS SINGAPORE DRIVING LICENCE, ADDITIONAL EXCESS OF \$2500/- ON SECTION I WILL BE APPLICABLE.</b>		
I/We HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).		
Agent/Broker : B000018/COMFORTDELGRO INSURANCE BROKERS PTE LTD Date of Issue : 20/09/2021 11:22:19 MX1-Private Car (Insured Driving)		For India International Insurance Pte Ltd <div style="text-align: center; margin-top: 20px;">   <hr style="width: 100%; border: 0.5px solid black;"/>             Authorised Signatory           </div>



# VEHICLE CONDITION REPORT FORM / JOB RECORD

Date: 15/01/2022 Time: 1312  
Technician Name: HO: 226972  
Reg. No: SXP 6909A Job No: V522000190  
Odometer Reading (Customer Vehicle): 167485  
KM Travelled by Assistance Vehicle: (1 way)  
Fault Reported: Accident  
Fault Found:  
How was vehicle repaired?

Customer Name: mu ch.g  
Customer Telephone: 8126 0863  
Make/Model: VW, Taurus  
Location: 401, Serangan Ave 1  
Time on Scene: 1331  
Time Job Completed: 1350  
Repaired at Breakdown Scene: Y/N  
VIN No:


Hubcaps Y/N  
Spare Wheel Y/N  
Tools Y/N  
Audio System Y/N  
Keys + Remote Y/N  
Aerial Y/N  
Cashcard Y/N  
Fuel E ☐ F

Day/Night Wet/Dry Clean/Soiled

Please circle the above as appropriate

Place X on damaged area for scratch and Y for dent

Interior Condition :  
Front Seats  
Rear Seats  
Floor Covering  
Headlining



Delivery to Dealership / Date and Time:

VW, SXP 18/01/2022 1423

Vehicle received in the above condition YES/NO

If not stated as above specify difference:

## CUSTOMER DECLARATION

- I am entitled to the service requested. In the event of this subsequently not being the case I shall be responsible for the cost of any assistance provided.
- I accept that any roadside repairs will be of a temporary nature and that advice of a franchised dealer should be sought by me as soon as possible.
- In the case of forced entry, I confirm that I specifically requested that the operator forcefully enter the vehicle and that all damages occasioned thereby is and shall be my sole responsibility.
- I accept that any removable items left in the vehicle will not be the responsibility of the emergency service or their agents.

Customer Name & Signature (green copy)	Dealer/Workshop Signature, Name & Stamp (yellow copy)	Operators Signature (white & pink copy)
--	---	---



