



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: ONG KIAN THENG DERICK			Ref: CS/ASM22000709/Ety3e2 Date: 17/03/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	XD 2743X	Veh. Inspected	XE 5992T	
Policy No.	GA537671	Coverage (\$)	0.00	
Claim No.	S2M03R58	Excess (\$)	0.00	
Assign From	ONG KIAN THENG DERICK	Assign Date	19/01/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MERCEDES BENZ AROCS	c.c	7698	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	W1T96401420464256	Colour	WHITE	
Odometer	42219 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	DUNLOP	4 mm	
L/H Front Tyre	295/80 R22.5	DUNLOP	4 mm	
R/H Rear Tyre	295/80 R22.5	DUNLOP	4 mm	
L/H Rear Tyre	295/80 R22.5	DUNLOP	4 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	13/01/2022	Inspection Date	20/01/2022	
Survey held at	ZENITH ENGINEERING PTE LTD NO. 34 JOO KOON CIRCLE SINGAPORE 629060			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	