

Case Details

Case Reference Number : TAX/01/22/2032
Type of Repair : Accident Repair
Vehicle Registration Number : SHB1222P

Company Type : Strides Taxi Pte Ltd
Estimation ID : EST-17258-ID
Assigned By : Wei Siong #

Insurance Company Name : NTUC Income Insurance Co-operative Ltd
Accident Date and Time : 16/01/2022 03:25 AM
Vehicle Age(In Months) : 4

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			DOOR ASM-FRT SI-R	1	2,338.44	2,338.44	10.00	2,104.60	Replace	1	2,104.60	Replace	bf
One Time Key In	Main			DOOR ASM-RR SI-R	1	2,185.04	2,185.04	10.00	1,966.54	Replace	1	1,966.54	Replace	bf
One Time Key In	Main			PANEL-BODY SI OTR RR-R	1	977.08	977.08	10.00	879.37	Replace	1	879.37	Repair	bf-Repair
One Time Key In	Main			FASCIA-RR BPR	1	758.47	758.47	10.00	682.62	Replace	1	0	Repair	R
One Time Key In	Main			WHEEL	1	618.07	618.07	10.00	556.26	Replace	1	0	Repair	R
One Time Key In	Main			MIRROR ASM-O/S RR VIEW-R	1	478.40	478.40	10.00	430.56	Replace	0	0	Not Give	Xm
One Time Key In	Main			REGULATOR ASM-FRT S/D WDO-R	1	444.50	444.50	10.00	400.05	Replace	0	0	Check	?xm
One Time Key In	Main			FENDER ASM-FRT-R	1	379.81	379.81	10.00	341.83	Replace	0	0	Not Give	Xm
One Time Key In	Main			REGULATOR ASM-RR S/D WDO-R	1	265.30	265.30	10.00	238.77	Replace	0	0	Check	?xm
One Time Key In	Main			MOTOR ASM-FRT S/D WDO REG-R	1	248.04	248.04	10.00	223.24	Replace	0	0	Not Give	Xm
One Time Key In	Main			MOTOR ASM-RR S/D WDO REG-R	1	169.00	169.00	10.00	152.10	Replace	0	0	Not Give	Xm
One Time Key In	Main			LATCH ASM-FRT S/D-R	1	158.91	158.91	10.00	143.02	Replace	0	0	Not Give	Xm

Total Spare Part Cost 8,645.93

Lump Sum Discount (%) 0.00

Final Spare Part Cost 8,645.93

Surveyor Total 5,010.51

Lump Sum Dis (%) 0


Final Sur Total 5,010.51

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			LATCH ASM-RR S/D -R	1	139.98	139.98	10.00	125.98	Replace	0	0	Not Give	X _{an}
One Time Key In	Main			LINER ASM-RR WH PNL -R	1	85.49	85.49	10.00	76.94	Replace	0	0	Not Give	X _{an}
One Time Key In	Main			HINGE ASM-RR S/D LWR-R	1	47.22	47.22	10.00	42.50	Replace	0	0	Not Give	X _{an}
One Time Key In	Main			HINGE ASM-RR S/D UPR-R	1	46.90	46.90	10.00	42.21	Replace	0	0	Not Give	X _{an}
One Time Key In	Main			BRACKET-RR BPR FASCIA SI MTG	1	46.07	46.07	10.00	41.46	Replace	0	0	Check	?X _{an}
One Time Key In	Main			HOUSING-O/S RR VIEW MIR-R	1	34.53	34.53	10.00	31.08	Replace	0	0	Not Give	X _{an}
One Time Key In	Main			INSULATOR ASM-F/FDR-R	1	29.22	29.22	10.00	26.30	Replace	0	0	Not Give	X _{an}
One Time Key In	Main			CHECK ASM-FRT S/D-R	1	21.01	21.01	10.00	18.91	Replace	0	0	Not Give	X _{an}
One Time Key In	Main			CHECK ASM-RR S/D -R	1	21.01	21.01	10.00	18.91	Replace	0	0	Not Give	X _{an}
One Time Key In	Main			STRIKER-FRT S/D LK	1	16.74	16.74	10.00	15.07	Replace	0	0	Not Give	X _{an}
One Time Key In	Main			BRACKET-RR BPR FASCIA LWR MTG	1	12.79	12.79	10.00	11.51	Replace	0	0	Not Give	X _{an}
One Time Key In	Main			COVER ASM-WHL TR	1	8.94	8.94	10.00	8.05	Replace	0	0	Not Give	X _{an}
One Time Key In	Main			INSULATOR ASM-F/FDR MID	1	8.94	8.94	10.00	8.05	Replace	0	0	Not Give	X _{an}
Standard	Main			STICKER STRIDES TAXI (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	ne
Total Spare Part Cost									8,645.93	Surveyor Total 5,010.51				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									8,645.93	Final Sur Total 5,010.51				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	4,800.00	1,250	1000
Total:			4,800.00	1,250.00	

Spray Cost Detail

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	7,600.51
Surveyor Approved Amount		7,600.51
No of Repair Days*	10	7
Remarks		PART BY PART REPAIR / RESURVEY BEFORE PAINT PHOTO.
Surveyor Name		Rasul
Signature		
		Save Clear
Survey Date	19/01/2022	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: