



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22000713/Avf3n2	
			Date: 18/03/2022	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SMJ 5559R	Veh. Inspected	SJB 3888G
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2200281/SYH	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	20/01/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	MERCEDES BENZ E 200	c.c	1796
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	WDD2120482A349846	Colour	GREY
	Odometer	158273 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	245/45 R17	CONTINENTAL	6 mm
	L/H Front Tyre	245/45 R17	CONTINENTAL	6 mm
	R/H Rear Tyre	245/45 R17	CONTINENTAL	6 mm
	L/H Rear Tyre	245/45 R17	CONTINENTAL	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	18/01/2022	Inspection Date	24/01/2022
	Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	