

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000724/UTY3N2**Date:** 20/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00208022101	
Claimant Vehicle No :	SMG7954K	Insured Vehicle No :	SKW9869A	
Date of Loss:	15/01/2022	Nature of Claim:	TP	Claim No: SNM22D200437/C02/CHEESC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG7954K	Engine No:	HR16937636C
Make & Model:	NISSAN SYLPHY, 1.6 CVT (A)	Chassis No:	MNTBBAB17Z0033943
Reg. Date:	31/12/2018 (Man. Year: 2018)	Odometer:	43606 km
Colour:	Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60R16	Rear Tyre Size:	195/60R16
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,640.00	5,290.00	3,350.00	38.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,024.40	2,011.80	12.60	0.62
Paintwork Labour	1,279.06	1,522.31	-243.25	-19.02
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	11,943.46	8,824.11	3,119.35	26.12
+ GST 7.00/7.00% (\$\$)	836.04	617.69	218.35	26.12
Nett Amount (\$\$)	12,779.50	9,441.80	3,337.70	26.12

INSPECTION

Date of Assignment:	15/02/2022	Present Location:	Jin Auto Services Pte Ltd (Defu)
Date Inspected:	20/01/2022	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	24.0 days		

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 May 2022)
Parts:	143	NISSAN SYLPHY 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG7954K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		8,540.00 F	*5,190.00 F
2	1		*SUNDRY		100.00 F	*100.00 F
F=Franchise part.						
Total Parts (S\$)					8,640.00	5,290.00
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TOTAL PAINT LABOUR	New	1,279.06	1,522.31
<u>Labour Items</u>				
2	TOTAL LABOUR	New	2,024.40	2,011.80
Gross Labour Cost (\$)			3,303.46	3,534.11

Report was unsubmitted during this print-out.

< END OF ESTIMATES >