



Your Ref: S1M03H4N

Date: 28th Jan 2022

Our Ref: CS3/ASM21009735/Bqy3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn: Teo Kitty

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SDV 4007S
INSURED VEHICLE: SHA 7895M
ACCIDENT DATE: 01/09/2021**

We thank you for your instruction on 20/01/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SDV 4007S from M/s Par Automotive Consultancy.
- b) Singapore Accident Statement of Vehicles SDV 4007S and SHA 7895M.
- c) Final Repair Bill of SDV 4007S from M/s Hiap Lek Automobile Trading.
- d) Colour damaged vehicle photographs of SDV 4007S.

Pre-Repair Inspection Date : 17/09/2021 at M/s Hiap Lek Automobile Trading, 160 Sin Ming Drive #05-17 Sin Ming Autocity, Singapore 575722.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SDV 4007S
Make & Model	: Volvo XC60 T5
Year of Registration	: 2015
Chassis Number	: YV1DZ40LDF2661858
Engine Capacity	: 1969 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.