

ASS. REC. BY:

Steve

REF:

CS/CT122000763/ETY3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLK 3541K Yr Regn: 13/1/17Type: ☒ M.Car ☐ M.Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover ☐

Truck / Trailer or

Make: Toyota Prius c.c. 1798Colour: Silver A/C: ☐ Insured ☐ Std ☐ NI ☐ NASp. Reading: 249753 T/Radio: ☐ Insured ☐ Std ☐ NI ☐ NA

Eng/No: \_\_\_\_\_

C/No: JTDKB3FU603543723Gen. Cond: ☒ Good ☐ Fair ☐ Poor ☐ BurntSteering: ☒ Inorder ☐ Jammed ☐ Leaked ☐ Burnt orBrake: ☒ Inorder ☐ Jammed ☐ Leaked ☐ Burnt orMod: ☐ Nil ☒ S/Rim ☐ STD A/Rim orTyre Size: F: R5/55R15R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Toy

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 4 mm R/Bal. 4 mmL/Bal. 4 mm L/Bal. 4 mm

D.O.A. \_\_\_\_\_ D.O.I. \_\_\_\_\_

Survey held at \_\_\_\_\_

Des. of Damages: ☐ Frt ☐ Rear ☐ O/S ☐ N/S ☐ U/C ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time \_\_\_\_\_ Action / Instruction

MV-61K

We will be advising our Principal a cost of repair of \$18,327.30 (P/P before GST) - with 11 days of repair,

RED:10064.6 ;34%

28931.9

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: 11

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL



# Borneo Motors



# TOYOTA

Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No. 2 PANDAN CRESCENT  
SINGAPORE 128462, Tel no. : 6631 1188

*Steve (LKK)*  
*21/1/22, 11.30am*

*Mr P*  
*11 dys*  
*P/P*  
*My B/L*

## ESTIMATE

Account Details		Account No.	Customer Details				
THIRD PARTY CLAIM <i>Ching</i>		S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd				
		Document No. 0	6 Battery Road #38-04 Singapore 049909				
		Document Date 20/01/2022	Work: 65703925				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZVW50R	AHXEBW Q2	13/01/2017	SLK3541K	0	12900	75/DS/SLK3541K
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKB3FU603543723		2ZRR990124	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.: GBL524T ACC DATE: 18/01/22 TOW IN: 18/01/22 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50	100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR REAR RH DOOR					60.00 ✓
3	S	BP-SUBLET TO REPLACE REAR RH TYRE AND SPORT-RIM TO BALANCE.					180.00 ✓
4	B	BP-ECU2 TO RESET ECU AND REPROGRAMME					180.00 ✓
5	B	BP-MECH2 TO CONDUCT WHEEL ALIGNMENT CHECK.					180.00 ✓
6	B	BP-MECH2 R/I REAR SUSPENSION TO CHECK AND REPLACE NECESSARY PARTS. <i>(photo not held)</i>					1440.00
7	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.					122.40 ✓
8	B	BP-LAB2 R/I REAR CARPET, TRIMMINH, REAR SEATS AND ALL OTHER ATTACHMENT TO FACILITATE REPAIRS. <i>(photo)</i>					720.00 ✓
9	B	BP-LAB2 TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS. <i>720 x 7</i>				5040	7200.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature	Charge Summary		Total		
		Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others		Less		
					Amount Due		

Customer Copy





# Borneo Motors

Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No 2 PANDAN CRESCENT  
SINGAPORE 128462, Tel no 6631 1188



# TOYOTA

## ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd		
			Document No.		6 Battery Road		
			0		#38-04		
			Document Date		Singapore 049909		
			20/01/2022		Work: 65703925		
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZVW50R	AHXEBW Q2	13/01/2017	SLK3541K	0	12900	75/DS/SLK3541K
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKB3FU603543723		2ZRR990124	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
10	B	BP-RES2 TO SPRAY PAINT OH REAR ACCIDENT AFFECTED AREAS. <i>6 x 590</i>				<i>3540</i>	5900.00
11	1	U52159-47913 COVER, RR BUMPER / <i>BR</i>	1.00	469.50			469.50
12	2	U52575-47040 RETAINER, RR BUMPER / <i>BR</i>	1.00	124.90			124.90
13	3	U52576-47040 RETAINER, RR BUMPER / <i>X</i>	1.00	123.60			123.60
14	4	U52591-47050 SEAL, RR BUMPER / <i>MIS</i>	1.00	93.50			93.50
15	5	U52592-47040 SEAL, RR BUMPER / <i>X</i>	1.00	93.50			93.50
16	6	U52023-47030 REINFORCEMENT / <i>X</i>	1.00	353.10			353.10
17	7	U52453-47010 GUARD, RR BUMPER, / <i>CUT</i>	1.00	611.30			611.30
18	8	U52565-47900 FILLER, RR BUMPER / <i>MIS</i>	1.00	131.10			131.10
19	9	U52566-47900 FILLER, RR BUMPER / <i>X</i>	1.00	131.10			131.10
20	0	U58307-47090 PANEL SUB-ASSY, BODY / <i>DD (end M)</i>	1.00	689.70			689.70
21	1	U58311-47130 PAN, RR FLOOR / <i>X R</i>	1.00	618.90			618.90
22	2	U58398-47050 COVER, FLOOR UNDER, / <i>CRY</i>	1.00	185.60			185.60
23	3	U90467-17026 A0 CLIP / <i>MIS</i>	1.00	3.50			3.50
24	4	U58399-47030 COVER, FLOOR UNDER, / <i>?</i>	1.00	256.50			256.50
25	5	U61601-47150 PANEL SUB-ASSY, / <i>DD (Front Rn RH)</i>	1.00	925.90			925.90
26	6	U61607-47902 PANEL S/A, QTR W/H, / <i>?</i>	1.00	576.20			576.20
27	7	U65637-47060 LINER, RR WHEEL / <i>CUT</i>	1.00	148.00			148.00
28	8	U61631-47070 PANEL, QUARTER WHEEL / <i>?</i>	1.00	314.20			314.20
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		Less		
			Labour				
			Sublet				
			Lubrication/Fluid				
			Others		Amount Due		

Customer Copy



# Borneo Motors



# TOYOTA

Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No 2 PANDAN CRESCENT  
SINGAPORE 128462, Tel no: 6631 1188

## ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd
	Document No. 0	6 Battery Road #38-04 Singapore 049909
	Document Date 20/01/2022	Work: 65703925

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZVV50R	AHXEBW Q2	13/01/2017	SLK3541K	0	12900	75/DS/SLK3541K
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDKB3FU603543723	2ZRR990124	60	Ng Mei Yen	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
29	9	U61601-47150 PANEL SUB-ASSY, ?	1.00	925.90		925.90
30	0	T08826-08115 PANEL BONDING AD ?	1.00	267.20		267.20
31	1	U62940-47010 DUCT ASSY, QUARTER / CR4	1.00	70.90		70.90
32	2	U58745-47030 PROTECTOR, QUARTER / MR	1.00	24.40		24.40
33	3	U62505-47011 COVER SUB-ASSY, A	1.00	219.50		219.50
34	4	U81551-47283 LENS & BODY, RR / BR	1.00	479.30		479.30
35	5	U81497-47020 COVER, RR / CR	1.00	68.50		68.50
36	6	U81581-47011 LENS & BODY, RR / BR	1.00	532.00		532.00
37	7	U67003-47211 PANEL SUB-ASSY, RR / OD	1.00	1371.80		1371.80
38	8	U75763-47010 MOULDING, RR DOOR / ?	1.00	97.90		97.90
39	9	U75765-47010 MOULDING, RR DOOR / ?	1.00	41.00		41.00
40	0	U75403-48010 EMBLEM SUB-ASSY, / MR	1.00	76.00		76.00
41	1	U75441-47130 PLATE, LUGGAGE COMPT / MR	1.00	58.00		58.00
42	2	U75442-47130 PLATE, LUGGAGE COMPT / MR	1.00	58.00		58.00
43	3	U42611-47450 WHEEL, DISC / CR	1.00	1995.20		1995.20
44	4	YTDG19-565R1 5 GRAB DUNLOP 195-65R15 / TM	1.00	88.00		88.00
45	5	U75977-47080 STRIPE, RR DOOR, / MR	1.00	23.20		23.20
46	6	U75987-47060 STRIPE, RR DOOR, / MR	1.00	37.00		37.00
47	7	U75979-47070 STRIPE, RR DOOR, / MR	1.00	16.30		16.30

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	28,382.60	
<div>WV to Consultant hence not the Repairer of the following:</div> <ul style="list-style-type: none"><li>• To resurvey before/after spray painting</li><li>• To display damaged part(s) during resurvey</li><li>• Parts prices are subject to confirmation</li><li>• Third party survey is on a "Without Prejudice" basis</li><li>• No illegal modification(s) is allowed</li><li>• Supplementary item(s) must be returned and is subject to final approval from Insurance Company</li></ul>	Please acknowledge receipt of vehicle	Parts	12,300.20	GST 7.00%	1,986.78
		Labour	15,902.40		
		Sublet	180.00	Less	0.00
		Lubrication/Fluid	0.00		
		Others	0.00		
				Amount Due	30,369.38

Acknowledged by Repairer

Signature:

Date:

Customer Copy



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	19/01/2022 11:03 (SGT)
Date of Accident	18/01/2022 17:45 (SGT)
Exact Location of Accident	Bukit Batok Cres, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SLK3541K

#### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	GRAB RENTALS PTE LTD
Company Reg No	2XXXXX200G
Email Address	gr.sg.accident@grab.com
Mobile Phone No	(Phone) +65-91501141
Alternative Phone No	(Office) +65-66550005

#### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1798

#### INSURANCE COMPANY

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	G 400001194 MCX
Cover Note Number	-

#### DRIVER

Name of Driver	NG TECK KHIM
NRIC No	SXXXX673Z

Date Of Birth  
 Occupation  
 Date Of Driving Pass  
 Driving experience  
 Gender  
 Mobile Number  
 Alt. Phone Number  
 Email Address  
 Address  
 Address complement  
 Postcode  
 Is the driver the policyholder?  
 If No, Relationship of the Driver with the Insured  
 Does Driver Own Other Vehicles?  
 Vehicle Registration Number of Other Vehicle Owned by Driver  
 Insurance Company of Other Vehicle Owned by Driver

17/04/1975  
 Outdoor  
 03/01/1996  
 26 YEARS  
 Male  
 (Phone) +65-91501141  
 -  
 gr.sg.accident@grab.com  
 BLK 393 BUKIT BATOK WEST AVENUE 5 #07-460  
 -  
 650393  
 No  
 Hirer  
 No

Supplement  
 Company Name  
 1 Damage  
 of property damaged in a  
 Passenger (Including Driver)  
 INJURED 1  
 Name of injured person  
 Gender  
 Phone No  
 Address

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident  
 Weather Conditions  
 Road Surface

Collision - Head to Rear  
 Clear  
 Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?  
 Number of vehicles involved in the accident  
 Was anybody injured in the Accident?  
 Was any injured conveyed to hospital by ambulance?  
 Was any other vehicle or property damaged?  
 Number of Passengers (Including Driver)  
 Has the driver been approached by unknown person(s)  
 soliciting/offering accident claims assistance?

No  
 2  
 Yes  
 No  
 Yes  
 1  
 No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?  
 Was notice of intended Prosecution given?  
 If yes, against whom?

No  
 No  
 -

#### CIRCUMSTANCES OF ACCIDENT

ON THE 18/01/2022 AT ABOUT 1745 HOURS, I WAS DRIVING VEHICLE A (SLK3541K) IN STATIONARY POSITION WAITING TO FETCH A PASSENGER WHEN SUDDENLY VEHICLE B (GBL524T) REAR ENDED ME ON THE REAR RIGHT CORNER PORTION OF MY CAR. I SUFFERED DULL PAIN TO MY NECK, SHOULDER AND LOWER BACK DUE TO THE HARD IMPACT.

#### ATTACHMENT(S)

Are accident photos available for attachment?  
 Was there any video captured by Car Camera?  
 Was there any audio recorded?

Yes  
 No  
 No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number  
 Vehicle Manufacturer  
 Vehicle Model  
 Vehicle Variant  
 Vehicle Colour  
 Vehicle Category  
 Name of Driver  
 Contact Number

GBL524T  
 -  
 -  
 -  
 -  
 Commercial vehicle  
 -  
 (Phone) +65-97157769

S #07-460

plement	-
Company Name	-
Of Damage	-
ills of property damaged in accident	-
Of Passenger (Including Driver)	1

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	NG TECK KHIM
Gender	Male
Phone No	(Phone) +65-91501141
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	PAIN ON NECK, SHOULDER AND LOWER BACK
Injured person in which vehicle?	SLK3541K
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan





## Describe Circumstances of the Accident


ON THE 18/01/2022 AT ABOUT 1745 HOURS, I WAS DRIVING VEHICLE A (SLK3541K) IN STATIONARY POSITION WAITING TO FETCH A PASSENGER WHEN SUDDENLY VEHICLE B (GBL524T) REAR ENDED ME ON THE REAR RIGHT CORNER PORTION OF MY CAR. I SUFFERED DULL PAIN TO MY NECK, SHOULDER AND LOWER BACK DUE TO THE HARD IMPACT.

## Declaration

We declare the foregoing particulars are true in every respect.

\_\_\_\_\_  
Policyholder's Signature / Date & Time

\_\_\_\_\_  
Driver's Signature (If driver is not the policyholder) / Date & Time

  
18/01/22 1820

\_\_\_\_\_  
Witnessed by Reporting Centre Personnel

