

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |                                                                                                                                     |                                       |                 |                     |  |
|-------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------|-----------------|---------------------|--|
|                                                                   | CHINA TAIPING IN                                                                                                                    | ISURANCE (S) PTE LTD                  | Ref:            | CS/CTI22000763/Ety3 |  |
|                                                                   | 3 ANSON ROAD #<br>SPRINGLEAF TOV                                                                                                    | 16-00<br>VERSINGAPORE 079909          | Date:           | 21/01/2022          |  |
|                                                                   |                                                                                                                                     |                                       | Code:           | CTI                 |  |
| 1.                                                                | . Policy Particulars :- THIRD PARTY CLAIM                                                                                           |                                       |                 |                     |  |
|                                                                   | Insured Veh.                                                                                                                        | GBL 524T                              | Veh. Inspected  | SLK 3541K           |  |
|                                                                   | Policy No.                                                                                                                          | DMCVSNW00023762100                    | Coverage (\$)   | 0.00                |  |
|                                                                   | Claim No.                                                                                                                           | SNM22D200519/C02/LEEPG                | Excess (\$)     | 0.00                |  |
|                                                                   | Assign From                                                                                                                         | CECILIA LEE PENG GEOK                 | Assign Date     | 21/01/2022          |  |
| 2. Vehicle Particulars & Condition                                |                                                                                                                                     |                                       |                 |                     |  |
|                                                                   | Make & Model                                                                                                                        |                                       | c.c             | 0                   |  |
|                                                                   | Engine No.                                                                                                                          | HIDDEN                                | Year of Reg.    |                     |  |
|                                                                   | Chassis No.                                                                                                                         |                                       | Colour          |                     |  |
|                                                                   | Odometer                                                                                                                            | -                                     | Steering        |                     |  |
|                                                                   | Brakes                                                                                                                              |                                       | Modification    |                     |  |
|                                                                   | General                                                                                                                             |                                       |                 |                     |  |
| 3. Conditions of Tyres                                            |                                                                                                                                     |                                       |                 |                     |  |
|                                                                   |                                                                                                                                     | Size                                  | Make            | Balance             |  |
|                                                                   | R/H Front Tyre                                                                                                                      |                                       |                 | mm                  |  |
|                                                                   | L/H Front Tyre                                                                                                                      |                                       |                 | mm                  |  |
|                                                                   | R/H Rear Tyre                                                                                                                       |                                       |                 | mm                  |  |
|                                                                   | L/H Rear Tyre                                                                                                                       |                                       |                 | mm                  |  |
| 4.                                                                |                                                                                                                                     | Description of Damages                |                 |                     |  |
|                                                                   |                                                                                                                                     |                                       |                 |                     |  |
| 5.                                                                |                                                                                                                                     | General Information                   |                 |                     |  |
|                                                                   | Accident Date                                                                                                                       | 18/01/2022                            | Inspection Date | 21/01/2022          |  |
|                                                                   | Survey held at                                                                                                                      | BORNEO MOTORS (S) PTE LTI             | )               |                     |  |
|                                                                   |                                                                                                                                     | 2 PANDAN CRESCENT<br>SINGAPORE 128462 |                 |                     |  |
| 5a.                                                               | Remarks                                                                                                                             |                                       |                 |                     |  |
|                                                                   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                       |                 |                     |  |