

Your Ref: RT/JY/325/2021/ml

Date: 04th Mar 2022

Our Ref: CS1/LAW22000767/Uvf3e2

M/s Tan Chin Hoe & Co

24 Raffles Place

#24-01 Clifford Centre

Singapore 048621

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLM 8130U
INSURED VEHICLE: SLT 6410M
ACCIDENT DATE: 13/08/2020**

We thank you for your instruction on 21/01/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLM 8130U from M/s RW Automotive Appraisers Services.
- b) Survey report by Formteam Adjusters Pte Ltd with colour photographs.
- c) Singapore Accident Statement of Vehicles SLM 8130U.
- d) Police Report of Vehicles SLM 8130U and SLT 6410M
- e) Colour damaged vehicle photographs of SLM 8130U.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLM 8130U
Make & Model	: KIA Cerato K3 1.6 Sunroof (A)
Chassis Number	: KNAFZ411MH5708126
Year of Registration	: 2017
Engine Capacity	: 1591 cc

- 2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.