



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22000794/Aqf3e2	Date: 10/05/2022
			Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJU 4031E	Veh. Inspected	SMW 5027R
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10013510/JM	Excess (\$)	0.00
	Assign From	IVY RATILLA	Assign Date	24/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALTIS	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	MR2BE3BE300010180	Colour	WHITE
	Odometer	85535 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	MICHELIN	6 mm
	L/H Front Tyre	225/45 R17	MICHELIN	6 mm
	R/H Rear Tyre	225/45 R17	MICHELIN	6 mm
	L/H Rear Tyre	225/45 R17	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	19/01/2022	Inspection Date	20/01/2022
	Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	