

SEC. REC. BY:

Thavan

11/12/18 ching

# ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Vol.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Rebate: 22542

Date/Time, File Pass to?

☐

: Procl. Report

U

☐

: Final Report

Date/Time, File Return to?

3

Report Form:

Long Form / LB: 1

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Wheel end

Veh No:

SLC 26354

Yr Regn:

11/12/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) / Prime Mover /

Truck / Trailer or

Make:

Hyundai Ionix

C.C 1580

Colour

A/C: Insured / Std / NI / NA

Sp. Reading

442918

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MMHC851CVHU/22138

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SIRIm / STD AIRIm or

Tyre Size:

F:

195/65R13

R:

195/65R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

16/1/22

D.O.I.

18/1/22 1630

Survey held at

CDCOE

Des. of Damages: Frt / (Rear) / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Survey Fee:

Transportation:

S + RS. \$

Pinus

Oliver

Total

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: 821R

Owner ID:

### Vehicle Details

Vehicle No.: SHC2635U

Vehicle to be Exported: No

Intended Deregistration Date: 21 Jan 2022

Vehicle Make: HYUNDAI

Vehicle Model: AE IONIQ HEV 1.6 DCT

Primary Colour: Blue

Manufacturing Year: 2018

Engine No.: G4LEJU133551

Chassis No.: KMHCH851CVKU122138

Maximum Power Output: 103.6 kW (138 bhp)

Open Market Value: \$25,070.00

Original Registration Date: 11 Dec 2018

First Registration Date: 11 Dec 2018

Transfer Count: 0

Actual ARF Paid: \$12,098.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 10 Dec 2026

PARF Rebate Amount: \$9,073.00

### Intended COE Rebate Details

COE Expiry Date: 10 Dec 2026

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$22,057.00

COE Rebate Amount: \$13,469.00

Total Rebate Amount: \$22,542.00

**Message**  
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 21 Jan 2022

OK

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd

205 Darden Road Singapore 579701  
Mobile + 65 5383 6280 Facsimile + 65 8280 9755

Workshops  
205 Darden Road Singapore 579701  
Seng Guan Drive Singapore 509969  
301-303 Miao Drive Singapore 575717

Date/Time: 17.01.2022 15:42 Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 4163901

JC NO305501862

CUSTOMER

NAME COMFORT TRANSPORTATION PTE LTD  
CUSTOMER NO 7010045  
ADDRESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
L (R) 65508755 (O)  
(P)


COUNT CARD NO

REGN NO SHC2635U	MILEAGE
MAKE HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G2)	DATE/TIME IN 17.01.2022 14:20
YR OF MANU 11.12.2018	TARGET DATE
CHASSIS CODE KMHC851CVKU122138	COMPLETION DATE/TIME:

Accident Date: 16.01.2022  
NATURE: 3P 16.01.2022

JOB DESCRIPTION

:/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Vehicle Identification Slip

Exit Pass

No.: SHC2635U YY

Vehicle No.: SHC2635U

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SHC2635U

Make : HYUNDAI

Model : IONIQ(G2)

Date: 17/01/2022

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
1	REAR BUMPER REINFORCEMENT BRACKET LH RH		\$138.10	\$276.20
1	REAR BUMPER LOWER CTR MOULDING			\$155.00
1	REAR BUMPER TOWING COVER			\$98.80
1	REAR BUMPER FOG LAMP			\$201.50
1	LICENCE LAMP			\$85.30
1	ANTHENA SMARTKEY			\$40.50
1	REAR PANEL			\$532.00
1	REAR PANEL GARNISH			\$346.80
1	REAR BUMPER UNDER CENTRE COVER			\$225.00
	<b>SUB TOTAL</b>			\$3,288.55
	<b>LESS 20%</b>			\$657.71
	<b>DISCOUNTED TOTAL</b>			<b>\$2,630.84</b>
1	REAR BUMPER RUBBER MAT			\$50.00
1	REAR NUMBER PLATE WITH TRIM COVER			\$55.00
1	REAR BUMPER REVERSE SENSOR			\$180.00
				<b>\$285.00</b>
	<b>Labour Charge</b>			
	PANEL BEATING			\$1,100.00
	SPRAY PAINTING CHARGE			\$500.00
	CHK ALL LIGHTING			\$50.00
	REMOVE/REFIX REVERSE SENSOR			\$80.00
	<b>TOTAL LABOUR</b>			<b>\$1,730.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$4,645.84</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Thuan @ Lhhayto - low

82235769

18/1/22 1630

C/S after repair photo

2 days wp

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission 17/01/2022 18:31 (SGT)  
Date of Accident 16/01/2022 13:20 (SGT)  
Exact Location of Accident CTE, Singapore  
Additional Location Information AYE  
Country/State of Loss Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SHC2635U  
INSURED/POLICYHOLDER  
Is company? Yes  
Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD  
Company Reg No 1XXXXX821R  
Email Address fleetsafety@cdgtaxi.com.sg  
Mobile Phone No (Phone) +65-89442558  
Alternative Phone No (Office) +65-65508768

### VEHICLE PARTICULARS

Manufacturer Hyundai  
Model Ae ioniq  
Variant -  
Exact purpose for which vehicle was being used at time of accident Private hire  
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party  
Vehicle Category Taxi  
Transmission Auto  
CC 1580

### INSURANCE COMPANY

Name of Insurance Company AXA Insurance Pte Ltd  
Type of Coverage ThirdPartyFireTheft  
Fleet Policy Yes  
Policy Number VFX/P2419138  
Cover Note Number -

### DRIVER

Name of Driver TAN KANG YANG(CHEN JIANG YANG)  
NRIC No SXXXX216J

Date Of Birth	10/06/1982
Occupation	Outdoor
Date Of Driving Pass	21/10/2002
Driving experience	19 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-89442558
Alt. Phone Number	-
Email Address	fleetsafety@cdgtaxi.com.sg
Address	668A EDGEFIELD PLAINS #03-706
Address complement	-
Postcode	821668
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### PASSENGER 1

Name	UNKNOWN
Gender	Male

#### PASSENGER 2

Name	UNKNOWN
Gender	Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Punggol Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18006049999
Alt. Police Station Phone No	(Fax) +65-64468015
Police Station Address	Blk 21A Tebing Lane Singapore 828837
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO POLICE REPORT No.T/20220117/2049

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE IS NOT SUITABLE
Was there any audio recorded?	No

# DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ5219C
Vehicle Manufacturer	Toyota
Vehicle Model	Hiace
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	MUHAMMAD NIFAIL FIRDAUS BIN ALI
NRIC No	SXXXX354C
Contact Number	(Phone) +65-87508020
Address	-
Address complement	714 BEDOK RESERVOIR ROAD #03-3024
Postcode	470714
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2







Describe Circumstances of the Accident

PLEASE REFER TO POLICE REPORT T/20220117/2049

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &  
Time

Driver's Signature (If driver is not the policyholder) / Date  
& Time

Witnessed by Reporting Centre  
Personnel



17/01/22

1430





SINGAPORE  
POLICE FORCE



T/20220117/2049

1 of 3

Police Station Of Origin:  
Punggol N.P.C  
151 Punggol Central SINGAPORE 828727  
Tel No: 1800-6049999

Report No. T/20220117/2049

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/01/2022 13:30	Vide Report No.:	Station Diary No.: 20
--	------------------	--------------------------

<b>Informant's Particulars</b>		
Name of Informant: TAN KANG YANG		Address: APT BLK 668A EDGEFIELD PLAINS #03-706 SINGAPORE 821668
ID Type / ID No.: NRIC NO / S8218216J		Contact No.: Home/Office: Mobile: 97578216
Nationality: SINGAPORE CITIZEN		Email:
Sex: Male	Age: 39	Date of Birth: 10/06/1982
Race: Chinese		Type of Informant: Driver
Occupation: Taxi driver		Language: Institution / School Name:
Driving Licence Information: Class: 2B,2A,2,3		Date of Expiry:

<b>General Information of the Accident</b>			
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 16/01/2022 13:20
Type of Location: Expressway			
Location: CENTRAL EXPRESSWAY			
Weather: Clear		Road Surface: Dry	Road Speed Limit:
Traffic Flow:		Traffic Control: Not Controlled	Traffic Volume: Light
Type of Collision: Moving vehicle to stationary			Anyone conveyed by ambulance: No

<b>Details of Vehicle Involved</b>					
Vehicle No	Type	Make	Model	Color	Condition
GBJ5219C	Van				Slightly Damaged
SHC2835U	Car				Slightly Damaged
No of Passenger					
1					
2					

<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	
No of Pedestrians Injured: NIL	
Use of Pedestrian Crossing: NA	



**SINGAPORE  
POLICE FORCE**



T/20220117/2049

Police Station Of Origin:  
Punggol N.P.C  
151 Punggol Central SINGAPORE 828727  
Tel No: 1800-6049999

2 of 3

Report No. T/20220117/2049

## CONTINUATION OF REPORT

Driver			
Name	MUHAMMAD NIFAIL FIRDAUS BIN ALI	ID No.	S9002354C
Related Vehicle	GBJ5219C (Van)	Contact No.	87508020
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TAN KANG YANG	ID No.	S8218216J
Related Vehicle	SHC2635U (Car)	Contact No.	97578216
Hospital/Clinic	A LIFE CLINIC PTE LTD	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	17/01/2022	Date Discharge	17/01/2022
No. of Days granted Medical Leave	07	Degree of Injury	Slight

**Brief Details.**

On 16/01/2022 at around 1320 hours, I was driving my vehicle SHC2635U on the extreme left lane of a 6-lane road along CTE towards AYE near to slip road toward towards PIE (Changi).

While approaching the slip road, I noticed that the vehicles in front of me was piling up and as such, we were driving at a very slow speed. At one point of time, the vehicles even became stationary.

Shortly after, I felt an impact coming from the rear of my vehicle GBJ5219C. Subsequently, we then came out of our vehicles. We took some photos before exchanging particulars and proceeded on our way.

This is the first time such incident happens, and I have an inbuilt camera in my vehicle. I am not sure if there are any CCTVs at the said location.



**SINGAPORE  
POLICE FORCE**



T/20220117/2049

3 of 3

Police Station Of Origin:  
Punggol N.P.C  
151 Punggol Central SINGAPORE 828727  
Tel No: 1800-6049999

Report No. T/20220117/2049

## CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report  
F /

Sr Staff Sgt CHIANG JING XUAN

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / AEIT /  
SIANG YI TING, STEPHANIE  
Contact No. 65478414

Signature Of Informant:

Date/Time:  
17/01/2022 13:30

Classification Of Case:

Authentication Stamp  
NP168



SINGAPORE  
POLICE FORCE

SN158

SIGNATURE