

|   |   |          |   |   |   |   |        |   |   |             |
|---|---|----------|---|---|---|---|--------|---|---|-------------|
| ⏪ | < | 1 of 2 ? | > | ⏩ | ↺ | ↻ | 100% ▼ | 🖨 | 📄 | Find   Next |
|---|---|----------|---|---|---|---|--------|---|---|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                         |                                                                                                    |                         |            |  |
|-------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------|-------------------------|------------|--|
| SOMPO INSURANCE SINGAPORE PL                                                                                                              |                                                                                                    | Ref: CS/SMO22000802/Kf3 |            |  |
| 50 RAFFLES PLACE #03-03                                                                                                                   |                                                                                                    | Date: 24/01/2022        |            |  |
| SINGAPORE LAND TOWERS SINGAPORE 048623                                                                                                    |                                                                                                    | Code: SMO               |            |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                                                    |                         |            |  |
| Insured Veh.                                                                                                                              | YP 5498J                                                                                           | Veh. Inspected          | SLP 6335T  |  |
| Policy No.                                                                                                                                |                                                                                                    | Coverage (\$)           | 0.00       |  |
| Claim No.                                                                                                                                 | CMTD2200305/THE                                                                                    | Excess (\$)             | 0.00       |  |
| Assign From                                                                                                                               | GRACE TEO                                                                                          | Assign Date             | 24/01/2022 |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                                                    |                         |            |  |
| Make & Model                                                                                                                              |                                                                                                    | c.c                     | 0          |  |
| Engine No.                                                                                                                                | HIDDEN                                                                                             | Year of Reg.            |            |  |
| Chassis No.                                                                                                                               |                                                                                                    | Colour                  |            |  |
| Odometer                                                                                                                                  | -                                                                                                  | Steering                |            |  |
| Brakes                                                                                                                                    |                                                                                                    | Modification            |            |  |
| General                                                                                                                                   |                                                                                                    |                         |            |  |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                                                    |                         |            |  |
|                                                                                                                                           | Size                                                                                               | Make                    | Balance    |  |
| R/H Front Tyre                                                                                                                            |                                                                                                    |                         | mm         |  |
| L/H Front Tyre                                                                                                                            |                                                                                                    |                         | mm         |  |
| R/H Rear Tyre                                                                                                                             |                                                                                                    |                         | mm         |  |
| L/H Rear Tyre                                                                                                                             |                                                                                                    |                         | mm         |  |
| <b>4. Description of Damages</b>                                                                                                          |                                                                                                    |                         |            |  |
|                                                                                                                                           |                                                                                                    |                         |            |  |
| <b>5. General Information</b>                                                                                                             |                                                                                                    |                         |            |  |
| Accident Date                                                                                                                             | 20/01/2022                                                                                         | Inspection Date         | 25/01/2022 |  |
| Survey held at                                                                                                                            | SUPREME AUTO SERVICE PTE LTD<br>176 SIN MING DRIVE<br>#02-01 SIN MING AUTOCARE<br>SINGAPORE 575721 |                         |            |  |
| <b>5a. Remarks</b>                                                                                                                        |                                                                                                    |                         |            |  |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                    |                         |            |  |