



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: HO WINNIE			Ref: CS/ASM22000818/Avy3e2 Date: 01/04/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 4416S	Veh. Inspected	SCK 101Z
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S2M03RJZ	Excess (\$)	0.00
	Assign From	HO WINNIE	Assign Date	24/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 640I GRAN COUPE	c.c	2979
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WBA6A02040DZ11913	Colour	BRONZE
	Odometer	45805 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/40 R19	KAPSEN	6 mm
	L/H Front Tyre	245/40 R19	KAPSEN	6 mm
	R/H Rear Tyre	245/40 R19	KAPSEN	6 mm
	L/H Rear Tyre	245/40 R19	KAPSEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	14/01/2022	Inspection Date	24/01/2022
	Survey held at	2020 SPRAY PAINTING PTE LTD 53 UBI AVENUE 1, #05-15, PAYA UBI INDUSTRIAL PARK, SINGAPORE 408934		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	