



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:WINNIE			Ref: CC4/ASM22000821/Apa3q2 Date: 13/12/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SLH 652J	Veh. Inspected	SLK 4528T
	Policy No.	GA568887	Coverage (\$)	0.00
	Claim No.	S2M03RQJ	Excess (\$)	0.00
	Assign From		Assign Date	24/01/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HONDA VEZEL HYBRID	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	RU31216032	Colour	BRONZE
	Odometer	154355 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	CRUCERO	6 mm
	L/H Front Tyre	215/60 R16	CRUCERO	6 mm
	R/H Rear Tyre	215/60 R16	CRUCERO	6 mm
	L/H Rear Tyre	215/60 R16	CRUCERO	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	22/01/2022	Inspection Date	24/01/2022
	Survey held at	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	