

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Rakeswaran Anand
CLAIM DEPARTMENT
DID : 66547506
FAX : 66547540

Date : 25/01/2022
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department


FAX :

Owner : ETHOZ Group Ltd
SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTHCVE000061 Accident Date : 27/12/2021
Vehicle No : YP -8565-D Make & Model : HINO FD9JPNA-HAS 5.1 Y (M) EURO 6

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
List Item			
1	LH RAILING SIDE PANEL <i>x Repair</i>	RESTORE	
	Sub Total	0.00	
	Discount % On Parts	(0.00)	
Special Nett Item			
1	LH REAR SLIDING DOOR 1ST PANEL <i>Cut (photo after dismantle)</i>	800.00	<i>✓</i>
1	LH REAR SLIDING DOOR ADVERTISEMENT STICKER <i>Cut</i>	1,800.00	<i>✓ 400</i>
	Sub Total	2600.00	
Labour & Misc			
	LABOUR AND SPRAY PAINTING	300.00	<i>1500 ✓</i>
		1500	



Date : 25/01/2022
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTHCVE000061 Accident Date : 27/12/2021
Vehicle No : YP -8565-D Make & Model : HINO FD9JPNA-HAS 5.1 Y (M) EURO 6

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	300.00	

3 Days.

P/P.

25/1/22

Gmo Qiao - 82880282.

After repair photos.

Remarks:

2,900.00

SUB TOTAL

GST 7.0 % 203.00

TOTAL 3,103.00

Surveyor's name: _____

Principal's name: ETHOZ Group Ltd

Survey Date & Time: _____