



Claim

# Service Request Details

S2M03RV2

Reference
CS3/ASM22000906/Gqy3

Vendor Name

24 January 2022

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss Incident Only

Report Date

25 Jan 2022 1:31:01 PM

Request Date

25 January 2022

Due Date

3 February 2022

Services

Pre-Repair Survey

## Actions

**Next Step** 

Agree to perform service

**Decline Work** 



| Vehicle | e Inforn | nation |
|---------|----------|--------|
|         |          |        |

Incident Vehicle Registration #

SLK617X

Make

**TPVD** 

Model

TOYOTA

### Service Address

, , ,

# Primary Contact/Insured

NG YONG THONG 17 SIN MING WALK, #08-08, 573913, Singapore 90122753 MAG2CAM@GMAIL.COM

#### Claim Handler

ANG Yvonne

yvonne.ang@axa.com.sg

Additional Instructions

Messages Invoices History **Documents** Assessment Metrics Notes

1/26/22, 10:27 AM VendorEngage



Document SubType

~

**♣** Upload Documents

### **Already Attached**

NAME REPLY FROM TP.msg.msg

TYPE Letters and Correspondence

SUBTYPE Others

AUTHOR KUMAR Shailendra

DATE UPLOADED 25 January 2022

NAME PRI TP MAIL FROM SOLICIOTR.msg.msg

TYPE Legal

SUBTYPE Others

AUTHOR KUMAR Shailendra

DATE UPLOADED 25 January 2022

NAME TP GIA.pdf.pdf

TYPE Reports & Statement

SUBTYPE GIA Report

AUTHOR KUMAR Shailendra

DATE UPLOADED 25 January 2022