



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI22000921/Knf3e2 Date: 10/08/2022	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SMM 1814P	Veh. Inspected	GBF 9723H
Policy No.		Coverage (\$)	0.00
Claim No.	C10013535 /KY	Excess (\$)	0.00
Assign From	FRAULEINE KHOO	Assign Date	26/01/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	NISSAN NV200 (M)	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	VSKYBAM20Z0139686	Colour	RED
Odometer	213691 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	175/70 R14	ROADSTONE	6 mm
L/H Front Tyre	175/70 R14	ROADSTONE	6 mm
R/H Rear Tyre	175/70 R14	GOODYEAR	2 mm
L/H Rear Tyre	175/70 R14	GOODYEAR	2 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	22/01/2022	Inspection Date	09/02/2022
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD (HQ) 176 SIN MING DRIVE #01-06/07/13, SIN MING AUTOCARE SINGAPORE 575721		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	