

ASS. REC. BY:

REF:

C72 / 22 000 924 / Kt

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLK 5432D

Yr Regn:

01, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy ALTAS

c.c

1598

Colour

M-Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

101473

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NR053REM104560101

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD / Rlm or

Tyre Size:

F:

215/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

6

mm

L/Bal.

5

mm

L/Bal.

6

mm

D.O.A.

20/1/22

D.O.I.

28/1/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. \$

F.P.M.S

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEY COPY

M/S : FOO CHI-HUI ESME
 524 SERANGOON NORTH AVE 4
 #11-56
 SINGAPORE 550524

Estimate No: MC1902435
 Date: 24 Jan 2022
 Policy No: MT/00881560/01
 Veh Reg No: SLK5432D
 Make/Model: TOYOTA COROLLA
 ALTIS 1.6 CVT

ATTN:

Your Ref No: SLK5432D
 Claim Type: Third Party → China
 Accident Date: 20/01/2022
 TP Veh Reg No: SJN3431C

4K
 2K
 230pm

Not with hold
 Recovery B4 paint
 3 days

Estimate Repair Cost to Vehicle No :SLK5432D

| Description | Quantity | List Price | Amount |
|--|----------|------------|----------|
| | | S\$ | S\$ |
| SPARE PARTS | | | |
| 1 FRONT BONNET | 1 PC | 135.00 | X |
| 2 HEADLAMP LH & RH | 2 PC | 5,999.60 | 4 |
| 3 HEADLAMP CHROME MLDG LH & RH | 2 PC | 289.20 | X |
| 4 RADIATOR GRILLE BASE ASSY | 1 PC | 643.00 | — |
| 5 RADIATOR GRILLE TOP COVER | 1 PC | 80.70 | X |
| 6 RADIATOR GRILLE TOP COVER CLIPS | 6 PC | 27.00 | X |
| 7 FRONT BUMPER | 1 PC | 531.10 | — |
| 8 FRONT BUMPER LOWER GRILLE | 1 PC | 170.10 | X |
| 9 FRONT BUMPER SIDE RETAINER LH & RH | 2 PC | 171.00 | 4 |
| 10 FRONT BUMPER CLIPS | 3 PC | 13.50 | — |
| 11 FRONT BUMPER SPONGE | 1 PC | 90.10 | X |
| 12 FRONT BUMPER REINFORCEMENT | 1 PC | 399.50 | X |
| 13 FRONT FENDER DUAL VVT-I LOGO | 1 PC | 47.60 | X |
| 14 FRONT FENDER COWLING LH | 1 PC | 227.00 | X |
| 15 FRONT FENDER COWLING CLIPS | 8 PC | 23.20 | X |
| 16 BRACE PANEL | 1 PC | 149.40 | X |
| 17 AIR CON CONDENSER | 1 PC | 1,801.70 | X |
| 18 RADIATOR SUPPORT PANEL ASSY | 1 PC | 1,136.30 | X |
| | | 11,935.00 | |
| | | 2,983.75 | 8,951.25 |
| Special Nett | | | |
| 19 NUMBER PLATE | 1 PC | 35.00 | — |
| 20 RADIATOR COOLANT | 1 PC | 30.00 | X |
| | | 65.00 | 65.00 |
| LABOUR | | | |
| 21 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING. | 1 PC | 40.00 | 20 |
| 22 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS. | 1 PC | 100.00 | X |
| 23 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS. | 1 PC | 60.00 | X |
| 24 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL. TO KNOCK & REPAIR FRONT BONNET, FRONT FENDER LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME. | 1 PC | 700.00 | 300 |
| 25 TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH. | 1 PC | 700.00 | 400 |

Zila
 Ah Lim Motor Company

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting Less 25%
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|---------------------------------|-----------------------------|
| Date of Submission | 21/01/2022 17:06 (SGT) |
| Date of Accident | 20/01/2022 15:30 (SGT) |
| Exact Location of Accident | Bishan Street 13, Singapore |
| Additional Location Information | - |
| Country/State of Loss | Singapore |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|---|
| Vehicle Registration Number | SLK5432D |
| INSURED/POLICYHOLDER | |
| Is company? | No |
| Name Of Registered Owner | FOO CHI-HUI ESME MRS ESME LOH-FOO CHI HUI |
| NRIC No | SXXXX457A |
| Email Address | mrs_loh2005@yahoo.com.sg |
| Mobile Phone No | (Phone) +65-98722282 |
| Alternative Phone No | +65-98722282 |

VEHICLE PARTICULARS

| | |
|--|---------------------------|
| Manufacturer | Toyota |
| Model | Corolla |
| Variant | COROLLA ALTIS 1.6 CVT |
| Exact purpose for which vehicle was being used at time of accident | Private use |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category | Private car |
| Transmission | Auto |
| CC | 1598 |


INSURANCE COMPANY

| | |
|---------------------------|---|
| Name of Insurance Company | Direct Asia Insurance (Singapore) Pte Ltd |
| Type of Coverage | Comprehensive |
| Fleet Policy | No |
| Policy Number | MT/00881560/01 |
| Cover Note Number | 20/01/2022 - 19/1/2023 |

DRIVER

| | |
|----------------|---|
| Name of Driver | FOO CHI-HUI ESME MRS ESME LOH-FOO CHI HUI |
| NRIC No | SXXXX457A |

SKETCH PLAN #2
Date of accident: 20-1-2022 Time: 3.30 PM Location: Bishan #DB Car park
My Vehicle A: SLE543LD Vehicle B: SJH3431C Vehicle C:
SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I parallel parked behind car B. I turned off my engine. Was about to alight from car when suddenly car B reversed and ramp against me car twice. I harked him and he retracked. Both of us got out of car and he apologised. He gave me his contact number and ic.

☒ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop:

Email address:


& myself:

Email address:


Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Zila
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Ah Lim Motor Company