ASS. REC. BY:	22 600 925/kgf3
1/ - /	SIGNMENT
From: Date:  Estimated Cost:  OD / TP / WS / TP RES / OD RES / EVA / INV / MV  To Inspect Vehicle No:  at Workshop m/s Kien Checy	Veh No: SKX 58357 Yr Regn: 12, 15  Type: M.Car/ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  Truck / Trailer or  Make: Tay ALio c.c 1888
Insured: Policy No. Claims No. MFL 200000018 Sum Insured: Excess: (Client's Record)	Colour M.P. White A/C: Insured / Std / NI / NA  Sp.Reading 55276 T/Radio: Insured / Std / NI / NA  Eng/No:  C/No: URE 161 Coo 9267  Gen. Cond: Good? Fair / Poor / Burnt  Steering: Inorder / Jammed / Leaked / Burnt or  Brake: Inorder / Jammed / Leaked / Burnt or
(Policy Condition)  Remark: The veh had commenced its repair at the time of inspection.  Bal. or Market Value:  IDAC Accident Rport:  Consistent?: Yes or No  GIA / PR Seen:  Consistent?: Yes or No  Est. Repairs:  Adays Res.: Yes or No  Lum Sum:  CA / REV / REP. / 24 HRS  Date / Time  Action / Instruction  Action / Instruction	Modi: Nil / SKIm / STD A/Rim or  Tyre Size: F: // S / GOR 15  R:  BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  TOYO / YOKO or Continue /  Front Rear  R/Bai. 7 mm R/Bai. 3 mm  L/Bai. 7 mm L/Bai. 3 mm  D.O.A. 7 / / 22 D.O.I. 27 / / 202 2  Survey held at  Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  The U/C / Chassis frame / Body Structure affected due to collision.
1129/2 01/1891	Red & 2490.43, (49%)         ys Of Repair:       4         survey No. of Trip:       2         Survey Fee:
Report Format: MERTP Lump Sum / I.B.H: (S 3200	Transportation   S + RS   SI     Interview (\$   Fixed > S     Tech Invs (\$   Others     Weekend (\$   Others

# KIEN CHEONG AUTOMOTIVE

BLK 9 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-26 SINGAPORE 575644

H/P: 8125 9406 FAX: 64550902

The Motor Claims Dept. **India International Insurance** (LKK)

No Whair DATE:

1/Pm & 3200/2 VEHICLE NO:

MAKE/MODEL:

MAKE/MODEL:

Painy ACC DATE:

(4day)

ESTIMATE

26/1/2022 SKX 5835T Toyota Axio 8/1/2022

S/N	PC	List Items	Page.1.	AMOUNT SS
1	1	Front bumper		Bu 515.60
2	1	Front bumper retainer		177.10
3	1	Front RH head lamp		mgcm 582.30 2
4	1	Front RH fender 676		By 731.35 -
5	1	Front RH fender inner shield		5 371.25 <b>★</b>
6	1	Front RH kunkle 497.96		By 561.60 2
7	1	Front RH lower arm		ari 371.25 ~
8	1	Front RH wheel bearing		Nec 230.10 2
9	1	Front RH shock absorber 417.96		By 571.45
10	1	Front RH shock absorber mounting		~ 271.50 ₹
				3,867.90
			Less 25%	966.97
				2,900.93
		Special Items		4
1	1	Front bumper clip		12 30.00 <u> </u>
2	1	Front head lamp clip		~~ 20.00 X
3	1	Front RH fender clip		20.00 X
4	1	Front RH fender inner shield clips		NN 30.00 X
5	1	Front RH tyre rim		Res 280.00 -
6	1	Fromt RH trye		180.00 X
				560.00

	Labour Charges	LKK Auto Consultants hence notify	/
1	Wheel alignment	the Repairer of the following:	150.00
2	To check up electrical wiring	To resurvey before after spray painting To display damage Leart(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis	80.00 Z
3	Anti rust		100.00 20
4	To remove and fix under carriage		450.00 2
5	To respray painting & etc	No illegal modification(s) is allowed	000.00
6	6 Panel beat, remove and replacing ab	ove Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	1,000.00
			2,230.00
		Acknowledged by Repairer	
	Total	al Repair Cost	5,690.93
		Vale:	

(S/DLS: Five Thousand Six hundred ninety and cents Ninety-three only.)



# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation of withouting of material facts may allow insurance companies to report policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident Exact Location of Accident Additional Location Information Country/State of Loss

08/01/2022 16:35 (SGT) 07/01/2022 23:55 (SGT) Singapore SIMEI STREET 1 Singapore

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

SKX5835T

Toyota

Axio

1500

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Company Reg No Email Address Mobile Phone No Alternative Phone No

Yes ASIA CARZ AUTO 5XXXX402E philipkoh888@gmail.com (Phone) +65-98581286 +65-98581286

VEHICLE PARTICULARS

Manufacturer Model Variant Exact purpose for which vehicle was being used at time of Are you claiming under your own insurance policy for repair to your vehicle? Vehicle Category Transmission CC

No - Claiming third party Private hire Auto

INSURANCE COMPANY

Name of Insurance Company Type of Coverage Fleet Policy Policy Number Cover Note Number

NTUC Income Insurance Co-operative Ltd Comprehensive 5115406146-01-000004 DRIVO CLASSIC

DRIVER

Name of Driver NRIC No

PHILIP KOH CHEE BOON SXXXX861D



Date Of Birth 12/12/1977 Occupation Outdoor Date Of Driving Pass 16/09/2002 Driving experience 19 YEARS AND 4 MONTHS Gender Mobile Number (Phone) +65-98581286 Alt. Phone Number **Email Address** philipkoh888@gmail.com Address BLK 234 CHOA CHU KANG CENTRAL Address complement #07-19 680234 No

Postcode 6802
Is the driver the policyholder? No
If No, Relationship of the Driver with the Insured Hirer
Does Driver Own Other Vehicles? No
Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Side Swipe
Weather Conditions Clear
Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

No
Number of vehicles involved in the accident

Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged?

Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No

PASSENGER 1

Name MICHELLE Gender Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Police Station Name

Police Station Phone No

Alt. Police Station Phone No

Police Station Address

Was notice of intended Prosecution given?

Was description of the police?

Yes

Hougang Neighbourhood Police Centre

(Phone) +65-18004890999

(Fax) +65-63128989

60 Hougang Ave 9 Singapore 538775

No

If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?


Was there any video captured by Car Camera?

No
Was there any audio recorded?

No

### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLK5203Z Vehicle Manufacturer -



Vehicle Model	
Vehicle Variant	
Vehicle Colour	-
Vehicle Category	2
Name of Driver	Private car
Contact Number	TENG KOK ENG
Address	(Phone) +65-93208111
The state of the s	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-
140. Of Fasseriger (including Driver)	-

## INJURED PERSONS DETAILS

### INJURED 1

Name of injured person Gender Phone No Address Address Complement Post Code Approximate Age Years Old Injuries Sustained	PHILIP KOH CHEE BOON Male (Phone) +65-98581286 BLK 234 CHOA CHU KANG CENTRAL #07-19 680234
Injured person in which vehicle? Were seat belts worn? Was this injured conveyed to hospital by ambulance?	SKX5835T Yes No

#### SKETCH PLAN

	13/1c 123	1 funtz	(simiz)
·	- CLANTER	3 -	
	TAT		TZE82 KN2 (A)
			B SKX5835T
	11	1	

#### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

May ref	er to the	attuck	pokaru	port no:	7/2100	0108120	33	
			No. 19					AT A PLANT
					A service	and see highly	or other	day in
							-	

### DECLARATION

i/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Tirne:

Driver's Signature (If driver is not the policyholder) Date & Time:

CITY AUTO PTE LTD

Blk 8 Sin Ming Road

#01-58/60/62 Sin Ming Ind Est
Singapore 575643

Tel: 6453 1235 Fax: 6453 7944

(Claims Section)

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

Where the thirt has a

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

M (

ROC

53310402E

Policyholder's Signature Date & Time: Airpon

Driver's Signature (If driver is not the policyholder) Date & Time: CITY AUTO PTE LTD

Blk 8 Sin Ming Road #01-58/60/62 Sin Ming Ind Est Singapore 575643 Tel: 6453 1235 Fax: 6453 7944 (Claims Section)

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:





Police Station Of Origin: Hougang N.P.C

60 Hougang Avenue 9 SINGAPORE 538775

Tel No: 1800-4890999

1 of 3 Report No. T/20220108/2033

#### REPORT OF A TRAFFIC ACCIDENT

08/01/2022 12:02			Vide Report No.:		Station Diary No.:		
Informant'	s Particul	ars					
Name of Informant:			Address:				
PHILIP KOH CHEE BOON			APT BLK 234 CHOA CHU KANG CENTRAL #07-19				
			SINGAPORE 680234				
ID Type / II	D No.:		Contact No.:	Contact No.:			
NRIC NO / S7773861D			Home/Office: Mobile: 98581286		581286		
Nationality			Email:				
SINGAPOR	RE CITIZE	N					
Sex:	Age:	Date of Birth:	Type of Informant:				
Male	44	12/12/1977	Driver				
Race:			Language:	Institution	/ School Name:		
Chinese							
Occupation	1:		Driving Licence Information:				
PRIVATE I		/ER	Class: 3	Date of Ex	piry:		

Type of Accident:	ent: Otners		Date/Time of Accident: 07/01/2022 23:55		Type of Location Car Park
Location: SIMEI STREI	ET 1				
Weather:		Road Surface:		Road	d Speed Limit:
Weather: Clear Traffic Flow: Two Way		Road Surface: Dry Traffic Control: Not Controlled			ic Volume:

Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
SKX5835T	Car	ТОУОТА	COROLLA AXIO 1.5X A	White	Slightly Damaged	1
SLK5203Z		MAZDA	MAZDA3 4- DOOR SEDAN 1.5L SP.6EAT	Blue	Slightly Damaged	0





Police Station Of Origin: Hougang N.P.C 60 Hougang Avenue 9 SINGAPORE 538775 Tel No: 1800-4890999

2 of 3 Report No. T/20220108/2033

#### CONTINUATION OF REPORT

#### **Brief Details.**

On the above mentioned date, time and place, I was driving my vehicle bearing vehicle registration plate number SKX5835T with one passenger onboard. I am a Gojek driver.

I was making a left turn at the T-junction when suddenly a vehicle bearing vehicle registration plate number SLK5203Z reversed and collided into my front right portion with his rear right portion. Both vehicle sustained dents and scratches on the point of contact. We alighted and exchanged contact details. No one was injured at the time of the accident as such the matter was not reported to the Traffic Police. No ambulance attended to us as well.

After the incident, I felt pain on right arm, back of my neck, as well as my right shoulder. I went to consult a doctor and was given 5 days of MC dating from 08/01/2022 to 12/01/2022. I am lodging this report as required.





Police Station Of Origin:

Hougang N.P.C

60 Hougang Avenue 9 SINGAPORE 538775

Tel No: 1800-4890999

CONTINUATION OF REPORT

3 of 3

Report No. T/20220108/2033

## Sketch Plan

NP168

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature of Officer Recording The Report	Signature Of Informant:
Sgt 1 TAY YONG KIAT	1 Dubl
Signature Of Interpreter:	Date/Time:
Not applicable	08/01/2022 12:02
· ·	
**	
Officer In Charge Of Case:	Classification Of Case:
TP / AEIT /	2: 085
SSI TAY CHUN KEEN	
Contact No.: 65476436	
Authentication Stamp	mature

Singapore Paisto Force