

Immediate Advice

To: AXA Insurance Pte Ltd 18/3/2022

Survey Details:

Date of loss	21-Jan-22
Date of appointment	26-Jan-22
Date of survey	13-Jan-21
Location of survey	2020 SPRAY PAINTING PTE LTD

Vehicle Details:

Claim Type:	Third Par	ty Claim]
Vehicle number	SMW 947	76B	
Make and Model	MAZDA 6	S SEDAN 2.0 AT STAND	DARD 14
Date of registration	18/12/20)20]
Excess	-]
Market Value	\$	115,000.00	
Parf Rebate	\$	55,996.00	
Nett Loss	\$	59,004.00	1

Repair details:

Initial Estimate	\$	5,385.50
	τ	-,

Proposed/Revised repair cost:

Parts	\$ 2,732.00
Check items (estimate)	\$ -
Labour	\$ 810.00
Total	\$ 3,542.00
Lump Sum(if applicable)	\$ 2,800.00

Number of days for repair	<u>3</u>



51 UBI AVE 1, #91-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Mandate:

Liability(TP)	%]
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	