



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Mr Pang Keong 141 Bukit Batok Street 11 #08-21 Singapore 650141 Mobile: 96329102		
			Document No.				
			0				
			Document Date				
			27/01/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2015	ZRE171R	GEXGKZ S2	16/11/2015	SKW7590R	0	12983	65DS/SKW7590R
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MR053REH104540422		1ZR535185	60	Francis Cher T S	--/--/----		0.00 --/--/----
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES T/P INS. : T/P VEH. : SG5960J ACC DATE : 24.01.22 BY :				50	100.00
2	S	BP-SUBLET RESET AND REPROGRAMME ECU.					180.00
3	B	BP-LAB2 DRILL HOLE TO INSTALL REVERSE SENSOR.					180.00
4	B	BP-LAB2 STRAIGHTEN TAIL-LAMP PANEL. REPLACE AND REALIGN REAR BUMPER. 1.5 x 700 REPAIR REAR BOOT.				1080	2160.00
5	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED 2 x 540 PORTION OF CAR.				1180	1770.00
6	1	SPZ061-12028 76 GREY METALLIC 2 REVERSE SENSOR	1.00	158.30		101.05	158.30
7	2	S52159-0Z904 COVER,RR BUMPER	1.00	589.50			589.50
8	3	S52023-02190 REINFORCEMENT,RR	1.00	423.90			423.90
9	4	S52576-02140 RETAINER,RR BUMPER L	1.00	116.00			116.00
10	5	S52575-02140 RETAINER,RR BUMPER R	1.00	116.00			116.00
11	6	S81590-02550 LAMP ASSY,RR LH	1.00	374.50			374.50
12	7	T90975-02063 REAR BOOT LID EMBLEM,	1.00	50.70			50.70
13	8	S75442-02330 PLATE, LUGGAGE COMPT	1.00	43.50			43.50
For & on behalf of			Customer's Signature		Total		
Borneo Motors (Singapore) Pte Ltd					Less		
LKK Auto Consultant like following: • To resurvey before repair • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			Charge Summary		Amount Due		
			Parts Labour Sublet Lubrication/Fluid Others				
Acknowledged by Repairer Signature: Date:							

Customer Copy



Borneo Motors

inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Mr Pang Keong 141 Bukit Batok Street 11 #08-21 Singapore 650141 Mobile: 96329102			
			Document No.					
			0					
			Document Date					
			27/01/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2015	ZRE171R	GEXGKZ S2	16/11/2015	SKW7590R	0	12983	65DS/SKW7590R	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR053REH104540422		1ZRX535185	60	Francis Cher T S	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
14	9	S75442-02340 PLATE, LUGGAGE COMPT <i>— nrc</i>			1.00	48.30		48.30
<i>Steve (LKK)</i> <i>27/1/22, 3:00pm</i> <i>W/L</i> <i>5 Lys</i> <i>PIP</i> <i>My B/Ly</i>								
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd						6,310.70		
 		Please acknowledge receipt of vehicle		Parts	1,920.70	GST 7.00%		
				Labour	4,210.00	441.75		
				Sublet	180.00	Less		
				Lubrication/Fluid	0.00	0.00		
				Others	0.00	Amount Due		
						6,752.45		

Customer Copy

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	25/01/2022 11:49 (SGT)
Date of Accident	24/01/2022 13:50 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	PIE JURONG TOWN HALL EXIT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW7590R
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	PANG KEONG
NRIC No	SXXXX229J
Email Address	YQPANG@GMAIL.COM
Mobile Phone No	(Phone) +65-96329102
Alternative Phone No	(Home) +65-96329102

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Corolla
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1600

INSURANCE COMPANY

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	A29137458AT2
Cover Note Number	-

DRIVER

Name of Driver	ANG POO YONG
NRIC No	SXXXX918J

Date Of Birth	27/05/1957
Occupation	Indoor
Date Of Driving Pass	23/04/1981
Driving experience	40 YEARS AND 9 MONTHS
Gender	Female
Mobile Number	(Phone) +65-96693046
Alt. Phone Number	-
Email Address	BELLANGPY@GMAIL.COM
Address	BLK 141 BUKIT BATOK ST 11 #08-21
Address complement	-
Postcode	650141
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Jurong Division Headquarters
Police Station Phone No	(Phone) +65-18007910000
Alt. Police Station Phone No	(Fax) +65-68965647
Police Station Address	No. 2 Jurong West Avenue 5 Singapore 649482
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO ATTACHED SEKTCH PLAN AND STATEMENT.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SG5960J
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Bus

Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

CHEN HUAYONG

-
-
-
-
-
-
-
-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time
9.30 AM

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Francis Cher
Motor Claims Assessor
Borneo Motors (S) Pte Ltd

Sketch Plan




Describe Circumstances of the Accident

Ref: Police Report

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date &
Time 25/1/22
6:30pm


Driver's Signature (If driver is not the policyholder) / Date
& Time


Francis Cher
Motor Claims Assessor
Borneo Motors (S) Pte Ltd
Witnessed by Reporting Centre
Personnel



SINGAPORE POLICE FORCE



J/20220124/7032

1 of 2

POLICE REPORT (NP299)

Police Station Of Origin
Jurong Division HQ
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No:1800-7910000

Report No. J/20220124/7032

Date/Time Report Made 24/01/2022 14:55	Vide Report No.	Station Diary No.
Name Of Informant ANG POO YONG	Address 141 BUKIT BATOK STREET 11 #08-21 SINGAPORE 650141	
ID Type / ID No. NRIC NO / S1243918J	Contact No. Home/Office: Mobile: 96693046	
Nationality SINGAPORE CITIZEN	Email Address bellangpy@gmail.com	
Occupation IT consultant (HR systems)	Sex Female	Age 64
Institution/School Name	Date of Birth 27/05/1957	Race Chinese
Date/Time Of Incident 24/01/2022 13:50 - 24/01/2022 13:55	Location Of Incident PAN ISLAND EXPRESSWAY	

Brief details.

The incident occurred when I was looking to exit the PIE exit.

While waiting for the traffic to clear up, I moved up slightly to prepare for my exit.

I still noticed a few more cars and decided to wait for a safer moment to exit.

However, the bus behind did not notice that I stopped and rear ended me.

Dashcam footage is available.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 24/01/2022 14:55
Officer In-Charge Of Case:	Classification Of Case:



SINGAPORE POLICE FORCE



J/20220124/7032

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. J/20220124/7032

Driver name: Chen Huayong

Driver license: G8609034T

Vehicle Type: SMRT double decker bus

Vehicle number: SG5960J

Subjects Involved			
Victim			
Person Name	ANG POO YONG		
ID Type	NRIC NO	ID No	S1243918J
Gender	Female	Age	64
Race	Chinese	Language	English
Occupation	IT consultant (HR systems)	Address	141 BUKIT BATOK STREET 11 #08-21 SINGAPORE 650141
Mobile No	96693046	Is Informant A Victim?	Yes
Person Name	ANG POO YONG (Informant)		

Signature Of Officer Recording The Report:
Not applicableSignature Of Interpreter:
Not applicable

Officer In-Charge Of Case:

Signature Of Informant:

The identity of the person making this
report has been authenticated by Singpass.
No signature is required.Date/Time:
24/01/2022 14:55

Classification Of Case: