,An	7	to.co	-
ASS, REC. BY:	0	TEVE	

# REF: CS/SMR22000943/Etc

ASSI	GNMENT
From: Date:	Veh No: SLG 912P Yr Regn: 15/6/21
110111	Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Estimated Cost:  OD (TP) WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
	Make: Toyota APTIS c.c 1398
To Inspect Vehicle No:	Colour A/C: Insured / Std / N1 / NA
at Workshop m/s	Sp.Reading 11963 T/Radio: Insured / Std / NI / NA
of	Eng/No:
Insured:	CNO: MRJBE-3RE-1000150N
Policy No.	Gen. Cond. Good / Fair / Poor / Burnt
Claims No.  Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
Sum insured.	Brake: Inorder/ Jammed / Leaked / Burnt or
(Client's Record)	Modl: NII / S(Rim) / STD A/Rim, or
Make of Veh:	Tyre Size: F: 205/55 R16
(Deline Condition)	P.
(Policy Condition)  Remark: The veh had commenced Its  N/S O/S	BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of Inspection.	TOYO / YOKO or
	Front Rear RyBel. 4 mm
Bal. or Market Value:  IDAC Accident Rport:  Consistent?: Yes or No	R/Bal. 4 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 0/11/20
Est. Repairs: days Res.: Yes or No	Survey held at Some?
a Mala Man or No	
TOTAL DED. / 24 UPS	Des. of Damages (Frt) Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN/OUT	The U/C / Chassis frame / Body Structure affected due to collision.
Date:Person Contacted:	The O/C / Chassis Hamo / Doc,
Date / Time Action / Instruction	
MY-104 K	
advising our Principal a	cost of repair of \$45,453.31 (P/P
before GST) - with 22 c	
repair red: 21829;329	
	67282.31
	Page Of Benefit 22
Date/Time, File Pass to? : Prell. Report	Days Of Repair.
1) : Final Report	Resurvey No. of Trip: Survey ree Transportation:
Date/Time, File Return to?  Add Fe	e: : Site Insp (\$)s+Rssi
<u>2)</u>	: Interview (\$) Photos
Panert Format	: Tech. Invs (\$) Others
Report Format: Lump Sum / I.B.I: (\$	:Weekend (\$
	TOTAL



# **Borneo Motors**



Co. Reg No.: 196700086Z GST Reg No.: MR-8500000-9 No. 2 PANDAN CRESCENT SINGAPORE 128462, Tel no: 6631 1188

TP/25

				EST	IMATE				Acres 4		
	-	Account Detail	\$	Account No			Customer	Details			
		ARTY CLAIM	liability cheek	Document 0	0 / TPCLAIM	Mr Teo Ngee Hong 222 Simei Street 4 #02-18 Singapore 520222					
V	23	rounded		Document Date		Mobile: 8198					
Yea	r	Model	Variant F	Reg. Date	Reg. No. Kilometers V		Wip No. Order No. / Re		o. / Rem	emarks	
202	1	ZRE210R GE	EXGPZ C1 1	5/06/2021	SLG0912P	0 12963 69DS/		69DS/S	SLG091	12P	
	0	Chassis No.	Engine No.	Terms	SA / Counter		Vehicle In	Co	ollected	On	
MR	2B	BE700015026 1ZR0G93619 60		60	Raymond Seah I	_M/	0.00		-	0.00	
L	Cd	Job/Parts Description			Qt	y Unit Price	Disc %		Amount		
3 4 5 6 7 8	B B Z B B B	BP-MECH2 R/I AIRCO FACILIATE REPAIRS. BP-SLANT SUPPLY S FOR BONNET, FRONT BP-LAB2 TO CHECK TO FOCUS HEADLAMF BP-LAB2 TO TRANS MOTOR/REGULATOR FACILIATE REPAIRS. BP-LAB2 TO REPLAI STRAIGHTEN/REALIGI BP-RES2 TO SPRAY AFFECTED AREAS.	ACC DATE:23/01/2 REPAIR DAYS: DATE SURVEY: SED ON: FECU AND REPROGON CONDENSER/RA BEALANT (NETT) RH APRON PANEL A WIRING AND LIGHT FER FRONT RH DOG AND OTHER ATTAC CE FRONT ACCIDEN	GRAMME ADIATOR TO AND FRONT TING. OR GLASS, HMENT TO NT DAMAGE CTED AREA	FRH DOOR. BOARD, E PARTS. 7405				7 60 3600 3540	30.00 180.00 180.00 180.00 122.40 360.00 5760.00 4720.00	
		behalf of Motors (Singapore) Pte Lt	d Customer's Sig		Charge Su Parts Labour Sublet Lubrication/Fluid Others	immary	Less	Due			




# **Borneo Motors**



Co. Reg No.: 196700086Z GST Reg No.: MR-8500000-9 No 2 PANDAN CRESCENT SINGAPORE 128462, Tel no.: 6631 1188

### **ESTIMATE**

				E3	INAIE						
_	-	Account Details		Account No	0.			Customer	Details		
THIR	DP	ARTY CLAIM		S100002 Document 0	No.	222 S #02-	eo Ngee H Simei Stree 18 apore 5202	et 4			
				Document 24/01/20		Mobi	le: 819893	91			
Ye	ar	Model	Variant I	Reg. Date	Reg. No.	Kilome	eters	Wip No.	Order N	Order No. / Remarks	
202	21	ZRE210R GE	XGPZ C1 1	5/06/2021	SLG0912P		0	12963 69DS/SLG091		12P	
	(	Chassis No.	Engine No.	Terms	SA / Counter		٧	ehicle In	cle In Collected On		l On
MF	2B	E3BE700015026	1ZR0G93619	60	Raymond Seah I	LM	//	0.00	11		0.00
L	Cd		Job/Parts Descript	ion			Qty	Unit Price	Disc %		Amount
14 15 16 17	B B B B B B B	FOR REAR BOOTLID,R SPARE TYRE PANEL. BP-MECH2 R/I REAR FACILIATE REPAIRS. BP-MECH2 R/I FUEL T FACILIATE REAPIRS. BP-LAB2 TO WATER BP-LAB2 R/I REAR RI REPAIRS AND TEST FUEL BP-WS R/I REAR WI BP-LAB2 R/I REAR C/I AND OTHER ATTACHM BP-LAB2 TO REPLACE STRAIGHTEN/REALIGN	UNDERCARRIAGE  TANK AND OTHER  TEST FOR LEAK.  EVERSE SENSOR  INCTION.  INDSCREEN TO FA  ARPET,TRIMMING, ENT TO FACILIATE  E REAR ACCIDENT  ALL OTHER AFFE  PAINT ON REAR ACR	COMPONE ATTACHME TO FACILIA CILIATE RE REAR SEAT E REPAIRS. T DAMAGE CTED AREA CCIDENT	ENT TO (pha)  TE  EPAIRS  TS (pha)  PARTS & X777  AS.  S y 597				2	12° 9 950	720.00 720.00 122.40 180.00 462.00 720.00 4720.00 824.31
		behalf of Motors (Singapore) Pte Ltd	Customer's Signature		Charge Su Parts Labour Sublet Lubrication/Fluid Others	mmary		Less Amount D	Due		





.o. Reg No. : 196700086Z GST Reg No. : MR-8500000-9 No. 2 PANDAN CRESCENT SINGAPORE 128462, Tel no. 6631 1188

### **ESTIMATE**

						HAIN I F					المرائد المراجع
		Account	Details	the state of the later of the state of the s	Account No	),	-		Customer	Details	
HIR	DP	ARTY CLAIM			S100002 Document	0 / TPCLAIM	222 #02-	Teo Ngee He Simei Stree 18 Japore 5202	14		
					Document Date			Mobile: 81989391			
Ye	ar	Model	Varia	int	Reg. Date	Reg. No.	Kilometers Wip N		Wip No.	No. Order No. / Remarks	
20:	21	ZRE210R	GEXGP	Z C1	15/06/2021	SLG0912P		0	12963 69DS/SLG09		LG0912P
	(	Chassis No.	Engi	ne No.	Terms	SA / Counter		V	ehicle In	Col	lected On
MF	R2B			60	Raymond Seah	LM	//	0.00		0.00	
L	Cd		Job	/Parts Descrip	tion			Qty	Unit Price	Disc %	Amount
19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38	2 3 4 5 6 7 8 9 0 1 2 3 4 5 6 7 8 9	\$81110-02U10 \$81150-02U00 \$85315-02740 \$85330-0K021 \$85301-02230 \$884A0-F4040 \$08889-80102 \$16400-0T400 \$16711-0T370 \$164A2-0T050 \$17753-0T090 \$17751-0T260 \$53112-02B90 \$52119-F2926 \$52125-02430 \$52115-02510 \$52116-02500 \$190467-05170 \$17749-30030 \$153879-33030	HEADLAM JAR, WASI MOTOR & INLET SUE CONDENS COOLANT, RADIATOR SHROUD, TANK, RES INLET, AIR INLET, AIR INLET, AIR GRILLE, R. COVER, FI BRACKET, SUPPORT, SUPPORT, CLIP, PIN F	PUMP ASSY, B-ASSY, WASISER ASSY, SU, SLLC&&&, SERVE SEALE CLEANER, CLEANER, ADIATOR, LW. FOG LAMP M. FR BUMPER LATER BUMPER LATER BUMPER LATER BUMPER LATER BUMPER LATER BUMPER LATER BUMPER FR BUMPER LATER BUMPER BUMPER BUMPER LATER BUMPER BUM	F + PP COSS			1.00 1.00 1.00 1.00 1.00 2.00 1.00 1.00	2170.90 2170.90 154.60 309.90 68.20 2125.00 84.30 2350.70 280.90 160.50 92.20 260.60 387.80 389.80 64.70 72.80 72.80 2.70 1.40		2170.9 2170.9 154.6 309.9 68.2 2125.0 168.6 2350.7 280.9 160.5 92.2 260.6 387.8 389.8 64.7 72.8 5.4 5.6
		behalf of Motors (Singapore)		Customer's S		Charge Su Parts Labour Sublet Lubrication/Fluid Others	ummar	у	Less Amount 0	Due	





on Reg No.: 196700086Z on Reg No.: MR-8500000-9 GST Reg No.: MR-8500000-9 No. 2 PANDAN CRESCENT SINGAPORE 128462, Tel no.: 6631 1188

### **ESTIMATE**

		Account	Details	Account No		COMMON AND		Customer	Details		
HIR	D P	ARTY CLAIM		Document 0	0 / TPCLAIM No.	222 #02	Teo Ngee He Simei Stree -18 gapore 5202	et 4			
				Document (24/01/20)		Mot	Mobile: 81989391				
Ye	ar	Model	Variant	Reg. Date	Reg. No.	Kilom	Kilometers Wip No. Ord		Order No	Order No. / Remarks	
202	21	ZRE210R	GEXGPZ C1	15/06/2021	SLG0912P		0	12963 69DS/SLG09		LG0912P	
	(	Chassis No.	Engine No.	Terms	SA / Counter		V	ehicle In	Co	flected On	
MF	R2B	E3BE700015026	1ZR0G93619	60	Raymond Seah	LM	//	0.00	11	0.00	
L	Cd		Job/Parts Des	scription			Qty	Unit Price	Disc %	Amoun	
39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58	3 4 5 6 7 8 9 0 1 2 3 4 5 6 7 8 9	\$53111-02D10 \$53395-02280 \$52161-0K040 \$52527-02070 \$75301-02210 \$53301-02400 \$53341-02410 \$790467-09050 \$53336-02040 \$790541-09117 \$753510-12C40 \$53410-02570 \$53420-02570 \$53440-02310 \$534452-02360	ABSORBER, FR BUI REINFORCEMENT S BRACKET SUB-ASS GRILLE ASSY, RADI GRILLE, RADIATOR SEAL, HOOD TO FR PIECE, RR BUMPER RETAINER, FR BUM EMBLEM SUB-ASSY HOOD SUB-ASSY INSULATOR, HOOD CLIP BRACKET, HOOD S' CUSHION LOCK ASSY, HOOD HINGE ASSY, HOOD HINGE ASSY, HOOD SUPPORT ASSY, HO HOLDER, HOOD ST, FENDER SUB-ASSY	END PER, PRAD PAY, RAD PAY, RAD PAY	C		1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00			95.9 457.1 235.7 328.1 198.7 112.3 43.0 25.6 71.6 1322.4 495.4 30.0 12.7 5.8 143.7 62.3 54.5 15.7 691.9	
		behalf of Motors (Singapore)	Pte Ltd	r's Signature ge receipt of vehicle	Charge Su Parts Labour Sublet Lubrication/Fluid Others	ummar	У	Less	Due		





O. Reg No.: 196700086Z OST Reg No.: MR-8500000-9 GST Reg No.: MR-8500000-9 SINGAPORE 128462. Tel no.: 6631 1188

# **ESTIMATE**

				ES	LIMINIE					
		Accour	nt Details	Account N	0.	acceptional Manifest	and the state of the state of	Customer	Details	
-	-		The second		20 / TPCLAIM	Mr.1	eo Ngee H	ong		
HIF	RD	PARTY CLAIM		Document	the state of the s	222	Simei Stree			
				0		#02 Sing	-18 Japore 5202	222		
				Document 24/01/20		Mob	Mobile: 81989391			
Ye	ar	Model	Variant	Reg. Date	Reg. Date Reg. No.		Kilometers Wip No.		Order No. / Remarks	
20		ZRE210R	ZRE210R GEXGPZ C1 15/06/2021		SLG0912P		0	12963	69DS/S	LG0912P
20	-		Engine No.	Terms	SA / Counter		V	ehicle In	Col	lected On
1.13		Onacoio (10)		60	Raymond Seah I	LM	//	0.00		0.00
L	C	BESBE / 000 13020		cription			Qty	Unit Price	Disc %	Amoun
59 51 52 53 54 55 56 57 68 59 70 71 72 73 74 75 76	3 4 5 6 7 8 9 0 1 2 3 4 5 6 7 8 9	\$53153-02120 \$53825-02180 \$53823-02211 \$53824-02211 \$53827-02270 \$53875-02120 \$53202-02910 \$53203-02905 \$53208-02290 \$53208-02290 \$53213-02230 \$53213-02230 \$53214-02230 \$53835-0260 \$53836-02060 \$53701-02430 \$55708-02880	FENDER SUB-ASSY, GUIDE, FR SIDE AIR PROTECTOR, FR FE PROTECTOR, FR SID PROTECTOR, FR SID PROTECTOR, FR FE R/FRT FENDER LINE SUPPORT SUB-ASS' SUPPORT SUB-ASS' SUPPORT SUB-ASS' SUPPORT, RADIATO SUPPORT, RADIATO SUPPORT, RADIATO BRACE, FR FENDER BRACE, FR FENDER APRON SUB-ASSY, FLOUVER SUB-ASSY, FLOUVER SUB-ASSY, FENDER SUB-ASSY,	NDER OF POEP OEP OEP OEP OEP OEP OEP OEP OEP OE	ELIN ?		1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	691.90 97.90 51.40 23.40 84.70 26.90 293.90 129.30 293.90 434.50 72.50 72.50 53.00 959.30 683.50 1335.20 356.80		691.9 97.9 51.4 23.4 84.7 26.8 293.9 129.3 293.9 434.5 72.5 53.0 959.3 683.5 1335.2 356.8
		h behalf of Motors (Singapore)	Pte Ltd	s Signature e receipt of vehicle	Charge Su Parts Labour Sublet Lubrication/Fluid Others	mmary	,	Less Amount D	)ue	





O. Reg No.: 196700086Z
O. Reg No.: MR-8500000-9
GST Reg No.: MR-8500000-9
GST Reg No.: MR-85000019
SINGAPORE 128462, Tel no.: 6631 1188

## **ESTIMATE**

			E31	INATE					
	Account	Details	Account No	).	1	and the second section of the second	Customer	Details	
HIRD	PARTY CLAIM		S100002 Document 0	0 / TPCLAIM	222 S	eo Ngee He Simei Stree 18 apore 5202	14		
				Document Date 24/01/2022		Mobile: 81989391			
Year	Model	Variant	Reg. Date			Kilometers Wip No.		Order No. / Remarks	
2021	ZRE210R	GEXGPZ C1	15/06/2021	SLG0912P	0 12963 69DS/S		.G0912P		
	Chassis No.	Engine No.	Terms	SA / Counter		Ve	ehicle In	Coll	ected On
MR2	BE3BE700015026			Raymond Seah	LM	//	0.00		0.00
L C	L. B. L. B		scription			Qty	Unit Price	Disc %	Amoun
880	1 SPC507-12005 17 2 T89997-30100 3 S81550-02D40 4 S81560-02D50 5 S81497-02070 6 S81498-02070 7 S81580-02C80 8 S81590-02C80 9 S81910-02280 0 S81920-02360 1 S52159-0Z961 2 S52161-0K040 8 S52575-02220 4 S52576-02220 5 S52563-02300 7 S52591-02420 8 S52592-02390 9 S52023-02240 0 S58311-02400	BACK SENSOR (11 ANTENNA, ELECTRI LAMP ASSY, RR CO LAMP ASSY, RR CO COVER, RR COMBIN COVER, RR COMBIN LAMP ASSY, RR, RI- LAMP ASSY, RR, LH REFLECTOR ASSY, REFLECTOR ASSY, COVER, RR BUMPER PIECE, RR BUMPER RETAINER, RR BUM SEAL, RR BUMPER SEAL, RR BUMPER REINFORCEMENT S PAN, RR FLOOR	CAL MBIN NATIO NATIO REFL REFL REFL REFL PER PER PER SIDE SUB-AS	·.)		1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	190.00 76.30 1297.70 1297.70 37.00 37.00 775.70 715.70 41.40 563.00 4.30 106.70 106.70 106.70 94.10 92.90 353.10 996.90		190.0 76.3 1297.7 1297.7 37.0 37.0 775.7 775.7 41.4 41.4 563.0 106.7 106.7 106.7 106.7 92.9 353.1
	R on behalf of Customer's Signeo Motors (Singapore) Pte Ltd  Please acknowledge rece			Parts Labour Sublet Lubrication/Fluid Others	ummary	,	Less Amount I	Due	





5. Reg No.: 196700086Z 5. Reg No.: MR-850000-9 35T Reg No.: MR-850000-9 35T Reg No.: MR-850000-9 35T Reg No.: MR-850000-9 35T Reg No.: 196700086Z No.: 2 PANDAN CRESCENT No.: 2 PANDAN CRESCENT No.: 2 PANDAN CRESCENT No.: 4 PANDAN CRESCENT No.: 5 PANDAN CRESCENT

# **ESTIMATE**

							-		
	Account (	Details	Account No	<b>)</b> .		Custome	Details		
HIRD PAR	RTY CLAIM			S1000020 / TPCLAIM   Mr Teo Ngee F   Document No.   222 Simei Stre   #02-18   Singapore 520		reet 4			
			1 2 3 2 2 3 1 5 1 5	Document Date 24/01/2022		9391			
Year	Model	Variant	Reg. Date	eg. Date Reg. No. Kilomet		ometers Wip No.		Order No. / Remarks	
2021	ZRE210R	GEXGPZ C1	15/06/2021	SLG0912P	0	12963	12963 69DS/SLG0		
Ch	nassis No.	Engine No.	Terms	SA / Counter		Vehicle In	Col	lected On	
MR2BE	3BE700015026	1ZR0G93619	60	Raymond Seah	LM//-	0.00	//	0.00	
L Cd		Job/Parts Des	cription		Q	ty Unit Price	Disc %	Amoun	
100 2 S 101 3 T 102 4 S 103 5 S 104 6 S 105 7 S 106 8 S 107 9 S 108 0 T 109 1 S 110 2 S 111 3 S 112 4 T 113 5 T 114 6 S 115 7 S 116 8 S 117 9 S	558387-02360 C0 790467-08186 C3 664719-02300 C0 6664771-02530 C0 661601-02570 661602-02600 661697-02190 661698-02190 66826-08115 664801-02360 664813-02250 664813-02270 721000-22 SII 664461-02310 664600-02080 664601-0680	PANEL SUB-ASSY, E PLATE, RR FLOOR CLIP COVER, LUGGAGE COVER, SPARE WI PANEL SUB-ASSY, C PANEL SUB-ASSY, C HOUSING, QUARTER HOUSING, QUARTER PANEL BONDING AD GLASS SUB-ASSY, E DAM, BACK WINDOV DAM, BACK WINDOV CA 182010 SIKA TAC KA 207. G+P ADHES PANEL SUB-ASSY, L WEATHERSTRIP, LU LOCK ASSY, LUGGAGE ARM SUB-ASSY, LUC	COMPA HEEL  QUAR QUAR QUAR R PAN R PAN BACK V GLA V GL	R P P P P P P	1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0	286.60 2.60 2.60 274.70 471.60 1061.20 1115.30 115.40 267.20 1630.80 17.20 30.30 108.00 200.00 905.20 200.00 423.90 16.20		653.2 286.6 5.2 274.7 471.6 1061.2 1115.3 115.4 1630.8 17.2 30.3 216.0 200.0 905.2 219.2 423.9 16.2 75.3	
or & on be	ehalf of lotors (Singapore) P	te Lto	's Signature	Charge Su Parts Labour Sublet Lubrication/Fluid Others	mmary	Less Amount D	)ue	*.	



Reg No.: 196700086Z JST Reg No.: MR-8500000-9 JST Reg No.: CRESCENT No. 2 PANDAN CRESCENT SINGAPORE 128462, Tel no.: 6631 1188



# **ESTIMATE**

						I IIVIA I L					
			Account	Details	Account N	0.	-	Calendary and the second	Customer	Details	
THIRD	PA	ARTY CLAI	М		-	Document No.		o Ngee Ho imei Stree 8 pore 5202	14		
					Document Date 24/01/2022		Mobile	Mobile: 81989391			
Yea	r		Model	Variant	Reg. Date	Reg. No.	Kilome	ters V	Vip No.	Order N	o. / Remarks
202	1	- 1	ZRE210R	GEXGPZ C1	15/06/2021	SLG0912P	(	)	12963	69DS/\$	SLG0912P
	С	hassis N	0.	Engine No.	Terms	SA / Counter		Ve	hicle In	Co	ollected On
MR	2BI	E3BE700	015026	1ZR0G93619	60	Raymond Seah	LM	//	0.00	//	0.00
L	Cd			Job/Parts Desc	cription			Qty	Unit Price	Disc %	Amoun
121 122 123 124	2 3 4 5 6	\$64503- \$90975- \$75442- \$75442- \$76801- \$76827- T90269-0	02062 02520 02530 02L10 02170 06017 LKK Aut the Fac • 1c • 1c • No dege • Suppler	ARM SUB-ASSY, LUC REAR LUGGAGE EM PLATE, LUGGAGE CO PLATE, LUGGAGE CO PLATE, LUGGAGE CO GARNISH SUB-ASSY RETAINER, BACK DO RIVET  Comment of following:  Comment	BLEM (FL) OMPT OMPT OMPT OR OMPT OR ON OR		W1 / 22	1.00 1.00 1.00 1.00 1.00 2.00	75.30 66.20 43.30 48.30 209.50 83.50 4.00		75.3 66.2 43.3 48.3 209.5 83.5 8.0
		behalf of Motors (S	ngapore) l	Pte Ltd Customer	s Signature	Charge Su	ımmary		Total		65,460.7
		6	)	Please acknowledg	e receipt of vehicle	Parts Labour Sublet Lubrication/Fluid		37,899.60 26,736.80 824.3	Less	)%	4,582.29
_						Others		0.00	Amount D	ue	70,042.96

### ack to OneMotoring

### quire PARF/COE Rebate for Registered Vehicle

**Vehicle Owner Particulars** 

Owner ID Type:

Owner ID: 189F

Vehicle Details

Vehicle Model:

Vehicle No.: 5LG912P

Vehicle to be Exported: Yes

Intended Deregistration Date: 24 Jan 2022
TOYOTA

Vehicle Make: COROLLA ALTIS STANDARD (AUTO)(2WD)

Primary Colour: Silver 2021

Manufacturing Year: 2021
Engine No.: 1ZR0G93619

Chassis No.: MR2BE3BE700015026

Maximum Power Output: 96.0 kW (128 bhp)

Open Market Value: \$19,481.00
Original Registration Date: \$19,481.00

First Registration Date: 15 Jun 2021

Transfer Count: \$19,481.00

Actual ARF Paid: Intended PARF Rebate Details

PARF Eligibility:
PARF Eligibility Expiry Date:

Yes

14 Jun 2031

PARF Rebate Amount: \$14,610.00

Intended COE Rebate Details 14 Jun 2031

COE Expiry Date:

A - Car up to 1600cc & 97kW (130bhp)

COE Category: 10

COE Period(Years): \$48,002.00

QP Paid: \$38,401.00

COE Rebate Amount: \$450.044.00

COE Rebate Amount: \$53,011.00

Total Rebate Amount:

The information contained herein is correct as at 24 Jan 2022

Singapore NRIC



# **Borneo Motors**



co. Reg No.: 196700086Z GST Reg No.: MR-8600000-9 No. 2 PANDAN CRESCENT SINGAPORE 128462, Tel no.: 6631 1168

# INTERNAL INVOICE

		THE RESIDENCE OF STREET, SALES AND ADDRESS OF THE PARTY O	-				Customer D	Totalla	
Vew vel	Account thicle preparation PDI or use by BMS PDI	Details	Account No. i0100001 Document N		Mr TNH 222 Sim #02-18	Teo nei Street		, class	
	ear Model Variant		38057699  Document Date 05/08/2021		Singapo	re 52022	2		
Year			Reg. Date			Kilometers Wip No		No. Order No. / R	
2021	ZRE210R	GEXGPZ C1	15/06/2021	SLG0912P	1	(	62848	69INT/SLG0912P	
	Chassis No.	Engine No.	Terms	SA / Counter		Ve	hicle In	Colle	ected On
MR2E	BE3BE700015026	1ZR0G93619	00	Raymond Seah	LM -	//	0.00	-11	0.00
L Co		Job/Parts Des	cription		10	Qty	Unit Price	Disc %	Amount
M	D1068*-PLATINUM	ABOUR FOR PLATIN	NUM SHINE PDI		7			Service 1	250.00
1 *	PSPRO PDI L D1068D) Platinum S PSPRO MAT PDI	Shine Glass Coating PLATINUM SHINE	7						
1 ** 2 **	D1068D) Platinum S PSPRO MAT PDI	Shine Glass Coating PLATINUM SHINE  Custome	r's Signature	Charge S	Summary		Total	000%	
1 * 2 * or & on	D1068D) Platinum S PSPRO MAT PDI	Shine Glass Coating PLATINUM SHINE  Custome	SET	Charge S Parts Labour Sublet	Summary	0	Total  .00 GST 0 .00 Less	.00%	250. 0. 0.

100005 / Borneo Motors Fite Ltd. 7 DATE & TIME: 24/01/2022 14:30 (SGT) AITTED BY Ashfyn China (SION 1 (24/01/2022 14 30 (SG1))



# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report porrectly the details of the accident to speed up the claims process

2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wiful misrepresentation or witholding of material facts may allow insurance companies to regulate

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (CIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

Date of Submission Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

24/01/2022 14:30 (SGT) 23/01/2022 13:00 (SGT) Singapore CHOA CHU KANG AVE 4 (LOOP)

Singapore

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

SLG912P

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner NRIC No Email Address

Mobile Phone No Alternative Phone No No

TEO NGEE HONG SXXXX189F

KTEO2010@GMAIL.COM (Phone) +65-81989391 (Home) +65-81989391

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category Transmission

CC

Toyota Corolla

No - Claiming third party

Private car Auto 1600

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage Fleet Policy **Policy Number** Cover Note Number AIG Asia Pacific Insurance Pte. Ltd.

Comprehensive

7210057645

DRIVER

Name of Driver NRIC No

TEO NGEE HONG

M A saldard round CB0G2210000E

SXXXX189F

Page 1 of 36

Birth pation e Of Driving Pass Jiving experience

Gender Mobile Number

Alt. Phone Number **Email Address** Address

Address complement

Postcode Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions

Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

PASSENGER 1

Name

Gender

DETAILS OF POLICE ACTION

Was the accident reported to the police? Was notice of intended Prosecution given?

If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO ATTACHED SKETCH PLAN AND STATEMENT.

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?

Yes Yes No

20/08/1968

05/01/2006

16 YEARS

(Phone) +65-81989391

(Home) +65-81989391

KTEO2010@GMAIL.COM

BLK 222 SIMEI ST 4 #02-18

Indoor

Male

520222

Chain Collision

Clear

Dry

No

No

Yes

2

No

Female

No No

WONG YONG YEE

3

Yes

No

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number

Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category

SMB1474U

Bus

Accident report SB0G221O0005

Page 2 of 36

Driver 10 act Number ıress .ddress complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

LEE YOON FEL SXXXX226G (Phone) +65-98909632

### **DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour

Vehicle Category Name of Driver NRIC No Contact Number

Address Address complement

Postcode Insurance Company Name

Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

Private car **LIM KAI SIANG** SXXXX711J

**SMA170H** 

(Phone) +65-90880286


### SKETCH PLAN

# IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wiful marepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Describe Circumstances of the Accident  1. Dr 23/1/2022, I was diturn my tool along thea the Famp  Are 4 at about 1 pm.  2. There was a publish by larry making a reverse furn into the small road next to BIL 200.  3. Car A and B were in a complete slop position to give ray to the lorry.  4. Suddenly, there was a tage bang on the back of my Ar and the docce pusher my car followerd, weather  5. This causes my car to hit the car right in front of my (ar.	Describe Circumstances of the Accident
into the small road next to BUE 308.  3. Car A and B were in a complete stop position to give ray to the long.  4. Suddenly, there was a truge bank on the back of my ar and the dorce pushe my car to mand the dorce pushes my car to mand the car not to find the c	1. On 23/1/2022, I was diliving my lord along thea they kang
into the small road next to BUE 308.  3. Car A and B were in a complete stop position to give ray to the long.  4. Suddenly, there was a truge bank on the back of my ar and the dorce pushe my car to mand the dorce pushes my car to mand the car not to find the c	Ax 4 at about 1 pm.
s. Car A and B were in a complete stop position to give rigy to the lorry.  For Suddenly, there was a huge bank on the back of my ar and the force pushes my car forward, acculting to this causes my car to hit the car right in front of my	De There was a subtral has been making a reverse fuces
Suddenly, there was a huge bank on the back of my ar and the force pushes my car forward, wenting I so This causes my car to hit the car right in front of my	
Suddenly, there was a huge bank on the back of my ar and the force pusher my car forward, wenting Is. This causes my car to hit the car right in front of my	and and Down to a complete the scattles to give
5. This causes my our to hit the car right in front of my	may to the long.
5. This causes my our to hit the car right in front of my	
5. This causes my our to hit the car right in front of my	ar and the force pusher my car forward, weather
s. This causes my car to hit the car right in them of my car.	
	car.

### Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



# MOTOR ACCIDENT INTERVIEW FORM

NAME (DRIVER)	. Teo Ngee Hong
VEHICLE NUMBER	: SLG 912 P
DATE/TIME OF ACCIDENT	: 23/1/2022, 1 pm
PLACE OF ACCIDENT	: choa chu cang loop
THIRD PARTY VEHICLE (IF ANY)	: SMA 170H SMB 1474 U
<b>安安老老老老老老老老老老老老老老老老老老老老老老老老老老老老老</b>	*************
where did you start your journey and where was the intended destination before the accident?  From choa chu kang BIK 476 to The Warren	
DID YOU DRINK ANY ALCOHOLIC DRINKS BEFORE YOU DRIVE ON THE DAY OF THE ACCIDENT? IF YES, DID THE TRAFFIC POLICE CONDUCT ANY BREATHE-ANALYSER TEST ON YOU? IF YES, WHAT IS THE RESULT?	
WHAT IS THE TYPE OF COLLISION AND THE EXTENSIVENESS OF THE DAMAGES TO ALL VEHICLES INVOLVED?	
WERE YOU OR YOUR PASSENGER/S INJURED? IF INJURED, WHICH HOSPITAL? WERE YOU TAKEN TO THE TRAFFIC POLICE FOR INVESTIGATION?	
Teo Ngee Hong	

I Affirmed The Above Information Is Given To My Best Knowledge.

AIG Asia Pacific Insurance Pte. Ltd. AIG Building 78 Shenton Way #07-16 Singapore 079120 Tel; 6419 3000