

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705 Code: SMR 1. Policy Particulars: - THIRD PARTY CLAIM Insured Veh. SHB 1285H Veh. Inspected SLH 4878Z Policy No. Coverage (\$) 0.00 Claim No. TAX/01/22/2043 Excess (\$) Assign From HUA YEN Assign Date 26/01/2022 2. Vehicle Particulars & Condition Make & Model HYUNDAI LF SONATA C.C 1999 Engine No. HIDDEN Year of Reg. 2016 Chassis No. KMHE341CMHA308364 Colour GREY	Vvcn2	
E4SINGAPORE 757705 Code: SMR 1. Policy Particulars: - THIRD PARTY CLAIM Insured Veh. SHB 1285H Veh. Inspected SLH 4878Z Policy No. Coverage (\$) 0.00 Claim No. TAX/01/22/2043 Excess (\$) 0.00 Assign From HUA YEN Assign Date 26/01/2022 2. Vehicle Particulars & Condition Make & Model HYUNDAI LF SONATA c.c 1999 Engine No. HIDDEN Year of Reg. 2016 Chassis No. KMHE341CMHA308364 Colour GREY		
1. Policy Particulars: - THIRD PARTY CLAIM Insured Veh. SHB 1285H Veh. Inspected SLH 4878Z Policy No. Coverage (\$) 0.00 Claim No. TAX/01/22/2043 Excess (\$) 0.00 Assign From HUA YEN Assign Date 26/01/2022 2. Vehicle Particulars & Condition Make & Model HYUNDAI LF SONATA c.c 1999 Engine No. HIDDEN Year of Reg. 2016 Chassis No. KMHE341CMHA308364 Colour GREY		
Insured Veh. SHB 1285H Veh. Inspected SLH 4878Z Policy No. Coverage (\$) 0.00 Claim No. TAX/01/22/2043 Excess (\$) 0.00 Assign From HUA YEN Assign Date 26/01/2022 2. Vehicle Particulars & Condition Make & Model HYUNDAI LF SONATA c.c 1999 Engine No. HIDDEN Year of Reg. 2016 Chassis No. KMHE341CMHA308364 Colour GREY		
Policy No. Coverage (\$) 0.00		
Claim No. TAX/01/22/2043 Excess (\$) 0.00 Assign From HUA YEN Assign Date 26/01/2022 2. Vehicle Particulars & Condition Make & Model HYUNDAI LF SONATA c.c 1999 Engine No. HIDDEN Year of Reg. 2016 Chassis No. KMHE341CMHA308364 Colour GREY		
Assign From HUA YEN Assign Date 26/01/2022 2. Vehicle Particulars & Condition Make & Model HYUNDAI LF SONATA c.c 1999 Engine No. HIDDEN Year of Reg. 2016 Chassis No. KMHE341CMHA308364 Colour GREY		
2. Vehicle Particulars & Condition Make & Model HYUNDAI LF SONATA c.c 1999 Engine No. HIDDEN Year of Reg. 2016 Chassis No. KMHE341CMHA308364 Colour GREY		
Make & ModelHYUNDAI LF SONATAc.c1999Engine No.HIDDENYear of Reg.2016Chassis No.KMHE341CMHA308364ColourGREY		
Engine No. HIDDEN Year of Reg. 2016 Chassis No. KMHE341CMHA308364 Colour GREY		
Chassis No. KMHE341CMHA308364 Colour GREY		
Odometer 124369 KM Steering IN ORDER		
Brakes IN ORDER Modification SPORTS RIM		
General GOOD		
3. Conditions of Tyres		
Size Make Balance		
R/H Front Tyre 206/60 R16 BRIDGESTONE 6 mm		
L/H Front Tyre 206/60 R16 BRIDGESTONE 6 mm		
R/H Rear Tyre 206/60 R16 BRIDGESTONE 6 mm		
L/H Rear Tyre 206/60 R16 BRIDGESTONE 6 mm		
4. Description of Damages		
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.		
DAMAGES SEE DETAILS.		
5. General Information		
Accident Date 20/01/2022 Inspection Date 26/01/2022		
Survey held at HUI HUANG HONG BAO MOTORS		
2 KAKI BUKIT AVENUE 2 #02-11 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks		
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair		
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days		