



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22000945/Uvf3n2 Date: 14/03/2022 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SBL 1881E	Veh. Inspected	SLM 6270L
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10013603/CD	Excess (\$)	0.00
	Assign From	IVY RATILLA	Assign Date	27/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA CITY SV (A)	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	MRHGM6660HP000533	Colour	GREY
	Odometer	68113 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/55 R16	DUNLOP	6 mm
	L/H Front Tyre	185/55 R16	DUNLOP	6 mm
	R/H Rear Tyre	185/55 R16	DUNLOP	6 mm
	L/H Rear Tyre	185/55 R16	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/01/2022	Inspection Date	27/01/2022
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	