

REF: CS1/FCI22000957/Rvf3

Special Instruction:

ASSIGNMENT (Office)

L/SUM : \$ 15,242.00

From (Person): ESTHER LIM of FCI Date/Time: 27/1/2022 1:40 PM

Third Parties:

Estimated Cost: _____ Bill to: _____

Claimant:

OD/TP Re-inspection / Evaluation

Surveyor:

Workshop: CROWN ASIA BUS BUILDER PTE LTD

To Inspect Vehicle No: PA 9349R Insured: YP 6451L

at Workshop m/s CROWN ASIA BUS BUILDER PTE LTD Tel: 9722 8998

of NO. 44 SUNGEI KADUT STREET 1 SINGAPORE 729349

Policy No: _____ Claim No: D17010246MFCV

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 01/11/2017
(Client's Record)

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 7/2/22 Confirmed with Lab 2320 Final Fig , days (Red \$ / %; Original 0 days)

Date/Time: 7/2/22 Submit Final Fig LS 3700, 5 days (Red \$ 11542 / 75 %; Original days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	
--	--

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

1) Date/Time _____ File Pass to _____ 2) Date/Time _____ File Return to _____
3) Date/Time _____ File Pass to _____ 4) Date/Time _____ File Return to _____
5) Date/Time _____ File Pass to _____ 6) Date/Time _____ File Return to _____