



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KHOR SAW THENG			Ref: CC4/ASM22000975/Aea3q2 Date: 18/05/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SBR 46A	Veh. Inspected	SKX 2429C
	Policy No.	GA588389	Coverage (\$)	0.00
	Claim No.	S2M03S24	Excess (\$)	0.00
	Assign From		Assign Date	27/01/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	MAZDA 3	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JM6BM42A8G0323876	Colour	BRONZE
	Odometer	101570 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm
	L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm
	R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm
	L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	24/01/2022	Inspection Date	07/02/2022
	Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	