

(08/11/13) wef

ASS. REC. BY: JamesREF: CS3/ALH21010221/RUG

Rvf3-1

3352

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBF 9630Sat Workshop m/s ENH SOON PAINTINGof 4, YANTEE IND EST 393-5Insured: GQ 4359SALH

Policy No.

Claims No. 6345301349SG

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 50K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: GBF 9630SYr Regn: 2017 / APRType: M.Car / M.Cycle / Bus / Van / Corry / Taxi / Prime Mover /

Truck / Trailer or

Make: MITSUBISHI CANTERPEAB c.c 2998Colour: WHITE

A/C: Insured / Std / NI / NA

Sp. Reading: 158673

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: PEA01BA 20519Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/75R15

R:

155R12CBS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

5/5

mm

L/Bal.

7

mm

L/Bal.

5/5

mm

D.O.A.

30/09/21

D.O.I.

26/10/21

Survey held at

ENH SOON

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair limit - 24K

27/10/21

Submit DAR

7/2/22

Submit LS \$2100 (red 2450, 53%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 7/2/22-typist

Days Of Repair: 4

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

): S + RS \$☐

: Interview (\$

): Photos

☐

: Tech. Invs (\$

): Others

☐

: Weekend (\$

):

Report Format: TP

Lump Sum / I.B.I: (\$

Condition (CON)
 (01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched (07) Deformed
 (08) Shifted (09) Buckled (10) Broken (11) Necessary (12) Missing (13) Torn
 (14) Unconfirmed (15) Not Working

ACTION (AC)
 (1) Replace (✓) (2) Repair (R) (3) Check (P)
 (4) Not Consistent (NC)

Aug 2005

VAN / LORRY (Frt)

6BF 96305

Vehicle No:

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1004	991300	Frt Bumper	bt	/	
2001	991477	Frt Bumper Upper			
2002	991387	Frt Bumper Lower			
2003	991449	Frt Bumper Side Cover			
2004	991443	Frt Bumper Side GARNISH LH	de	/	
1006	991325	Frt Bumper Bracket			
1008	991433	Frt Bumper Reinforcement			
2005	991466	Frt Bumper Signal Lamp			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
2006	990247	Frt Grille Sticker			
1023	991799	Frt Grille Chrome Moulding			
2007	991891	Frt Panel			
2008	991874	Frt Lower Panel			
2009	991328	Frt Panel Emblem			
2010	990247	Frt Panel Sticker			
2011	991893	Frt Panel Garnish			
1024	991222	Frt Apron Panel			
2012	991527	Frt Corner Panel LH	bt	/	
2013	991532	Frt Corner Panel Signal Lamp			
2014	995245	Frt Signal Lamp LH			
2015	995246	Frt Signal Lamp RH			
1029	995153	Frt LH Headlamp Assy	bro	/	
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
2016	992149	Frt Wiper Panel			
2017	995043	Frt Wiper Nozzle			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
2018	992145	Frt Wiper Link			
2019	992148	Frt Wiper Motor			
1122	995045	Wiper Panel Garnish			
1114	992093	Frt Windscreen			
1115	992097	Frt Windscreen Rubber			
1117	992098	Frt Windscreen Sealant			
2020	992114	Frt Windscreen Outer Pillar			
2021	992113	Frt Windscreen Inner Pillar			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
2022	991958	Frt Side Mirror (Big)			
2023	991959	Frt Side Mirror (Small)			
2024	991962	Frt Side Mirror (Round) MASTAY LH	bt	/	
2025	995015	Frt Wing Mirror Stay			
1025	992013	Frt Support Panel			
1033	990248	Bonnet			
1035	990287	Bonnet Lock			
1037	990273	Bonnet Hinge			
1039	990305	Bonnet Rubber			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1056	992758	Radiator Hose Top			
1058	992741	Radiator Expansion Tank			
2026	992596	Oil Cooler			
1079	994431	Power Steering Cooler Pipe			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1067	990219	Battery			
1069	990223	Battery Bracket			

NAC	INC	Item	CON	AC	Qty
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
2027	991500	Frt Cabin Assy			
2028	991501	Frt Cabin Mounting			
2029	991502	Frt Cabin Rear Panel			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
2030	990143	Air Con Evaporator Assy			
2031	990106	Air Con Blower			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
2032	990431	Brake Pedal			
2033	990021	Accelerator Pedal			
2034	990627	Clutch Pedal			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1131	990029	Airbag Control Unit			
1133	991922	Frt RH Seat Belt Assy			
1135	995182	Frt LH Seat Belt Assy			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
2035	994966	Frt LH Wheel Guard			
1102	995170	Frt LH Wheel Rim			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
2036	994966	Frt RH Wheel Guard			
1111	992087	Frt RH Wheel Rim			
1113	995065	Frt RH Tyre			
1255	995326	Frt LH Door			
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1272	991617	Frt LH Door Inner Trim Board			
1316	995327	Frt RH Door			
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1333	991617	Frt RH Door Inner Trim Board			
2037	991644	Frt Door Frt Pillar			
2038	991657	Frt Door Rear Pillar			
2039	992072	Frt Wheel Arch Panel			
2040	992069	Frt Wheel Arch Panel Garnish			
2041	991996	Frt Step Panel			
2042	994498	Frt Step Panel Top Garnish			
2043	994495	Frt Step Panel Inner Garnish			
1073	995053	Wiper Washer Tank			
1136	990247	Sticker			

4 days

No of Items: _____ Assessor: _____

ORIGINAL COPY

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	335C
Vehicle No.:	GBF9630S
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Oct 2021
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEA01BR2SDEB (CBU)
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	4P10C48B79
Chassis No.:	FEA01BA20519
Maximum Power Output:	-
Open Market Value:	\$30,506.00
Original Registration Date:	26 Apr 2017
First Registration Date:	26 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$1,526.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	25 Apr 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$45,906.00
COE Rebate Amount:	\$25,246.00
Total Rebate Amount:	\$25,246.00

The information contained herein is correct as at 26 Oct 2021

OK