

MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4 (South Wing) #04-01
Vicom Inspection Centre, Singapore 415933
Tel: 6243 1373 Fax: 6243 1376
GST. Reg. No. : 201427944N

Date : 22/1/2022

To : AXA INSURANCE SINGAPORE PTE LTD

By Fax & Email

Tel : 1800-0004741

Fax :

Email : motor-survey@axa.com.sg

Attn: Motor Claims Department

Dear Sir,

Re: Accident involving motor vehicle Nos. SJS 2624T and SLX 5878M along
183 JALAN PELIKAT CARPARK on 22/1/2022

We are instructed by ABDUL KAZAK BIN YUSOFF RAMADHAY (Name of Claimant)
to notify you of a road traffic accident on the above mentioned. A copy of the Singapore
Accident Statement / Traffic Police Report filed is enclosed.

As a result of the accident, our client's / customer's vehicle has been damaged. Before our client
/ we proceed to repair the damaged vehicle, please let us know within **2 working days** of your
receipt of this notice whether you or your insurer would like to conduct a **Pre- Repair Survey** of
the vehicle. If we do not receive any reply from you within the stipulated timeline, our client / we
shall proceed to repair the vehicle without further reference to you.

Thank you.

Yours faithfully,



MS. HENG YOKE HONG
HP: 8121 1373

FOR SURVEYOR

Please initial here after completion of pre-repair
inspection. Thank you.

Appointed Surveyor: _____
(Name & Signature)

Date & Time of Inspection: _____