

ASS. REC. BY:

REF: C12 / 22 000 999 / Kt

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP / 24 HRS

Date:

11/31

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKE 2244T

Yr Regn: 02, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volvo S80 T5 c.c. 1999

Colour:

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

198515

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

YV1AS475BC1154378

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

225/508R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

5 mm

R/Bal.

6 mm

L/Bal.

5 mm

L/Bal.

6 mm

D.O.A.

25/1/12

D.O.A.

28/1/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LUMP SUM \$4000, 4DAYS

RED: 2468.30; 38%

6468.30

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

MOTOR EDGEVANTAGE PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity #03-01/02, Singapore 575722 & GST 201534758N
+65 6453 7683 clientservices@edgevantage.com www.edgevantage.com

To:

Mr Ding Chin Look

SKE2244T, VOLVO, S80 T5 2.0 A/T ABS AIRBAGS 2WD 4DR TURBO

4 Lichi Avenue

Sennett Estate

Singapore 348777

Attn: Ding Chin Look (96881212)

Work Order

Job No. : WJ2201322

Date : 28/01/2022

Time in : 28/01/2022 10:00

Time out :

*Not Authorised
11 Sep @
Recovery After Repair*

4 days

T	Job Description	Operation	Quantity	UOM	Unit Price	Amt	
Essential Works							
S	Volvo rear boot lid assembly S80	<i>K</i>	1.00	PCS	2,150.00	2,150.00	<i>X</i>
S	Volvo rear boot lid chrome moulding S80	<i>L</i>	1.00	PCS	423.00	423.00	<i>X</i>
S	Volvo rear boot lid emblem (S80)	<i>M</i>	1.00	PCS	85.00	85.00	<i>✓</i>
S	Volvo rear boot lid emblem (VOLVO)	<i>M</i>	1.00	PCS	124.00	124.00	<i>✓</i>
S	Volvo rear boot lid emblem (T5)	<i>M</i>	1.00	PCS	86.00	86.00	<i>✓</i>
S	Volvo rear boot lid hinges LH	<i>K</i>	1.00	PCS	221.00	221.00	<i>X</i>
S	Volvo rear boot lid hinges RH	<i>K</i>	1.00	PCS	221.00	221.00	<i>X</i>
S	Volvo rear boot lid absorber	<i>L</i>	2.00	PCS	78.00	156.00	<i>X</i>
S	Volvo rear bumper assembly S80	<i>B</i>	1.00	PCS	2,128.30	2,128.30	<i>✓</i>
S	Volvo rear bumper side bracket RH		1.00	PCS	85.00	85.00	<i>?</i>
S	Volvo rear bumper side bracket LH		1.00	PCS	85.00	85.00	<i>?</i>
S	Volvo rear bumper reinforcement S80		1.00	PCS	1,582.00	1,582.00	<i>?</i>
S	Volvo rear bumper lower spoiler S80	<i>M</i>	1.00	PCS	1,120.00	1,120.00	<i>✓</i>
S	Volvo rear section panel S80	<i>K</i>	1.00	PCS	1,693.00	1,693.00	<i>✓</i>
S	Volvo rear boot lid lock S80	<i>M</i>	1.00	PCS	283.00	283.00	<i>✓</i>
S	Volvo rear boot lid catch S80	<i>K</i>	1.00	PCS	230.00	230.00	<i>X</i>
S	Volvo rear parking sensor S80		4.00	PCS	128.90	515.60	<i>?</i>
S	Volvo rear parking sensor harness S80	<i>10%</i>	1.00	PCS	850.00	850.00	<i>?</i>
S	To remove , re- install, replace of rear boot lid trunk , rear bumper , rear bumper reinforcement, lower spoiler		1.00		1,600.00	1,600.00	<i>400</i>
S	To putty, repair spray painting rear boot lid truck , rear bumper , rear inner section panel & spare tyre compartment		1.00		1,600.00	1,600.00	<i>660</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Continue on next page...

Acknowledged by Repairer

Signature:

Date:

MOTOR EDGEVANTAGE PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity #03-01/02, Singapore 575722 & GST 201534758N

+65 6453 7683 clientservices@edgevantage.com www.edgevantage.com

To:

Mr Ding Chin Look

SKE2244T, VOLVO, S80 T5 2.0 A/T ABS AIRBAGS 2WD 4DR TURBO

4 Lichi Avenue

Sennett Estate

Singapore 348777

Attn: Ding Chin Look (96881212)

Work Order

Job No. : WJ2201322

Date : 28/01/2022

Time in : 28/01/2022 10:00

Time out :

T	Job Description	Operation	Quantity	UOM	Unit Price	Amt
S	To conduct welding on rear section panel & Realign rear spare tyre compartment		1.00	~	600.00	600.00
S	To check wiring & reset fault code		1.00		200.00	200.00

Remarks:

cash card - \$\$\$

3rd party hit by construction vehicle

This is a computer generated Work Order. No Signature is required.

Subtotal

16,037.00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 26/01/2022 10:36 (SGT)
Date of Accident 25/01/2022 18:15 (SGT)
Exact Location of Accident Singapore
Additional Location Information CHOA CHU KANG WAY
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKE2244T

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner DING CHIN LOOK
NRIC No S2003142E
Email Address DING1807@GMAIL.COM
Mobile Phone No (Phone) +65-96881212
Alternative Phone No +65-96881212

VEHICLE PARTICULARS

Manufacturer Volvo
Model S80 T5 2.0 A/T ABS AIRBAGS 2WD 4DR TURBO
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1999


INSURANCE COMPANY

Name of Insurance Company Etiqa Insurance Pte Ltd
Type of Coverage -
Fleet Policy No
Policy Number M0004258
Cover Note Number -

DRIVER

Name of Driver DING CHIN LOOK
NRIC No S2003142E

SKETCH PLAN



A: SKE 2244T

B: XE 2409G

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 25.01.22 at about 18.15pm hrs
I was driving toward Choa Chu Kang way. I was checking
on coming traffic, trying to turn out. The Lorry
behind me XE 2409G didn't stop in time and hit onto
my Rear of my vehicle.

I will make the 3rd party claim at
Motor Edgeworks.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

