

REF:

E 9099A

Veh No: SLF2351A - Yr Regn: 2016 / August.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel Hybrid c.c 1496

Colour White A/C: Insured / Std / NI / NA

Sp. Reading 166013 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: R431205085 \*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/45R19.

R: 225/45R19.

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 26/01/22

\*Survey held at HD Perfect.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

679:☐: Prel. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:  : Site Insp (\$

☐ Interview (\$

Tech. Inve 63

Weekend 13

Transportation:

$$S + RS \rightarrow S$$

Photos

|   |        |     |
|---|--------|-----|
| 1 | Others | 1.0 |
|---|--------|-----|