

REF:

Veh No: SK486903 Yr Regn: 2015 / Hunt

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda3 C.C. 1496

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading 96879 T/Radio: Insured / Std / NI / NA

Enq/No:

C/No: JM6Bm44A860*316360

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17.

R: 215/55R17.

R: 215/55R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO/YOKO or *Falken*

Front ☐ Rear ☐

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 26/01/22

Survey held at YSK

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

	
N/S	O/S

Date / Time	Action / Instruction
	TP AIG
	MV :
	PV :
	Nett:

☐: Prel. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: : Site Insp (\$☐ : Site Insp (\$

 Interview (\$)

Tech. Invs (3)

Michael 13

Transportation:

$$S + PS \rightarrow SI$$

Photos

3	Others	
---	--------	--