(08/11/13) wef ASS. REC. BY: Marcus REF: CS/	27/22222111 2
	C7/22001011/Ugy3 SSIGNMENT
<u>A</u>	,
From: Date:	Veh No: FBL 2/6/T Yr Regn: 15/17/16
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP) WS / TP RES / OD RES / EVA / INV / MV	Truck/Trailer or 3- Wheele
To Inspect Vehicle No: FBC 2/6/	Make: ADIVA AR3 ZOU c.c /7/
at Workshop m/s	Colour Shul A/C: Insured / Std / NI / NA
of 2 c 2 c 2	Sp.Reading T/Radio: Insured / Std / NI / NA
Insured: 6BA 3881A	Eng/No:
Policy No.	C/No: RGVTC40AAGA00006
Claims No. SMM>10 20484/CO2	Gen. Cond: Good Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder Jammed Leaked Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 120 / 70 214
(Policy Condition)	R: 120 / 70-12
Remark: The veh had commenced its 0/8	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or SHINKD
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent?: Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. mm L/Bal. 6 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 8/12/21 D.O.I. 9/2/22
Lum Sum: 70 % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS 623M	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OU	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
27A atas 9-2-22 15 \$ 35-71	1
Nett & syze?	
3/3/224/5 \$5000 informed	Roymond. (Red \$ 10450, 68%) Le Tay vin Menanen.
39/3/22@ 11. War noted to lown	e Tay via Meñaren.
Date/Time, File Pass to?	
. Freii. Report	Days Of Repair:
1) 09/3 Miles : Final Report Date/Time, File Return to?	Resurvey No. of Trip: / Survey Fee:
Sater raile, the Neturn tor	Transportation:

Date/Time, File Pass to?	: Preli. Report	D	ays Of Repair:	5		
1) 09/3 truis	: Final Report	R	esurvey No. of 1	Γrip: /	Survey Fee:	
Date/Time, File Return to?					Transportation:	
2)		Add Fee:	: Site Insp	(\$)S+RS,SI	
			: Interview	(\$) Photos	
Report Format :	MER-TP		: Tech. Invs	(\$) Others	
Lump Sum / LB.T: (\$	5000)	: Weekend	(\$)	
					TOTAL	



QUOTATION

NO. : 39972

Customer:

CHINA TAIPING INSURANCE (S) PTE LTD

105 CECIL STREET #18-00 / 19-00 THE OCTAGON S'PORE 069534

ATTN: MOTOR CLAIMS DEPT

VEHICLE NO.

: FBL2161T

MAKE/MODEL

: ADIVA / AR3 200

not Arthurst ner 9/2/22

DATE

: 09/12/2021

CLAIM NO. : 11860

POLICY NO.

FROM

: RAYMOND

The ohe After Mg.

(Page 1 of 5)

		0 1 - 1					
S/N	Description		<u>Action</u>	Qty	Unit Price	, I	<u>Amount</u>
1	ADAPTER MIRROR (AFTERMARKET) P/N: 65136 - (REPORTED BY MECHANIC))	REPLACE	1.00	\$21.00	Dong 1	21.00
2	AXLE HOLDER COMP LH P/N: 53651 - (REPORTED BY MECHANIC)		REPLACE	1.00	\$364.00	sul	364.00
3	BALL SET P/N: 48814 - (REPORTED BY MECHANIC)		REPLACE	1.00	\$19.00	11	19.00 💃
4	BALL SET SMALL P/N: 48813 - (REPORTED BY MECHANIC)	102	REPLACE	1.00	\$14.00	12	14.00 🗶
5	BEARING 6005ZZ (NACHI) P/N: 15370 - (REPORTED BY MECHANIC)		REPLACE	2.00	\$14.00	11	28.00 🗴
6	BEARING 6007-2RSR (FAG) P/N: 30211 - (REPORTED BY MECHANIC)		REPLACE	4.00	\$25.00	nec	100.00
7	BEARING 6202-2NS (NACHI) P/N: 36695 - (REPORTED BY MECHANIC)		REPLACE	2.00	\$14.00	Ru	28.00 7
8	BEARING 6302-2NS (NACHI) P/N: 38132 - (REPORTED BY MECHANIC)		REPLACE	1.00	\$14.00	nn	14.00
9	BEARING SUSPENSION LOWER 1 P/N: 54205		REPLACE	8.00	\$13.00	X	104.00

*39972

- (REPORTED BY MECHANIC)

LKK Auto Consultants hence notify

- the Repairer of the following:

 To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company





Quote	ILIOIT 1405 33372				(1 ago 2 o. o)
<u>S/N</u> 10	Description BEÀRING SUSPENSION LOWER 2 P/N: 54206	Action REPLACE	<u>Qty</u> 16.00	Unit Price \$12.00	<u>Amount</u> 192.00 ≯
11	- (REPORTED BY MECHANIC) BOTTOM DUST GUARD P/N: 48811	REPLACE	1.00	\$27.00	17 27.00 X
12	- (REPORTED BY MECHANIC) BRACKET MUDGUARD REAR LH P/N: 48915 (REPORTED BY MECHANIC)	REPLACE	1.00	\$82.00	BUT 82.00
13	- (REPORTED BY MECHANIC) BRACKET UNDER FORK P/N: 57233 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$283.00	1 -1 283.00 X
14	COVER SIDE LH P/N: 48677	REPLACE	1.00	\$227.00	CU7 227.00
15	- (REPORTED BY MECHANIC) FOOTBOARD LH P/N: 49980	REPLACE	1.00	\$147.00	SAO 147.00
16	- (REPORTED BY MECHANIC) FRAME REAR P/N: 54560	REPLACE	1.00	\$1,165.00	But/ul 1,165.00
17	- (REPORTED BY MECHANIC) GEAR BOX ASSY (V4) P/N: 65522	REPLACE	1.00	\$2,520.00	MA 2,520.00 X
18	- (REPORTED BY MECHANIC) HEADLIGHT LH P/N: 49385	REPLACE	1.00	\$217.00	Cre 217.00
19	- (REPORTED BY MECHANIC) HEADLIGHT RH P/N: 51547	REPLACE	1.00	\$217.00	Scn 11 (C 217.00 X
20	- (REPORTED BY MECHANIC) IGNITION STEERING LOCK SWITCH ASSY P/N: 51423	REPLACE	1.00	\$462.00	Janyed 462.00
21	- (REPORTED BY MECHANIC) LOCK CAM 30MM P/N: 50288	REPLACE	4.00	\$26.00	Pin X 104.00 X
22	- (REPORTED BY MECHANIC) MIRROR (AFTERMARKET) LH P/N: 65270	REPLACE	1.00	\$84.00	CU7 84.00
23	- (REPORTED BY MECHANIC) MUDGUARD FRONT ASSY (UNPAINT) P/N: 48791 (REPORTED BY MECHANIC)	REPLACE	1.00	\$112.00	∠ 112.00 ¥
24	- (REPORTED BY MECHANIC) MUDGUARD REAR METALLIC LH P/N: 48918 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$84.00	300 84.00

*39972 *



~~~	tion Nos. : 39972					(rage o or s)
<u>S/N</u> ` 25	Description  RACE STRG TOP COND  P/N: 48807  - (REPORTED BY MECHANIC)		Action REPLACE	<u>Qty</u> 1.00	<u>Unit Price</u> \$27.00	Amount 27.00 X
26	RADIATOR P/N: 58486 - (REPORTED BY MECHANIC)		REPLACE	1.00	\$318.00	11 318.00 X
27	RADIATOR GRILL P/N: 51971 - (REPORTED BY MECHANIC)		REPLACE	1.00	\$70.00	70.00
28	REPAIR ON BODY ALIGNMENT - (REPORTED BY MECHANIC)	L	Repair 🙏	1.00	\$490.00	3SV 490.00
29	REPAIR ON CENTER SIDE BOXES LH - (REPORTED BY MECHANIC)	SCR	Repair 🎸	1.00	\$84.00 人	R SV 84.00
30	REPAIR ON REAR BOX - (REPORTED BY MECHANIC)	SCR	Repair 🛧	1.00	\$112.00 <u></u>	R & 112.00
31	REPAIR ON REAR SIDE BOXES LH - (REPORTED BY MECHANIC)	SCR	Repair 🕏	1.00	\$84.00	LR 10 84.00
32	REPAIR SADDLE P/N: 49646	SCR	REPLACE d	1.00	\$104.00	CR 80 104.00
33	- (REPORTED BY MECHANIC) RIM REAR ASSY P/N: 68297		REPLACE	2.00	\$336.00	15 benf 672.00 lcc
34	- (REPORTED BY MECHANIC) RIM SPORT FRONT P/N: 51630		REPLACE	1.00	\$448.00	<b>₹</b> 448.00 <b>£</b>
35	- (REPORTED BY MECHANIC) ROD REAR FRAME CONNECTOR P/N: 71646		REPLACE	1.00	\$280.00	RM 280.00 X
36	- (REPORTED BY MECHANIC) RUBBER BOOT (HARD) P/N: 33352		REPLACE	40.00	\$1.00	140.00
37	- (REPORTED BY MECHANIC) SEAL DUST STEERING CONE P/N: 53166	010	REPLACE	1.00	\$7.00	11 X 7.00
38	- (REPORTED BY MECHANIC) SHELVES REAR P/N: 53650		REPLACE	1.00	\$1,055.00	Suf (Tm 1,055.00
39	- (REPORTED BY MECHANIC) SHIELD ASSY FRONT METALLIC (UNPAIN P/N: 49437 - (REPORTED BY MECHANIC)	T)	REPLACE	1.00	\$528.00	Sno 528.00

*39972 *



(Page 4 of 5)

Quotation Nos.: 39972

Quota	tion Nos. : 39972				(1 age 4 01 0)
<u>S/N</u> 40	Description SPACER SUSPENSION ARM LH P/N: 54203	Action REPLACE	<u>Qty</u> 4.00	<u>Unit Price</u> \$42.00	Amount 168.00 X
41	- (REPORTED BY MECHANIC)  SPACER SUSPENSION ARM RH  P/N: 54204  - (REPORTED BY MECHANIC)	REPLACE	8.00	\$30.00	~7 × 240.00
42	SPARY PAINT ON REAR BOX - (REPORTED BY MECHANIC)	Spray 1	1.00	\$980.00	360, 980.00 /
43	SPRAY PAINT ON CENTER SIDE BOXES LH - (REPORTED BY MECHANIC)	Spray	1.00	\$112.00	112.00 K
44	SPRAY PAINT ON REAR SIDE BOXES LH - (REPORTED BY MECHANIC)	Spray	1.00	\$112.00	112.00
45	STICKER (SINGAPORE POST) SIDE BOX LH P/N: 47183 - (REPORTED BY MECHANIC)	REPLACE 4	2.00	\$42.00	· AA, 84.00 X
46	STICKER (SINGAPORE POST) SIDE BOX LH P/N: 47183 - (REPORTED BY MECHANIC)	REPLACE %	2.00	\$42.00	11, 84.00 X
47	STICKER (SINGPOST) BOX REAR P/N: 46357 - (REPORTED BY MECHANIC)	REPLACE d	1.00	\$232.00	11 232.00 X
48	SUPPORT MIRROR LH P/N: 53206 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$9.00	17 × 9.00
49	TOP CAP P/N: 48808 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$27.00	イカメ 27.00
50	TOP CAP P/N: 48810 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$27.00	u 1 × 27.00
51	TRANSMISSION SHAFT LH P/N: 54457 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$954.00	Pry X 954.00
52	TRANSPORT CHARGES (MOTORCYCLE) OVERSIZED P/N: 45837 - BIKE TOWED BACK TO BHH	₩	1.00	\$98.00	3€ 98.00
53	VALVE RIM P/N: 27762 - (REPORTED BY MECHANIC)	REPLACE	300	\$13.00	AU 39.00   PC

SUB TOTAL GST @ 7 %

**GRAND TOTAL (SGD)** 

\$14,200.00 \$994.00

\$15,194.00

*39972







CHINA TAIPING INSURANCE (S) PTE LTD

QUOTATION

NO. : 40162

Supplementary 1 To QTN: 39972

DATE

: 01/03/2022

: 11860

Acknowledge & Accepted By

CLAIM NO.

POLICY NO. :

**FROM** 

: RAYMOND

VEHICLE NO.

Customer:

105 CECIL STREET #18-00 / 19-00

THE OCTAGON

S'PORE 069534

: FBL2161T

MAKE/MODEL

: ADIVA / AR3 200

S/N	<u>Description</u>	1	<u>Action</u>	Qty	Unit Price		<u>Amount</u>
1	BRACKET SIDE MIRROR LH	( (02	Replace	1.00	\$35.00	CUI	35.00
	P/N: 65359					N 1	
2	CONNECTOR REAR FRAME		Replace	1.00	\$140.00	aged	140.00
	P/N: 64512						
3	LABOUR		Supply/Install	24.00	\$45.00	600	1,080.00
	P/N: 06766					000	

SUB TOTAL GST @ 7 %

**GRAND TOTAL (SGD)** 

\$1,255.00 \$87.85

\$1,342.85

### 50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

HIN CO PIL

**RAYMOND** 

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*40162 *



S/N Description

**Action** 

**Unit Price** 

Qty

**Amount** 

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

Acknowledge & Accepted By

BAN HOCK HIN CO PTE LTD



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*39972





# **Vehicle Details**

CO2 Emission:

Make / Model Vehicle No. ADIVA / AR3 200 3-WHEELER CVT FBL2161T Vehicle Attachment 1: Vehicle Type: No Attachment P01 - Passenger Scooter Chassis No.: Vehicle Scheme: RGVTC40AAGA000065 Normal Propellant: Engine No.: MA812089 Petrol Engine Capacity: Motor No.: 171 cc Power Rating: Maximum Power Output: Unladen Weight: Maximum Laden Weight: 420 kg 254 kg Year Of Manufacture: Original Registration Date: 15 Jul 2016 2016 Lifespan Expiry Date: COE Category: D - Motorcycle Quota Premium: COE Expiry Date: \$6,303.00 14 Jul 2026 Road Tax Expiry Date: PARF Eligibility Expiry Date: 25 Oct 2022 Intended Transfer Date: Inspection Due Date: 29 Jan 2022 25 Oct 2022

CEV/VES Rebate Utilised Amount:

SJ0421C9000Z / JP Knights Pte Ltd ENTRY DATE & TIME: 09/12/2021 21:30 (SGT) SUBMITTED BY: Kavi VERSION: 1 (09/12/2021 21:30 (SGT))

# **SINGAPORE ACCIDENT STATEMENT**

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving
- and that copies of this report will, for a fee, be made available upon application by interested parties.

  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date of Submission 09/12/2021 21:30 (SGT) Date of Accident 08/12/2021 11:40 (SGT) Exact Location of Accident Tuas Rd, Singapore Additional Location Information Country/State of Loss Singapore

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number FBL2161T

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner SINGAPORE POST LIMITED Company Reg No 1XXXXX623M Email Address afiganuar@singpost.com Mobile Phone No (Phone) +65-86521644 Alternative Phone No (Office) +65-68412000

#### VEHICLE PARTICULARS

Manufacturer Adiva Model Ar3 Variant Exact purpose for which vehicle was being used at time of accident Employment Are you claiming under your own insurance policy for repair to

your vehicle? No - Claiming third party Vehicle Category Motorcycle Transmission Auto CC 171

#### **INSURANCE COMPANY**

Name of Insurance Company Great Eastern General Insurance Limited Type of Coverage ThirdParty Fleet Policy Yes Policy Number V0107634-VMF Cover Note Number

DRIVER

Address	-
Address complement	_
Postcode	_
Insurance Company Name	_
Nature Of Damage	_
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

# INJURED PERSONS DETAILS

## INJURED 1

Name of injured person	<b>AZLAN BIN OTHMAN</b>
Gender	Male
Phone No	pro-recognise endage from
Address	-
Address Complement	-
Post Code	=
Approximate Age Years Old	
Injuries Sustained	5 DAYS MC
Injured person in which vehicle?	FBL2161T
Were seat belts worn?	ES DESCRIPTION OF THE
Was this injured conveyed to hospital by ambulance?	Yes

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- information provided must be as <u>truthful and accurate as possible</u>. Any wliful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

l understand, acknowledge, agree and consent that :

- (a) My insurer, my w orkshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) w ho have insured vehicle(s) involved in this accident (all insurers) w ho have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (II) Investigating the accident and/or my daims;
- (II) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as wiell as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

& Time 09/12/2021 430

Driver's Signature (if driver is not the policyhoider) / Date W

Dahnial
Witnessed by Reporting Centre

Personnel

Policyholder's Signature / Date & Time

Sketch Plan

TUMS POND
A - FELZIGIT
B - GEN 9-8-1 A
E

Describe Circumstances of the Accident

ON THE 08/12/2021 AT AROUND 1140HRSM I VEHICLE A(FBL2161T) WAS DRIVING ALONG TUAS ROAD ON THE RIGHT LANE INTENDING TO TURN RIGHT TOWARDS TUAS BASIN LINK. AS I WAS RIDING, VEHICLE B(GBA3587A) WHO WAS ON THE LEFT DID NOT SEE MY APPROACHING AND DECIDED TO CHANGED LANE RESULTING IN VEHICLE B SIDE SWIPING ME. I FELL AND WAS LATER CONVEYED TO NG TECK FONG HOSPITAL AND WAS AWARDED 5 DAYS OF MC.

-			
Dec	r	9.0	100
	 		81

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature / Date & Time Driver's Signature (if driver is not the policyholder) / Date & Time  $o_9/h/2\sigma_{L_1}/V\zeta_0$ 

Dahnial

Witnessed by Reporting Centre Personnel