

ASS. REC. BY: Steve

REF: C83/CT121011539/ENV3-1

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FBJ 8578X Yr Regn: 29/11/14
Type: M.Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: BMW R1200 GS c.c. 1170
Colour: White A/C: Insured / Std / NI / NA
Sp. Reading: 93278 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WB10A0200E2208096
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modl: NII / S/Rim / STD A/Rim or
Tyre Size: F: 120/70ZR19
R: 170/60ZR17
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Continental
Front _____ Rear _____
R/Bal. 4 mm R/Bal. 4 mm
L/Bal. _____ mm L/Bal. _____ mm
D.O.A. 30/10/21 D.O.I. 14/3/21
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV-18K</u>

Date/Time, File Pass to? ☐ : Prell. Report
1) ☐ : Final Report
Date/Time, File Return to?
2) _____

Days Of Repair: _____
Resurvey No. of Trip: _____

Report Format : _____
Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____
Transportation: _____
S + RS \$ _____
Photos _____
Others _____
TOTAL _____