



HS AUTOMOTIVES PTE LTD

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

ROC: 201907812C

Vehicle No: SLP1327A

Make/Model: P308

CHASSIS NO: VF3LP4N4W06S197226

Date: 7.2.22

☐	INDEPENDENT SURVEYOR
☒	DIRECT SETTLEMENT

Estimate cost of repair to the above mentioned

NO.	QTY	LIST ITEMS	MARKING	UNIT \$	AMOUNT (S\$)
1	1	FRONT BUMPER / CA			\$ 1699.70
2	1	FRONT BUMPER SENSOR X NR			\$ 233.94
3	1	FRONT BUMPER RETAINER Q?			\$ 188.76
4	1	FRONT BUMPER CLIP / MC	PK		\$ 78.40
5	1	LH FRONT FENDER / MC			\$ 688.75
6	1	LH FRONT FENDER INNER SHIELD ?			\$ 200.97
7	1	LH FRONT FENDER INNER SHIELD CLIP / PK			\$ 47.30
8	1	LH FRONT HEAD LAMP. X			\$ 360.97
9	1	LH FRONT HEAD LAMP LOWER BRACKET. X			
10	1	LH FRONT DOOR Repair X			\$ 1997.30
11	2	LH FRONT DOOR HINGE X		\$ 188.93	\$ 377.86
12	1	LH FRONT DOOR WEATHER STRIP X			
13	1	LH FRONT SIDE MIRROR. /			\$ 1976.60
14	1	LH FRONT SIDE MIRROR COVER. /			
15	1	LH FRONT SIDE MIRROR GLASS X			
16	1	LH FRONT LOWER ARM. X			\$ 489.70
17	1	LH FRONT SHOCK ABSORBER X			
18	1	LH FRONT SHOCK ABSORBER MOUNTING. X			
19	1	LH FRONT WHEEL KNUCKLE ?			\$ 999.57
20	1	LH FRONT WHEEL BEARING / JN			\$ 499.70

REMARKS:

NO OF DAYS:	
AGREED FIGURE/LUMP SUM:	
SURVEYOR NAME	CONTACT:
EMAIL ADD:	



HS AUTOMOTIVES PTE LTD

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

ROC: 201907812C

Vehicle No: SLP1327A

Make/Model: P308

CHASSIS NO: VF3LP4N4N68187226

Date: 7.2.22

INDEPENDENT SURVEYOR
☒ DIRECT SETTLEMENT

Estimate cost of repair to the above mentioned

NO.	QTY	LIST ITEMS	MARKING	UNIT \$	AMOUNT (\$\$)
1	1	LH FRONT LINKAGE ROD X NN			
2	1	LH FRONT SPOR? RM / CA			@1753.20
3	1	LH FRONT TYRE X NN			
4					
5					
6					
7	1	DANGL B3AT		500	@ 1200
8					
9		SPRAY PAINT		700	@ 1200
10					
11		WASH ALIGNMENT		60	@ 100
12					
13		TO REMOVE AND REFX UNDERCARRIAGE		120	@ 200
14					
15		TO CHECK WIRING		30	@ 80
16					
17		RUST PROOF		60	@ 100
18					
19					
20					

HS AUTOMOTIVES PTE LTD hereby notify the Repairer of the following:

- To result in survey before/after repair/painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved and subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

REMARKS:

NO OF DAYS:

AGREED FIGURE/LUMP SUM:

SURVEYOR NAME

EMAIL ADD:

CONTACT:

5
L/S
Gino Aiy.
7/2/22
After input photos