

SEA TEC BY: Thevan

CS/TMI2200/024/04/24

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. **M2200545**


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % J Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SHC2277U** Yr Rogn: **28/4 121**

Type: M. Car / M. Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make: **Hyundai** **long** c.c. **1580**

Colour: **blue** A/C: ☐ Insured / Std / NI / NA

Sp. Reading: **14748** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **kmh/c85/cv4/95/09**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: **195/65R15**

R: **195/65R15**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Westlake**

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 27/11/22 D.O.I. 27/11/22 28/11/22

Survey held at **CDGE**

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
22/02/22@4.22pm revised to TMI via Merimen.

Thevan finalised final fig \$1273.60, 2 days.

The final figure should be \$1284.60 (Red \$1452.12, 53%)

Date/Time File Pass to?

☐ : Procl. Report

UJ

☐ : Final Report

Date/Time File Return to?

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS. \$

Finishes

Others

Total

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Inve (\$

☐ : W/S and

Report Figures: **MER-TP**

1284.60

SHC2277U

CHIANG

Date/Time: 27.01.2022 16:53

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order: 4168128

305503012

JC NO.:


STOMER	REGN SHC2277U	MILEAGE
COMFORT TRANSPORTATION PTE LTD	MAKE HYUNDAI	FUEL
VMS 7010045	MODEL IONIQ(G3)	E.....1/2.....F
STOMER 383 SIN MING DRIVE	YR OF 20.09.2021	DATE TIME IN 27.01.2022 14:25
DRESS Singapore SINGAPORE 575717	CHASSIS 10MH0851CVLU195109	TARGET DATE
65508755		COMPLETION DATE/TIME:
.. (R) (O)		
(P)		
SCOUNT CARD NO.		

Accident Date: 27.01.2022

JOB DESCRIPTION

NATURE: 3P 27.01.2022 ,

3/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHC2277U CHIANG

Vehicle No.: SHC2277U

Signature/Date

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	27/01/2022
Vehicle Reg. No.:	SHC2277U	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Vehicle Reg. Date:	28/09/2021
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU432098	Chassis No:	KMHC851CVLU195109
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,645.72
Miscellaneous Items	11.00
Labour	1,080.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	2,736.72
+ GST 7.00% (\$\$)	191.57
Nett Amount (\$\$)	2,928.29

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 27 Jan 2022)

Parts: 143

HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHC2277U/27/01/2022 17:01

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info:

Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	*459.40 FL X r
2	1		*REAR BUMPER MOULDING	20.00	0.00	*451.25 FL Sdlt
3	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	*394.80 FL 7
4	2		*REAR BUMPER REINFORCEMENT STAY LH /RH	20.00	0.00	*276.20 FL 7
5	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL / nec
6	1		*REAR BUMPER REFLECTOR RH	20.00	0.00	*41.45 FL x Svc
7	1		*REAR BUMPER BRACKET RH	20.00	0.00	*55.80 FL x Svc
8	1		*REAR BUMPER MAT	0	0.00	*50.00 FS x Svc
9	1		*REAR REVERSE SENSOR	0	0.00	*180.00 FS / Cct
10	1		*REAR NUMBER PLATE WHOLDER	0	0.00	*55.00 FS / Cct

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,985.90
- List Item Discount on L Items (S\$)	340.18
Total Parts (S\$)	1,645.72

ComfortDelGro Engineering Pte Ltd/SHC2277U/27/01/2022 17:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	600.00 350
2	SPRAY PAINTING	New	300.00 250
3	REMOVE/REFIX REVERSE SENSOR	New	60.00 20
4	TUFF KOTE	New	60.00 26
5	CHECK WIRING LIGHTING	New	60.00 20
Gross Labour Cost (S\$)			1,080.00

ComfortDelGro Engineering Pte Ltd/SHC2277U/27/01/2022 17:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Therav@Lkhauto.com

82235769

28/1/22 1630

P/P before paint photo

2 days up

LKR Auto Insurance Ltd hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: