



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC21013330/Gty3e2-1 Date: 08/03/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 4368H	Veh. Inspected	SKZ 5141B	
Policy No.		Coverage (\$)	0.00	
Claim No.	21/21/22/VC05/025299	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	03/02/2022	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SYLPHY 1.6	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MNTBBAB17Z0026622	Colour	RED	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	CONTINENTAL	6 mm	
L/H Front Tyre	205/55 R16	CONTINENTAL	6 mm	
R/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm	
L/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/12/2021	Inspection Date	31/12/2021	
Survey held at	PAUL HOE ENTERPRISE PTE LTD 1 KAKI BUKIT AVENUE 6, #01-107, AUTOBAY @ KAKI BUKIT, SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	