

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 97 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: STIA 8114C Yr Regn: Nov / 2016  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Hyundai I40 c.c. 1685

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading: 569984 T/Radio: Insured / Std / NI / NA

Eng/No: D4FDGU620853

C/No: KMHLB41UMHC097120

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front R/Bal. 5 mm Rear R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 31/01/2022 D.O.I. 04/02/2022

Survey held at Bijrost Sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Partition

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	AXA STIA 9154E
	Vehicle balance about 33 months at time of accident.
	Value of tax about 10,923.00 at time of loss.
	BV calculation behind.
02/08/2022	Finalize 45 10,001 - with 9 dgs of 1/2

Date/Time, File Pass to?  : Preli. Report  : Final Report

1) Date/Time, File Return to? \_\_\_\_\_  
2) \_\_\_\_\_

Report Format : \_\_\_\_\_  
Lump Sum / I.B.I.: (\$ \_\_\_\_\_)

Days Of Repair: \_\_\_\_\_  
Resurvey No. of Trip: \_\_\_\_\_  
Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_  
Transportation: \_\_\_\_\_  
S + RS, SI \_\_\_\_\_  
Photos \_\_\_\_\_  
Others \_\_\_\_\_  
TOTAL \_\_\_\_\_