



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22001080/Kvy3n2	Date: 25/02/2022
			Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJU 9052L	Veh. Inspected	GBD 1691D
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10013708/CD	Excess (\$)	0.00
	Assign From	IVY RATILLA	Assign Date	04/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN NV200 (M)	c.c	1461
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	VSKYBAM20Z0081171	Colour	BLACK
	Odometer	123070 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	175/70 R14	DUNLOP	8 mm
	L/H Front Tyre	175/70 R14	DUNLOP	8 mm
	R/H Rear Tyre	175/70 R14	DUNLOP	8 mm
	L/H Rear Tyre	175/70 R14	DUNLOP	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/01/2022	Inspection Date	07/02/2022
	Survey held at	5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405		
	Repairer	MASSIVE TRADING & AUTO		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	