

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

UN					
	NITED OVERSEA	AS INSURANCE LTD	Ref:	CS/UOI22001081/Uvy3e2	
	146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909		Date:	14/03/2022	
			Code:	UOI2	
1.	Policy Particulars :- THIRD PARTY CLAIM				
Ins	sured Veh.	SKT 9458T	Veh. Inspected	EV 988A	
Po	olicy No.		Coverage (\$)	0.00	
Cla	aim No.	M12D17662202	Excess (\$)	0.00	
As	sign From	LEE KATIE	Assign Date	04/02/2022	
2. Vehicle Particulars & Condition					
Ма	ake & Model	TOYOTA VELLFIRE ZG (A)	c.c	2493	
En	ngine No.	HIDDEN	Year of Reg.	2016	
Ch	nassis No.	AGH300040229	Colour	BLACK	
Od	dometer	147953 KM	Steering	IN ORDER	
Bra	akes	IN ORDER	Modification	SPORTS RIM	
Ge	eneral	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
R/l	H Front Tyre	225/50 R18	FALKEN	6 mm	
L/H	H Front Tyre	225/50 R18	FALKEN	6 mm	
R/I	H Rear Tyre	225/50 R18	FALKEN	6 mm	
L/H	H Rear Tyre	225/50 R18	FALKEN	6 mm	
4.	<u>-</u>				
TH	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.				
DA	DAMAGES SEE DETAILS.				
5.	General Information				
Ac	cident Date	01/02/2022	Inspection Date	04/02/2022	
Su	rvey held at	FASTECH AUTO PTE LTD			
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a.	a. Remarks				
A)T B)II	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
	c. Estimate Days of Repair				
5b.			<u> </u>		