

ASS. REG. BY: JuneREF: CS/FCI22001084/Rty32006

- ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP/WS/TP RES/OD RES/EVA/INV/MVTo Inspect Vehicle No: SLN 3424at Workshop m/s BORNEO MOTORSof 2, Pandan CrescentInsured: FCI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 72K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLN 3424 Yr Regn: 2011 / APRType: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: TOYOTA PRIUS HYBRID 1.8 CVT c.c. 1798Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 290837 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JDAB3FU103555908Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orMod: Nil / ☒ Rim / STD A/Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or KumHo

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 30/01/22 D.O.I. 12/04/22Survey held at BORNEO MOTORSDes. of Damages: Frt / Rear / O/S ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>REPAIR LIMIT - 41K</u>
	<u>advising our principal a cost of repair of P/P \$5,824.30 /- with 05 days of repair</u>
	<u>red: 7569.00;56%</u>

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1) _____

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) _____

Add Fee: ☐ : Site Insp (\$ _____)

Survey Fee: _____

Transportation: _____

Report Format: _____

Lump Sum / L.S. (\$) _____

☐ : Interview (\$ _____)

S + RS. SI

☐ : Tech. Invs (\$ _____)

Photos

☐ : Weekend (\$ _____)

Others



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No. 0				
			Document Date 04/02/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	20/04/2017	SLN0342Y	0	13133	75/DS/SLN0342Y
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKB3FU103555908		2ZRS038038	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:PA6523Z ACC DATE:30/01/2022 DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30 100.00	
2	B	BP-LAB2 CHECK WIRING & CONDUCT LEAK TEST				X 180.00	
3	B	BP-LAB2 CHECK WIRING & CONDUCT LEAK TEST				180.00	
4	S	BP-SUBLET RESET ECU UPON COMPLETION OF REPAIR				180.00	
5	B	BP-LAB2 TRANSFER DOOR MACH				360 720.00	
6	Z	BP-SLANT SUPPLY SEALANT (NETT)				100 200.00	
7	B	BP-LAB2 REPL ACC AFF AREA STRAIGHTEN & PANEL ACC AFF AREA @720				1440 3600.00	
8	B	BP-RES2 RESPRAY ACC AFF AREA e550 X 35				2065 2950.00	
9	1	T67002-47163 PANEL SUB-ASSY, FR repair	1.00	1377.90		1377.90	
10	2	U75976-47060 STRIPE, FR DOOR, X	1.00	14.10		14.10	
11	3	U75986-47050 STRIPE, FR DOOR, X	1.00	46.20		46.20	
12	4	U75966-47030 STRIPE, FR DOOR, X	1.00	27.90		27.90	
13	5	T67004-47210 PANEL SUB-ASSY, RR 4	1.00	1371.80		1371.80	
14	6	U75978-47080 STRIPE, RR DOOR, ne	1.00	23.20		23.20	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts		Less
					Labour		
					Sublet		
					Lubrication/Fluid		Amount Due
					Others		



Borneo Motors



TOYOTA

inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925			
			Document No. 0					
			Document Date 04/02/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZVW50R	AHXEBW Q3	20/04/2017	SLN0342Y	0	13133	75/DS/SLN0342Y	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDKB3FU103555908		2ZRS038038	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
15	7	U75988-47060 STRIPE, RR DOOR, <i>na</i>			1.00	37.00		37.00
16	8	U75989-47070 STRIPE, RR DOOR, <i>na</i>			1.00	16.30		16.30
17	9	U61602-47160 PANEL SUB-ASSY, <i>repair</i>			1.00	925.90		925.90
18	0	U87940-47440 MIRROR ASSY, OUTER <i>repair</i>			1.00	1422.00		1422.00
<div style="border: 1px solid black; padding: 5px; margin: 10px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div> <div style="margin-top: 20px;"> <p><i>Resue</i> <i>Hp 900/0068</i> <i>5 days</i> <i>P/P</i> <i>12/04/22 P1145</i> <i>Reg before paint</i></p> </div>								
								13,393.30
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 13,372.30	
			Please acknowledge receipt of vehicle		Parts 5,262.30 Labour 7,930.00 Sublet 180.00 Lubrication/Fluid 0.00 Others 0.00		GST 7.00% 936.06 Less 0.00 Amount Due 14,308.36	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	31/01/2022 12:22 (SGT)
Date of Accident	30/01/2022 12:45 (SGT)
Exact Location of Accident	Stamford Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN342Y
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	GRAB RENTALS PTE LTD
Company Reg No	2XXXXX200G
Email Address	gr.sg.accident@grab.com
Mobile Phone No	(Phone) +65-81886033
Alternative Phone No	(Office) +65-66550005

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1798

INSURANCE COMPANY

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	400001149
Cover Note Number	-

DRIVER

Date of Birth
Occupation
Date Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

05/07/1975
Outdoor
20/10/1993
28 YEARS AND 3 MONTHS
Male
(Phone) +65-81886033
-
gr.sg.accident@grab.com
BLK 154 GANGSA ROAD #02-327
-
670154
No
Hirer
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Side Swipe
Weather Conditions Clear
Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
Number of vehicles involved in the accident 2
Was anybody injured in the Accident? No
Was any injured conveyed to hospital by ambulance? -
Was any other vehicle or property damaged? Yes
Number of Passengers (Including Driver) 1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
Was notice of intended Prosecution given? No
If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

ON THE 30/01/2022 AT AROUND 1245HRS. I VEHICLE A(SLM342Y) WAS TRAVELLING ALONG STAMFORD ROAD ON THE SECOND LANE FROM THE LEFT. AS I WAS TRAVELLING, I FELT AN IMPACT ON MY LEFT SIDE AND REALISED THAT VEHICLE B(PA6523Z) HAD GRAZED MY WHOLE LEFT DOOR AND MY LEFT MIRROR. NO ONE WAS INJURED AT THAT POINT OF TIME.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? No
Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PA6523Z
Vehicle Manufacturer -
Vehicle Model -
Vehicle Variant -
Vehicle Colour -
Vehicle Category Commercial vehicle
Name of Driver -
Contact Number (Phone) +65-97800969

Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



A - SLM 3424


B - PA 65232

Describe Circumstances of the Accident

ON THE 30/01/2022 AT AROUND 1245HRS. I VEHICLE A(SLM342Y) WAS TRAVELLING ALONG STAMFORD ROAD ON THE SECOND LANE FROM THE LEFT. AS I WAS TRAVELLING, I FELT AN IMPACT ON MY LEFT SIDE AND REALISED THAT VEHICLE B(PA6523Z) HAD GRAZED MY WHOLE LEFT DOOR AND MY LEFT MIRROR. NO ONE WAS INJURED AT THAT POINT OF TIME.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time 30/01/2022 1415



Dahnial

Witnessed by Reporting Centre Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	200G
Vehicle No.:	SLN342Y
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Apr 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2ZR5038038
Chassis No.:	JTDKB3FU103555908
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	20 Apr 2017
First Registration Date:	20 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Apr 2027
PARF Rebate Amount:	\$3,750.00
COE Expiry Date:	19 Apr 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,000.00
COE Rebate Amount:	\$27,090.00
Total Rebate Amount:	\$30,840.00

The information contained herein is correct as at 13 Apr 2022

OK

Toyota Prius Hybrid 1.8A

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

車
之
道

CARWAY

Your Satisfaction Is Our Success



Price	\$64,800		
Depreciation ⓘ	\$14,030 /yr View models with similar depre	Reg Date	15-Sep-2016 (4yrs 5mths 1day COE left)
Mileage	78,779 km (14.1k /yr)	Manufactured ⓘ	2016
Road Tax ⓘ	\$976 /yr	Transmission	Auto
Dereg Value ⓘ	\$29,386 as of today (change)	Fuel Type	Petrol-Electric
COE ⓘ	\$58,201	OMV ⓘ	\$31,008
Engine Cap	1,798 cc	ARF ⓘ	\$5,412
Curb Weight ⓘ	1,375 kg	Power	90.0 kW (120 bhp)