

Our Job Ref No : 305503404
Date : 12/02/22

**COMFORTDE
ENGINEERING**

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : THEVAN
Vehicle Reg No. : SHC3107X

Fax :

30.01.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: TOKIO SGG5580P

2. The finalized amount shall be:

(a) Spare Parts after List discount

\$2,322.60

(b) Labour Charges

\$1,290.00

Total for Part-By-Part Repair Cost

\$3,612.60

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as **Correct and Confirmed** if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : 

Name : _____

Date : _____

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

ComfortDelGro Engineering Pte Ltd (Co Reg No: 199508043W)59 Loyang Drive
Singapore 508069
Tel. 6214 8300**(SUPPLEMENTARY)****TP INSURER:** Tokio Marine Insurance Singapore Ltd (HQ)
TAN ZHEN YUAN

Singapore

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	
Policy No:	MX003851	Date of Loss:	30/01/2022
Vehicle Reg. No.:	SHC3107X	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A)	Vehicle Reg. Date:	20/12/2019
Vehicle Colour:	Blue	Gen Condition:	Good
Engine No:	2ZR2G11034	Chassis No:	JTDKB3FU103090420
Odometer:	180473 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	ACCIDENT INVOLVING SGG5580P & SHC3107X ALONG YISHUN AVE 2		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	50.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	50.00
+ GST 7.00% (S\$)	3.50
Nett Amount (S\$)	53.50
+ Previous Estimates (S\$)	10,736.99
Claim Total (S\$)	10,790.49

Generated using Merimen e-Claims Internet Estimation & Adjusting System

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 11.02.2022
Time: 10:59:11
Page: 3

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305503404
REGN NO : SHC3107X
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID
DATE OF REGN : 20.12.2019
DATE/TIME IN : 31.01.2022 11:4
ACCIDENT DATE : 30.01.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,612.60

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Feb 2022)
Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue: Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHC3107X/28/02/2022 11:05
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER MAT <i>Nec</i>	0	0.00	*50.00 FS
Total Parts (S\$)						50.00

ComfortDelGro Engineering Pte Ltd/SHC3107X/28/02/2022 11:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous Items selected.

Estimates on Labour

There are no labour Items selected.

ComfortDelGro Engineering Pte Ltd/SHC3107X/28/02/2022 11:05. Not valid without Reference section.
Generated using Merlmen e-Claims IEAS

< END OF ESTIMATES >

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305503404
 REGN NO : SHC3107X
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBR
 DATE OF REGN : 20.12.2019
 DATE/TIME IN : 31.01.2022 11
 ACCIDENT DATE : 30.01.2022

JOB / PARTS DESCRIPTION	QTY	IND	UNIT	PRICE	DISC%	AMOUNT
0014 04-01-0302-2725-G RETAINER REAR BUMPER LH	1			112.70	25.00	84.52
0015 04-01-0302-1150-A BUMPER PROTECTOR MAT	1			50.00		50.00
0016 04-01-0302-2288-G REINFORCEMENT SUB-ASSY RE	1			318.80	25.00	239.10
SUB-TOTAL :						2,322.60

JOB NATURE

0000 PB	PANEL BEATING SHC3107X	700.00
0001 SP	SPRAYPAINT CHARGE	500.00
0002 17-01	CHECK ALL LIGHTING	30.00
0003 20-22	REMOVE/REFIX REVERSE SENSOR	30.00
0004 20-00	TUFF COAT ON AFFECTED PARTS.	30.00
SUB-TOTAL :		1,290.00

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

6620

Date: 11.02.2022
Time: 10:59:11
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305503404
REGN NO : SHC3107X
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4A)
DATE OF REGN : 20.12.2019
DATE/TIME IN : 31.01.2022 11:40
ACCIDENT DATE : 30.01.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2711-G	GARNISH SUBASSY BACK DR O	1	889.70	25.00	667.27
0002 04-01-0302-2270-G	PLATE-BACK DOOR NAME (HYB	1	52.40	25.00	39.30
0003 04-01-0302-2271-G	PLATE-BACK DOOR NAME (PRI	1	52.90	25.00	39.67
0004 04-01-0302-2269-G	ORNAMENT SUB-ASSY BACK DO	1	60.80	25.00	45.60
0005 04-01-0302-2712-G	COVER REAR BUMPER	1	458.60	25.00	343.95
0006 04-01-0302-2713-G	GUARD REAR BUMPER CENTER	1	552.60	25.00	414.45
0007 04-01-0302-2267-G	BUMPER PIECE	10	22.00	25.00	16.50
0008 04-01-0302-2715-G	COVER RR BUMPER -TOW HOOK	1	82.70	25.00	62.02
0009 09-01-0302-2005-A	REVERSE SENSOR ASSY	1	135.70		135.70
0010 28-01-9999-2025-A	APP LOGO REAR BONNET CTPL	1	40.00		40.00
0011 28-01-0302-2015-A	REAR BONNET COMFORTDELGRO	1	30.00		30.00
0012 28-01-0302-0006-A	REAR BOOT 65521111 CTPL^	1	30.00		30.00
0013 04-01-0302-2714-G	RETAINER REAR BUMPER RH^	1	112.70	25.00	84.52

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 11.02.2022

Time: 10:59:11

Page: 3

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305503404
REGN NO : SHC3107X
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID
DATE OF REGN : 20.12.2019
DATE/TIME IN : 31.01.2022 11:4
ACCIDENT DATE : 30.01.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,612.60

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 03 Feb 2022)**Parts:** 144 TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC3107X/03/02/2022 11:28**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*GARNISH SUB -ASSY BACK DOOR	DT 25.00	0.00	*889.70 FL
2	1		*REAR TRUNK	SUC X 25.00	0.00	*1,126.60 FL
3	1		*REAR TRUNK COVER TRIM	SUC X 25.00	0.00	*254.40 FL
4	1		*REAR TRUNK LID LOCK	SUC X 25.00	0.00	*457.90 FL
5	1		*REAR TRUNK LID LOGO (PRIUS)	Rec 25.00	0.00	*52.90 FL
6	1		*REAR TRUNK LID LOGO (HYBIRD)	Rec 25.00	0.00	*52.40 FL
7	1		*REAR TRUNK LID LOGO (TOYOTA)	Rec 25.00	0.00	*60.80 FL
8	1		*REAR TRUNK LID GLASS W/MOULding UPPER	NN X 25.00	0.00	*1,778.30 FL
9	1		*REAR TRUNK LID GLASS W/MOULding LOWER	NN X 25.00	0.00	*1,569.70 FL
10	1		*REAR BUMPER	DT 25.00	0.00	*458.60 FL
11	1		*REAR BUMPER UNDER COVER	DT 25.00	0.00	*552.60 FL
12	10		*REAR BUMPER CLIPS	Rec 25.00	0.00	*22.00 FL
13	2		*REAR BUMPER SIDE RETAINER (LH) (RH)	Rec 25.00	0.00	*225.40 FL
14	1		*REAR BUMPER UNDER COVER CENTRE	SUC X 25.00	0.00	*252.00 FL
15	1		*TAIL LAMP UPPER RH	SUC X 25.00	0.00	*548.40 FL
16	1		*TAIL LAMP LOWER RH	SUC X 25.00	0.00	*602.10 FL
17	1		*REAR SMART KEY ANTENNA	SUC X 25.00	0.00	*447.10 FL
18	1		*REAR BUMPER TOWING COVER	mis 25.00	0.00	*82.70 FL
19	1		*REAR BUMPER REINFORCEMENT	DT 25.00	0.00	*318.80 FL
20	1		*REAR BUMPER REVERSE SENSOR	Cut 25.00	0.00	*135.70 FL
21	1		*REAR TRUNK LID COMFORT APP	Rec 25.00	0.00	*40.00 FL
22	2		*REAR TRUNK LID COMFORT /TEL NO STICKER	Rec 25.00	0.00	*120.00 FL
23	1		*REAR NUMBER PLATE W/HOLDER	SUC X 25.00	0.00	*50.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$) 10,098.10

- List Item Discount on L Items (\$\$) 2,524.53

Total Parts (\$\$) 7,573.57

ComfortDelGro Engineering Pte Ltd/SHC3107X/03/02/2022 11:28. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			11.00
1	1	OD/TP Case (Insurer)	
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	700 1,090.00
2	SPRAY PAINTING	New	500 1,000.00
3	CHECK WIRING & LIGHTING	New	30 90.00
4	REMOVE/REFIX REVERSE SENSOR	New	30 60.00
5	TUFF COATING	New	30 90.00
6	REMOV/REPLACE REAR WINDSCREEN	New	NNX 120.00
Gross Labour Cost (S\$)			2,450.00

ComfortDelGro Engineering Pte Ltd/SHC3107X/03/02/2022 11:28. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tham @Chhauto-lom
87235769
3/2/21 1645
P/P L/S after repair photo b4 paint photo
3 days wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: