



Service Request Details

Claim

S2M03SOP

Reference

CS3/ASM22001107/y3

Loss Date

4 February 2022

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

7 Feb 2022 10:06:38 AM

Request Date

7 February 2022

Due Date

14 February 2022

Services

Pre-Repair Survey

Actions

Next Step

Agree to perform service

Decline Work

Vehicle Information

Incident Vehicle Registration #
SMM6824C

Make
TPVD Honda

Model
Shuttle

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

CHAN Kian Chuan
68805444
kianchuan.chan@axa.com.sg

Additional Instructions

Messages2

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

TYPE	
SENT	7/2/22 11:53 AM

BODY

Noted with thanks. Repairer arrange on 08.02.2022....



TYPE



SENT

7/2/22 11:36 AM

FROM

CHAN Kian Chuan

SUBJECT

Re:WORKSHOP DETAIL

BODY

Address : Dynamics Mechanic Pte Ltd 184 Woodlands...



TYPE



SENT

7/2/22 11:34 AM

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT

WORKSHOP DETAIL

BODY

Dear Kian Chuan, Thank you for the assignment. Ple...

