

|   |   |          |   |   |   |   |        |   |   |             |
|---|---|----------|---|---|---|---|--------|---|---|-------------|
| ⏪ | < | 1 of 2 ? | > | ⏩ | ↺ | ↻ | 100% ▼ | 📄 | 🖨 | Find   Next |
|---|---|----------|---|---|---|---|--------|---|---|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                              |                 |                                                               |  |
|----------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------|--|
| EQ INSURANCE COMPANY LTD<br>5 MAXWELL ROAD<br>#17-00 TOWER BLOCK<br>MND COMPLEXSINGAPORE 069110                                        |                                                                              |                 | Ref: CS/EQI22001114/Ktf3<br>Date: 07/02/2022<br><br>Code: EQI |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                              |                 |                                                               |  |
| Insured Veh.                                                                                                                           | SME 9380M                                                                    | Veh. Inspected  | SHD 253X                                                      |  |
| Policy No.                                                                                                                             |                                                                              | Coverage (\$)   | 0.00                                                          |  |
| Claim No.                                                                                                                              | DM22HO00079/MT                                                               | Excess (\$)     | 0.00                                                          |  |
| Assign From                                                                                                                            | MELODY TEOH                                                                  | Assign Date     | 07/02/2022                                                    |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                              |                 |                                                               |  |
| Make & Model                                                                                                                           |                                                                              | c.c             | 0                                                             |  |
| Engine No.                                                                                                                             | HIDDEN                                                                       | Year of Reg.    |                                                               |  |
| Chassis No.                                                                                                                            |                                                                              | Colour          |                                                               |  |
| Odometer                                                                                                                               | -                                                                            | Steering        |                                                               |  |
| Brakes                                                                                                                                 |                                                                              | Modification    |                                                               |  |
| General                                                                                                                                |                                                                              |                 |                                                               |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                              |                 |                                                               |  |
|                                                                                                                                        | Size                                                                         | Make            | Balance                                                       |  |
| R/H Front Tyre                                                                                                                         |                                                                              |                 | mm                                                            |  |
| L/H Front Tyre                                                                                                                         |                                                                              |                 | mm                                                            |  |
| R/H Rear Tyre                                                                                                                          |                                                                              |                 | mm                                                            |  |
| L/H Rear Tyre                                                                                                                          |                                                                              |                 | mm                                                            |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                              |                 |                                                               |  |
|                                                                                                                                        |                                                                              |                 |                                                               |  |
| <b>5. General Information</b>                                                                                                          |                                                                              |                 |                                                               |  |
| Accident Date                                                                                                                          | 07/02/2022                                                                   | Inspection Date | 07/02/2022                                                    |  |
| Survey held at                                                                                                                         | TRANS-CAB AUTO SERVICES PTE LTD<br>NO.2 ANG MO KIO ST 63<br>SINGAPORE 569111 |                 |                                                               |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                              |                 |                                                               |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                              |                 |                                                               |  |