

ASS. REC. BY:

REF:

FC2/22001123/K9f3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. D22000317MFBP

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 878k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMD 965R Yr Regn: 07, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or WagonMake: Kia Carens C.C. 1685Colour: M.P Blue A/C: Insured / Std / NI / NASp. Reading: 268263 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNA14U815VJ.7211391Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Mod: NII / S/Rlm / STD A/Rlm or

Tyre Size: Granlander 205/55R16R Duratun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 30/1/22 D.O.I. 14/2/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

15/12 @ 310d Cahr Cred \$260.60, 41%23/07/22 @ 11.46am revised to FCI by email.

Date/Time, File Pass to?

☐

: Prell. Report

1) 23/02/2022☐

: Final Report

Date/Time, File Return to?

Days Of Repair: 4

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / L.B.T. (\$

TP
3100

Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869
Tel: +65 6255 2288 | Fax: +65 6265 5388
Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

ESTIMATION REPORT

Vehicle No : SMD965R
Make & Model : KIA, Carens EX 1.7 Diesel, KNAHU815VJ7211391
Year of Manufacture : 2018
Estimation No. : E22020003
Date : 08/02/2022

No.	Code	Description	Qty	U/P	Amt
Section: Remark					
1		MS FRIST CAPITAL INSURANCE LTD DOA : 30.01.2022 TP CLAIM	1.00	0.00	0.00
					Amt S\$ 0.00
					Discount (0.00%) S\$ 0.00
					Subtotal S\$ 0.00

Section: Labour					
2		FRONT BUMPER	1.00	618.00	618.00
3		FRONT HEADLAMP RH	1.00	1,450.00	1,450.00
4		FRONT HEADLAMP LOWER BRACKET RH	1.00	21.60	21.60
5		FRONT FENDER RH	1.00	384.00	384.00
6		FRONT FENDER INNER COWLING	1.00	68.00	68.00
7		FRONT RIM RH	1.00	650.00	650.00
8		FRONT BUMPER SIDE RETAINER RH	1.00	14.00	14.00
					Amt S\$ 3,205.60
					Discount (0.00%) S\$ 0.00
					Subtotal S\$ 3,205.60

Section: Special nett					
9		FRONT BUMPER CLIPS	6.00	5.00	30.00
10		FRONT FENDER INNER COWLING CLIPS	5.00	5.00	25.00
					Amt S\$ 55.00
					Discount (0.00%) S\$ 0.00
					Subtotal S\$ 55.00

Section: Labour					
11		TO REMOVE & REFIX, REPAIR, KNOCKING, WELDING FRONT PORTION, FRONT BUMPER, FRONT FENDER RH, AND DAMAGE AREA	1.00	600.00	600.00

Not with a new
L1 Rep 83100p
Repairing After Repair
4 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869

Tel: +65 6255 2288 | Fax: +65 6265 5388

Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

ESTIMATION REPORT

Vehicle No : SMD965R

Make & Model : KIA, Carens EX 1.7 Diesel, KNAHU815VJ7211391

Year of : 2018

Manufacture

Estimation No. : E22020003

Date : 08/02/2022

No.	Code	Description	Qty	U/P	Amt
12		TO CHECK AND ADJUST HEADLAMP LH/RH FOCUS	1.00	120.00	120.00
13		TO CHECK ALL WIRING FOR OPERATION	1.00	120.00	120.00
14		TO APPLY RUST-PROOFING ON AFFECTED AREA	1.00	120.00	120.00
15		TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT	1.00	120.00	120.00
16		TO REMOVE AND REFIX FRONT TYRE TO NEW RIM	1.00	120.00	120.00
17		TO RESPRAY FRONT PORTION, FRONT BUMPER, FRONT FENDER RH AND POLISH DAMAGE AREAS	1.00	800.00	800.00
					Amt S\$ 2,000.00
					Discount (0.00%) S\$ 0.00
					Subtotal S\$ 2,000.00

Remarks:

MS FRIST CAPITAL INSURANCE LTD

DOA : 30.01.2022

TP CLAIM

Total S\$ 5,260.60

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	05/02/2022 08:29 (SGT)
Date of Accident	30/01/2022 17:39 (SGT)
Exact Location of Accident	Siloso Rd, Singapore
Additional Location Information	SILOSO ROAD SENTOSA
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD965R
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	BIS MOTORING PTE LTD
Company Reg No	2XXXXX055D
Email Address	KEIFTAN@BISMOTORING.COM.SG
Mobile Phone No	(Phone) +65-86881311
Alternative Phone No	+65-86881311

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Carens
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1699

INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	COI-SPMF1000000413-SMD965R
Cover Note Number	-

DRIVER

Name of Driver	NG WEE HONG DENNIS
NRIC No	SXXXX727D

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	05/02/2022 08:29 (SGT)
Date of Accident	30/01/2022 17:39 (SGT)
Exact Location of Accident	Siloso Rd, Singapore
Additional Location Information	SILOSO ROAD SENTOSA
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD965R
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	BIS MOTORING PTE LTD
Company Reg No	2XXXXX055D
Email Address	KEIFTAN@BISMOTORING.COM.SG
Mobile Phone No	(Phone) +65-86881311
Alternative Phone No	+65-86881311

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Carens
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1699

INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	COI-SPMF1000000413-SMD965R
Cover Note Number	-

DRIVER

Name of Driver	NG WEE HONG DENNIS
NRIC No	SXXXX727D

Date Of Birth	20/12/1967
Occupation	Outdoor
Date Of Driving Pass	16/01/1997
Driving experience	25 YEARS
Gender	Male
Mobile Number	(Phone) +65-81342777
Alt. Phone Number	-
Email Address	dennisgreatarc@gmail.com
Address	301 CLEMENTI AVE 4
Address complement	#12-553
Postcode	120301
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC7382X
Vehicle Manufacturer	Volvo
Vehicle Model	B8r
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Bus
Name of Driver	SULAIMAN BIN BOIMIN
NRIC No	SXXXX676J
Contact Number	-
Address	-

Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	055D
Vehicle Details	
Vehicle No.:	SMD965R
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Feb 2022
Vehicle Make:	KIA
Vehicle Model:	CARENS 1.7 DCT DIESEL 5DR FWD
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	D4FDJD024165
Chassis No.:	KNAHU815VJ7211391
Maximum Power Output:	104.0 kW (139 bhp)
Open Market Value:	\$20,028.00
Original Registration Date:	31 Jul 2018
First Registration Date:	31 Jul 2018
Transfer Count:	0
Actual ARF Paid:	\$20,040.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jul 2028
PARF Rebate Amount:	\$15,030.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jul 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$33,900.00
COE Rebate Amount:	\$21,916.00
Total Rebate Amount:	\$36,946.00

The information contained herein is correct as at 12 Feb 2022

OK