



Claim	S2M03SP6
Reference	CS3/ASM22001124/Gty3e2 
Loss Date	6 February 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	7 Feb 2022 11:23:50 AM
Request Date	7 February 2022
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident

SLZ3544Z

Vehicle

Registration #

Make

TPVD

Model

TBC

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE, 575717, Singapore

65551188

Claim Handler

OH Vale

vale.oh@axa.com.sg

Additional Instructions

MessagesInvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2201024.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	25 February 2022
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	25 February 2022

FAQ English (SG) ▾ Elaine Kuan ▾			SUBTYPE	AUTHOR	DATE UPLOADED
	Service Requests 	ence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	21 February 2022
	RESURVEY SLZ 3544Z.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	21 February 2022
	LKKPhotosIn6 SLZ 3544Z.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	21 February 2022
	AXA Immediate Advice _ TP - SLZ 3544Z.pdf.pdf	Other	Other	LKK AUTO CONSULTANTS PTE LTD (TP)	21 February 2022
	PRI TP PDF.pdf.pdf	Legal	Others	KUMAR Shailendra	7 February 2022
	PRI TP EMAIL FROM SOLICITOR.msg.msg	Legal	Others	KUMAR Shailendra	7 February 2022
	REPLY FROM TP.msg.msg	Letters and Correspondence	Third Party	KUMAR Shailendra	7 February 2022